

Appendix H
Facility Data Sheets

THIS PAGE INTENTIONALLY LEFT BLANK


Perpendicular Ramp




Parallel Ramp




Combination Ramp




Median/Bus Stop




Perpendicular Ramp




Parallel Ramp




Combination Ramp



Median/Bus Stop



CR_48





OBJECTID (Combination Ramp): 1

Name: CR_48

Address: 616 SE Ramp St

TruncDomes: True

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 4.0

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 4.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 1.7

S3_RampCrossSlope2: 2.1

S4_RampSlope2: 5.9

S5_RampCrossSlope3: 0.8

S6_RampSlope3: 1.1

S7_RampSlope1: 3.5

S8_RampCrossSlope1: 1.6

S9_WingSlope1: 4.9


S10_WingSlope2: 3.2

S11_CounterSlope: 5.5

GutterSlope:

LipHeight:

CR_108





OBJECTID (Perpendicular Ramp): 19

Name: CR_108

Address: 406 SE Ramp St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 1.5

S3_RampSlope: 4.6

S4_RampCrossSlope: 1.3

S5_WingSlope1: 4.3

S6_WingSlope2: 3.3

S7_CounterSlope: 3.6

GutterSlope: 1.1

LipHeight:

CR_784





OBJECTID (Parallel Ramp): 61

Name: CR_784

Address: 1758 NE Airport Rd

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 2.3

S3_RampCrossSlope1: 1.0

S4_RampSlope1: 4.5

S5_RampCrossSlope2: 0.4

S6_RampSlope2: 11.5

S7_CounterSlope: 4.8

GutterSlope: 2.5

LipHeight:

CR_197





OBJECTID (Perpendicular Ramp): 108

Name: CR_197

Address: 1758 NE Airport Rd

TruncDomes:

Comments: Broken Guardrail blocking ramp. Post in wing

D1_LandingDim1: 6.7

D2_LandingDim2: 4.7

D3_RampWidth: 5.0

S1_LandingSlope1: 5.8

S2_LandingSlope2: 1.1

S3_RampSlope: 6.1

S4_RampCrossSlope: 2.1

S5_WingSlope1: 10.0


S6_WingSlope2: 3.0

S7_CounterSlope: 10.0

GutterSlope: 3.5

LipHeight:

CR_198





OBJECTID (Perpendicular Ramp): 109

Name: CR_198

Address: 1758 NE Airport Rd

TruncDomes:

Comments: On airport rd

D1_LandingDim1: 4.7

D2_LandingDim2: 5.1

D3_RampWidth: 4.7

S1_LandingSlope1: 0.4

S2_LandingSlope2: 1.3

S3_RampSlope: 9.8

S4_RampCrossSlope: 1.3

S5_WingSlope1: 12.8


S6_WingSlope2: 7.6

S7_CounterSlope: 13.9

GutterSlope: 0.1

LipHeight:

CR_199





OBJECTID (Perpendicular Ramp): 110

Name: CR_199

Address: 1758 NE Airport Rd

TruncDomes:

Comments: On Stuart pkwy

D1_LandingDim1: 4.8

D2_LandingDim2: 7.3

D3_RampWidth: 4.8

S1_LandingSlope1: 1.7

S2_LandingSlope2: 0.7

S3_RampSlope: 8.2

S4_RampCrossSlope: 1.4

S5_WingSlope1: 11.9


S6_WingSlope2: 8.2

S7_CounterSlope: 16.5

GutterSlope: 0.7

LipHeight:

CR_284





OBJECTID (Perpendicular Ramp): 195

Name: CR_284

Address: 1758 NE Airport Rd

TruncDomes:

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 5.1

D3_RampWidth: 4.5

S1_LandingSlope1: 1.0

S2_LandingSlope2: 2.9

S3_RampSlope: 8.4

S4_RampCrossSlope: 2.6

S5_WingSlope1: 5.4


S6_WingSlope2: 12.6

S7_CounterSlope: 11.8

GutterSlope: 3.7

LipHeight:

CR_285





OBJECTID (Perpendicular Ramp): 196

Name: CR_285

Address: 1758 NE Airport Rd

TruncDomes:

Comments: Non compliant ramp on airport

D1_LandingDim1: 5.4

D2_LandingDim2: 5.8

D3_RampWidth: 5.4

S1_LandingSlope1: 0.9

S2_LandingSlope2: 4.6

S3_RampSlope: 7.9

S4_RampCrossSlope: 0.6

S5_WingSlope1: 9.7


S6_WingSlope2: 5.0

S7_CounterSlope: 9.6

GutterSlope: 2.3

LipHeight:

CR_286





OBJECTID (Perpendicular Ramp): 197

Name: CR_286

Address: 1758 NE Airport Rd

TruncDomes:

Comments: Non compliant ramp on Stewart pkwy

D1_LandingDim1: 5.5

D2_LandingDim2: 6.3

D3_RampWidth: 5.5

S1_LandingSlope1: 0.1

S2_LandingSlope2: 3.4

S3_RampSlope: 8.3

S4_RampCrossSlope: 0.2

S5_WingSlope1: 8.7

S6_WingSlope2: 2.7

S7_CounterSlope: 8.0

GutterSlope: 1.3

LipHeight:

CR_532





OBJECTID (Perpendicular Ramp): 444

Name: CR_532

Address: 1758 NE Airport Rd

TruncDomes:

Comments:

D1_LandingDim1: 5.9

D2_LandingDim2: 5.8

D3_RampWidth: 5.9

S1_LandingSlope1: 1.1

S2_LandingSlope2: 2.7

S3_RampSlope: 9.6

S4_RampCrossSlope: 1.0

S5_WingSlope1: 8.6


S6_WingSlope2: 7.0

S7_CounterSlope: 7.9

GutterSlope: 2.0

LipHeight:

CR_533





OBJECTID (Perpendicular Ramp): 445

Name: CR_533

Address: 1453 NE Airport Rd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 2.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.3

S4_RampCrossSlope: 5.8

S5_WingSlope1: 14.6


S6_WingSlope2: 21.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_572





OBJECTID (Perpendicular Ramp): 484

Name: CR_572

Address: 1453 NE Airport Rd

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.4

S4_RampCrossSlope: 7.1

S5_WingSlope1: 29.7

S6_WingSlope2: 21.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_748





OBJECTID (Parallel Ramp): 25

Name: CR_748

Address: 532 NE Alameda Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.5

S1_LandingSlope1: 1.6

S2_LandingSlope2: 0.7

S3_RampCrossSlope1: 0.8

S4_RampSlope1: 6.4

S5_RampCrossSlope2: 1.7

S6_RampSlope2: 5.7

S7_CounterSlope: 0.9

GutterSlope: 1.4

LipHeight:

CR_851





OBJECTID (Unclassified Ramp): 26 **Address:** 1021 NE Alameda Ave

Name: CR_851

CR_852






OBJECTID (Unclassified Ramp): 27 **Address:** 1042 NE Alameda Ave

Name: CR_852

CR_193





OBJECTID (Perpendicular Ramp): 104

Name: CR_193

Address: 691 NE Alameda Ave

TruncDomes:

Comments: On alameda

D1_LandingDim1: 4.0

D2_LandingDim2: 3.4

D3_RampWidth: 4.0

S1_LandingSlope1: 2.5

S2_LandingSlope2: 4.0

S3_RampSlope: 11.1

S4_RampCrossSlope: 4.1

S5_WingSlope1: 13.3

S6_WingSlope2: 7.4

S7_CounterSlope: 4.5

GutterSlope:

LipHeight:

CR_194





OBJECTID (Perpendicular Ramp): 105

Name: CR_194

Address: 691 NE Alameda Ave

TruncDomes:

Comments: On vine

D1_LandingDim1: 4.0

D2_LandingDim2: 3.5

D3_RampWidth: 4.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 2.1

S3_RampSlope: 9.5

S4_RampCrossSlope: 1.9

S5_WingSlope1: 10.3


S6_WingSlope2: 9.6

S7_CounterSlope: 6.8

GutterSlope:

LipHeight:

CR_195





OBJECTID (Perpendicular Ramp): 106

Name: CR_195

Address: 691 NE Alameda Ave

TruncDomes:

Comments: On alameda

D1_LandingDim1: 4.1

D2_LandingDim2: 3.1

D3_RampWidth: 4.1

S1_LandingSlope1: 0.3

S2_LandingSlope2: 1.3

S3_RampSlope: 9.5

S4_RampCrossSlope: 0.7

S5_WingSlope1: 13.3


S6_WingSlope2: 10.0

S7_CounterSlope: 5.8

GutterSlope: 1.7

LipHeight:

CR_196





OBJECTID (Perpendicular Ramp): 107

Name: CR_196

Address: 691 NE Alameda Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.5

D3_RampWidth: 4.0

S1_LandingSlope1: 0.5

S2_LandingSlope2: 3.3

S3_RampSlope: 8.7

S4_RampCrossSlope: 4.4

S5_WingSlope1: 8.8

S6_WingSlope2: 9.5

S7_CounterSlope: 5.5

GutterSlope: 2.4

LipHeight:

CR_279





OBJECTID (Perpendicular Ramp): 190

Name: CR_279

Address: 691 NE Alameda Ave

TruncDomes:

Comments: Non compliant ramp on alameda

D1_LandingDim1: 4.0

D2_LandingDim2: 3.4

D3_RampWidth: 4.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 0.4

S3_RampSlope: 8.8

S4_RampCrossSlope: 0.3

S5_WingSlope1: 9.5


S6_WingSlope2: 11.4

S7_CounterSlope: 9.3

GutterSlope: 0.3

LipHeight:

CR_280





OBJECTID (Perpendicular Ramp): 191

Name: CR_280

Address: 691 NE Alameda Ave

TruncDomes:

Comments: Non compliant ramp on vine

D1_LandingDim1: 4.0

D2_LandingDim2: 3.6

D3_RampWidth: 4.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 0.3

S3_RampSlope: 8.4

S4_RampCrossSlope: 0.4

S5_WingSlope1: 10.1


S6_WingSlope2: 10.3

S7_CounterSlope: 6.8

GutterSlope: 0.8

LipHeight:

CR_281





OBJECTID (Perpendicular Ramp): 192

Name: CR_281

Address: 682 NE Alameda Ave

TruncDomes:

Comments: Non compliant ramp on vine

D1_LandingDim1: 4.0

D2_LandingDim2: 3.1

D3_RampWidth: 4.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 6.2

S3_RampSlope: 7.0

S4_RampCrossSlope: 2.2

S5_WingSlope1: 8.7


S6_WingSlope2: 12.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_282





OBJECTID (Perpendicular Ramp): 193

Name: CR_282

Address: 682 NE Alameda Ave

TruncDomes:

Comments: On alameda

D1_LandingDim1: 4.0

D2_LandingDim2: 3.7

D3_RampWidth: 4.0

S1_LandingSlope1: 0.1

S2_LandingSlope2: 6.4

S3_RampSlope: 7.8

S4_RampCrossSlope: 4.3

S5_WingSlope1: 5.6

S6_WingSlope2: 16.7

S7_CounterSlope: 7.3

GutterSlope: 2.8

LipHeight:

CR_442





OBJECTID (Perpendicular Ramp): 354

Name: CR_442

Address: 1673 NW Almond Ave

TruncDomes:

Comments: No ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.6

S4_RampCrossSlope: 3.1

S5_WingSlope1: 26.6

S6_WingSlope2: 16.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_59





OBJECTID (Combination Ramp): 12

Name: CR_59

Address: 2825 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.2

D3_RampWidth2: 6.5

D4_RampWidth3: 6.5

D5_RampWidth1: 3.9

S1_LandingSlope1: 1.3

S2_LandingSlope2: 1.0

S3_RampCrossSlope2: 2.7

S4_RampSlope2: 3.5

S5_RampCrossSlope3: 1.2

S6_RampSlope3: 8.8

S7_RampSlope1: 9.1

S8_RampCrossSlope1: 1.0

S9_WingSlope1: 6.8


S10_WingSlope2: 12.2

S11_CounterSlope: -3.2

GutterSlope: 0.2

LipHeight:

CR_60





OBJECTID (Combination Ramp): 13

Name: CR_60

Address: 2805 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth2: 6.4

D4_RampWidth3: 6.5

D5_RampWidth1: 3.9

S1_LandingSlope1: 3.4

S2_LandingSlope2: 1.7

S3_RampCrossSlope2: 1.6

S4_RampSlope2: 12.0

S5_RampCrossSlope3: 2.2

S6_RampSlope3: 6.9

S7_RampSlope1: 7.6

S8_RampCrossSlope1: 1.5

S9_WingSlope1: 13.7


S10_WingSlope2: 10.0

S11_CounterSlope: -1.8

GutterSlope: 1.8

LipHeight:

CR_64





OBJECTID (Combination Ramp): 17

Name: CR_64

Address: 3354 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 3.8

D3_RampWidth2: 6.5

D4_RampWidth3: 6.2

D5_RampWidth1: 5.0

S1_LandingSlope1: 2.3

S2_LandingSlope2: 1.6

S3_RampCrossSlope2: 1.2

S4_RampSlope2: 1.8

S5_RampCrossSlope3: 1.1

S6_RampSlope3: 10.4

S7_RampSlope1: 10.5

S8_RampCrossSlope1: 2.2

S9_WingSlope1: 8.2


S10_WingSlope2: 11.3

S11_CounterSlope: -1.1

GutterSlope: 3.3

LipHeight:

CR_71





OBJECTID (Combination Ramp): 24

Name: CR_71

Address: 3354 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.1

D3_RampWidth2: 6.5

D4_RampWidth3: 6.5

D5_RampWidth1: 4.9

S1_LandingSlope1: 2.0

S2_LandingSlope2: 1.6

S3_RampCrossSlope2: 2.4

S4_RampSlope2: 7.9

S5_RampCrossSlope3: 1.5

S6_RampSlope3: 7.3

S7_RampSlope1: 2.9

S8_RampCrossSlope1: 0.1

S9_WingSlope1: 7.2

S10_WingSlope2: 8.6

S11_CounterSlope: -5.2

GutterSlope: 0.3

LipHeight:

CR_72





OBJECTID (Combination Ramp): 25

Name: CR_72

Address: 3200 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.7

D3_RampWidth2: 6.2

D4_RampWidth3: 6.7

D5_RampWidth1: 4.7

S1_LandingSlope1: 1.7

S2_LandingSlope2: 1.5

S3_RampCrossSlope2: 3.8

S4_RampSlope2: 4.9

S5_RampCrossSlope3: 1.9

S6_RampSlope3: 0.3

S7_RampSlope1: 6.4

S8_RampCrossSlope1: 2.4

S9_WingSlope1: 6.6


S10_WingSlope2: 5.1

S11_CounterSlope: 3.5

GutterSlope: 1.7

LipHeight:

CR_752





OBJECTID (Parallel Ramp): 29

Name: CR_752

Address: 2371 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.7

S1_LandingSlope1: 0.8

S2_LandingSlope2: 0.9

S3_RampCrossSlope1: 0.6

S4_RampSlope1: 6.1

S5_RampCrossSlope2: 0.3

S6_RampSlope2: 3.4

S7_CounterSlope: 4.4

GutterSlope: 2.4

LipHeight:

CR_753





OBJECTID (Parallel Ramp): 30

Name: CR_753

Address: 2371 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.9

S1_LandingSlope1: 1.9

S2_LandingSlope2: 0.3

S3_RampCrossSlope1: 1.2

S4_RampSlope1: 4.4

S5_RampCrossSlope2: 1.2

S6_RampSlope2: 7.5

S7_CounterSlope: 4.5

GutterSlope: 0.7

LipHeight:

CR_763





OBJECTID (Parallel Ramp): 40

Name: CR_763

Address: 3200 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 7.2

S1_LandingSlope1: 0.3

S2_LandingSlope2: 2.9

S3_RampCrossSlope1: 1.3

S4_RampSlope1: 11.8

S5_RampCrossSlope2: 1.9

S6_RampSlope2: 3.2

S7_CounterSlope: 2.0

GutterSlope: 3.4

LipHeight:

CR_764





OBJECTID (Parallel Ramp): 41

Name: CR_764

Address: 3200 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 6.5

S1_LandingSlope1: 2.6

S2_LandingSlope2: 2.0

S3_RampCrossSlope1: 2.4

S4_RampSlope1: 7.3

S5_RampCrossSlope2: 2.2

S6_RampSlope2: 9.4

S7_CounterSlope: 2.8

GutterSlope: 1.2

LipHeight:

CR_766





OBJECTID (Parallel Ramp): 43

Name: CR_766

Address: 3200 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 6.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 0.1

S3_RampCrossSlope1: 2.3

S4_RampSlope1: 7.3

S5_RampCrossSlope2: 1.6

S6_RampSlope2: 3.8

S7_CounterSlope: -5.9

GutterSlope: 1.0

LipHeight:

CR_775





OBJECTID (Parallel Ramp): 52

Name: CR_775

Address: 3100 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.9

S1_LandingSlope1: 1.7

S2_LandingSlope2: 1.8

S3_RampCrossSlope1: 2.6

S4_RampSlope1: 2.9

S5_RampCrossSlope2: 2.3

S6_RampSlope2: 10.6

S7_CounterSlope: 5.5

GutterSlope:

LipHeight:

CR_776





OBJECTID (Parallel Ramp): 53

Name: CR_776

Address: 3200 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 9.4

S1_LandingSlope1: 1.1

S2_LandingSlope2: 0.2

S3_RampCrossSlope1: 1.3

S4_RampSlope1: 2.8

S5_RampCrossSlope2: 0.8

S6_RampSlope2: 5.8

S7_CounterSlope: -2.7

GutterSlope: 0.2

LipHeight:

CR_777





OBJECTID (Parallel Ramp): 54

Name: CR_777

Address: 2371 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 6.0

D2_LandingDim2: 4.4

S1_LandingSlope1: 1.8

S2_LandingSlope2: 2.7

S3_RampCrossSlope1: 1.9

S4_RampSlope1: 5.6

S5_RampCrossSlope2: 1.2


S6_RampSlope2: 0.5

S7_CounterSlope: 0.9

GutterSlope: 0.1

LipHeight:

CR_778





OBJECTID (Parallel Ramp): 55

Name: CR_778

Address: 2371 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 1.1

S3_RampCrossSlope1: 2.3

S4_RampSlope1: 2.8

S5_RampCrossSlope2: 8.1

S6_RampSlope2: 2.2

S7_CounterSlope: 1.4

GutterSlope: 1.2

LipHeight:

CR_882





OBJECTID (Unclassified Ramp): 57 **Address:** 3200 NW Aviation Dr

Name: CR_882

CR_201





OBJECTID (Perpendicular Ramp): 112

Name: CR_201

Address: 2321 NW Aviation Dr

TruncDomes:

Comments: No landing. Hydrant at back of ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.6

S4_RampCrossSlope: 4.2

S5_WingSlope1: 7.3


S6_WingSlope2: 9.6

S7_CounterSlope: 13.9

GutterSlope:

LipHeight:

CR_288





OBJECTID (Perpendicular Ramp): 199

Name: CR_288

Address: 2321 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.6

S4_RampCrossSlope: 4.3

S5_WingSlope1: 13.3

S6_WingSlope2: 5.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_304





OBJECTID (Perpendicular Ramp): 215

Name: CR_304

Address: 3000 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.6

S2_LandingSlope2: 3.3

S3_RampSlope: 7.8

S4_RampCrossSlope: 2.8

S5_WingSlope1: 9.4


S6_WingSlope2: 5.2

S7_CounterSlope: 2.0

GutterSlope: 3.1

LipHeight:

CR_305





OBJECTID (Perpendicular Ramp): 216

Name: CR_305

Address: 2251 NW Aviation Dr

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.8

S4_RampCrossSlope:

S5_WingSlope1: 9.9


S6_WingSlope2: 6.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_306





OBJECTID (Perpendicular Ramp): 217

Name: CR_306

Address: 2251 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 3.4

D2_LandingDim2: 2.7

D3_RampWidth: 4.0

S1_LandingSlope1: 3.4

S2_LandingSlope2: 2.1

S3_RampSlope: 10.2

S4_RampCrossSlope: 1.9

S5_WingSlope1: 9.7


S6_WingSlope2: 11.1

S7_CounterSlope: 3.9

GutterSlope: 1.6

LipHeight:

CR_307





OBJECTID (Perpendicular Ramp): 218

Name: CR_307

Address: 2151 NW Aviation Dr

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.6

S4_RampCrossSlope: 6.6

S5_WingSlope1: 4.1


S6_WingSlope2: 14.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_394





OBJECTID (Perpendicular Ramp): 306

Name: CR_394

Address: 3030 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.1

D3_RampWidth: 5.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 2.7

S3_RampSlope: 9.8

S4_RampCrossSlope: 3.6

S5_WingSlope1: 7.9


S6_WingSlope2: 9.3

S7_CounterSlope: 2.4

GutterSlope: 0.1

LipHeight:

CR_486





OBJECTID (Perpendicular Ramp): 398

Name: CR_486

Address: 3030 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.5

S2_LandingSlope2: 0.6

S3_RampSlope: 7.3

S4_RampCrossSlope: 0.2

S5_WingSlope1: 7.4

S6_WingSlope2: 6.3

S7_CounterSlope: 0.5

GutterSlope: 1.7

LipHeight:

CR_487





OBJECTID (Perpendicular Ramp): 399

Name: CR_487

Address: 3000 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 3.9

D3_RampWidth: 4.9

S1_LandingSlope1: 1.3

S2_LandingSlope2: 2.9

S3_RampSlope: 8.5

S4_RampCrossSlope: 4.8

S5_WingSlope1: 8.7


S6_WingSlope2: 11.9

S7_CounterSlope: 5.3

GutterSlope:

LipHeight: 0.3

CR_488





OBJECTID (Perpendicular Ramp): 400

Name: CR_488

Address: 2868 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.6

D3_RampWidth: 5.0

S1_LandingSlope1: 3.0

S2_LandingSlope2: 1.6

S3_RampSlope: 8.5

S4_RampCrossSlope: 2.0

S5_WingSlope1: 10.0


S6_WingSlope2: 12.1

S7_CounterSlope: 1.9

GutterSlope: 0.4

LipHeight:

CR_489





OBJECTID (Perpendicular Ramp): 401

Name: CR_489

Address: 2866 NW Aviation Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 2.4

S3_RampSlope: 6.5

S4_RampCrossSlope: 3.1

S5_WingSlope1: 8.7


S6_WingSlope2: 13.0

S7_CounterSlope: 0.3

GutterSlope: 1.8

LipHeight:

CR_490





OBJECTID (Perpendicular Ramp): 402

Name: CR_490

Address: 2251 NW Aviation Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 0.6

S5_WingSlope1: 8.6


S6_WingSlope2: 11.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_491





OBJECTID (Perpendicular Ramp): 403

Name: CR_491

Address: 2251 NW Aviation Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.2

S4_RampCrossSlope: 5.0

S5_WingSlope1: 4.2


S6_WingSlope2: 10.3

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_492





OBJECTID (Perpendicular Ramp): 404

Name: CR_492

Address: 2151 NW Aviation Dr

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 2.9

S2_LandingSlope2: 2.3

S3_RampSlope: 8.7

S4_RampCrossSlope: 0.1

S5_WingSlope1: 22.9


S6_WingSlope2: 13.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_893






OBJECTID (Unclassified Ramp): 68 **Address:** 490 W Bellows St

Name: CR_893

CR_894






OBJECTID (Unclassified Ramp): 69 **Address:** 490 W Bellows St

Name: CR_894

CR_534





OBJECTID (Perpendicular Ramp): 446

Name: CR_534

Address: 492 W Bellows St

TruncDomes:

Comments:

D1_LandingDim1: 3.5

D2_LandingDim2: 3.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.4

S3_RampSlope: 6.5

S4_RampCrossSlope: 4.5

S5_WingSlope1: 10.0


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_535





OBJECTID (Perpendicular Ramp): 447

Name: CR_535

Address: 494 W Bellows St

TruncDomes:

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 3.9

D3_RampWidth: 5.0

S1_LandingSlope1: 2.4

S2_LandingSlope2: 1.7

S3_RampSlope: 9.0

S4_RampCrossSlope: 1.1

S5_WingSlope1: 5.7


S6_WingSlope2: 7.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_536





OBJECTID (Perpendicular Ramp): 448

Name: CR_536

Address: 494 W Bellows St

TruncDomes:

Comments: No landing

D1_LandingDim1: 2.2

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 0.4

S5_WingSlope1: 16.8


S6_WingSlope2: 14.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_537





OBJECTID (Perpendicular Ramp): 449

Name: CR_537

Address: 496 W Bellows St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 2.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 1.9

S5_WingSlope1: 14.4


S6_WingSlope2: 15.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_573





OBJECTID (Perpendicular Ramp): 485

Name: CR_573

Address: 490 W Bellows St

TruncDomes:

Comments:

D1_LandingDim1: 3.3

D2_LandingDim2: 3.0

D3_RampWidth: 4.7

S1_LandingSlope1: 2.9

S2_LandingSlope2: 0.7

S3_RampSlope: 7.9

S4_RampCrossSlope: 1.2

S5_WingSlope1: 8.6

S6_WingSlope2: 7.6

S7_CounterSlope: 9.6

GutterSlope: 0.4

LipHeight:

CR_89





OBJECTID (Combination Ramp): 42

Name: CR_89

Address: 640 NE Bellview Ct

TruncDomes: True

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 3.8

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 3.0

S3_RampCrossSlope2: 1.7

S4_RampSlope2: 6.1

S5_RampCrossSlope3: 1.0

S6_RampSlope3: 13.5

S7_RampSlope1: 2.4

S8_RampCrossSlope1: 3.6

S9_WingSlope1: 5.4

S10_WingSlope2: 10.1

S11_CounterSlope: 9.8

GutterSlope: 2.4

LipHeight:

CR_686





OBJECTID (Perpendicular Ramp): 598

Name: CR_686

Address: 620 NE Bellview Ct

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.2

S4_RampCrossSlope: 6.9

S5_WingSlope1: 8.7

S6_WingSlope2: 21.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_368





OBJECTID (Perpendicular Ramp): 280

Name: CR_368

Address: 110 NW Brent Ct

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 8.4

S5_WingSlope1: 13.0

S6_WingSlope2: 24.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_452





OBJECTID (Perpendicular Ramp): 364

Name: CR_452

Address: 110 NW Brent Ct

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 19.5

S5_WingSlope1: 8.7

S6_WingSlope2: 38.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_61





OBJECTID (Combination Ramp): 14

Name: CR_61

Address: 3307 Broad St

TruncDomes: True

Comments: Broad St

D1_LandingDim1: 5.0

D2_LandingDim2: 5.8

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 5.2

S3_RampCrossSlope2: 1.2

S4_RampSlope2: 4.7

S5_RampCrossSlope3: 0.7

S6_RampSlope3: 11.8

S7_RampSlope1: 4.1

S8_RampCrossSlope1: 4.4

S9_WingSlope1: 5.2

S10_WingSlope2: 11.8

S11_CounterSlope: 5.9

GutterSlope: 3.1

LipHeight:

CR_68





OBJECTID (Combination Ramp): 21

Name: CR_68

Address: 3265 Broad St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.8

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 0.1

S3_RampCrossSlope2: 0.2

S4_RampSlope2: 12.2

S5_RampCrossSlope3: 0.9

S6_RampSlope3: 5.2

S7_RampSlope1: 2.7

S8_RampCrossSlope1: 1.1

S9_WingSlope1: 10.6

S10_WingSlope2: 5.6

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_69





OBJECTID (Combination Ramp): 22

Name: CR_69

Address: 3307 Broad St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 2.4

S2_LandingSlope2: 2.8

S3_RampCrossSlope2: 1.8

S4_RampSlope2: 9.9

S5_RampCrossSlope3: 0.7

S6_RampSlope3: 4.5

S7_RampSlope1: 2.2

S8_RampCrossSlope1: 0.6

S9_WingSlope1: 10.0

S10_WingSlope2: 5.3

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_765





OBJECTID (Parallel Ramp): 42

Name: CR_765

Address: 3261 Broad St

TruncDomes: True

Comments: Broad st Non compliant ramp no landing

D1_LandingDim1: 5.0

D2_LandingDim2: 5.8

S1_LandingSlope1: 2.3

S2_LandingSlope2: 4.4

S3_RampCrossSlope1: 0.6

S4_RampSlope1: 4.3

S5_RampCrossSlope2: 0.4


S6_RampSlope2: 12.6

S7_CounterSlope: 8.4

GutterSlope: 4.1

LipHeight:

CR_65





OBJECTID (Combination Ramp): 18

Name: CR_65

Address: 1999 NW Calkins Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 3.9

D3_RampWidth2: 5.9

D4_RampWidth3: 5.7

D5_RampWidth1: 5.1

S1_LandingSlope1: 5.0

S2_LandingSlope2: 2.4

S3_RampCrossSlope2: 7.5

S4_RampSlope2: 12.6

S5_RampCrossSlope3: 4.7

S6_RampSlope3: 12.5

S7_RampSlope1: 7.9

S8_RampCrossSlope1: 5.8

S9_WingSlope1: 2.6

S10_WingSlope2: 9.9

S11_CounterSlope: 10.8

GutterSlope: 5.9

LipHeight:

CR_336





OBJECTID (Perpendicular Ramp): 248

Name: CR_336

Address: 1999 NW Calkins Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 5.3

S5_WingSlope1: 18.1


S6_WingSlope2: 7.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_338





OBJECTID (Perpendicular Ramp): 250

Name: CR_338

Address: 1777 NW Calkins Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.1

S4_RampCrossSlope: 0.1

S5_WingSlope1: 8.6


S6_WingSlope2: 9.9

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_421





OBJECTID (Perpendicular Ramp): 333

Name: CR_421

Address: 2062 NW Calkins Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.7

S4_RampCrossSlope: 12.4

S5_WingSlope1: 6.8


S6_WingSlope2: 21.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_422





OBJECTID (Perpendicular Ramp): 334

Name: CR_422

Address: 2104 NW Calkins St

TruncDomes:

Comments: No landing. Retaining wall in landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.9

S4_RampCrossSlope: 13.0

S5_WingSlope1: 1.9

S6_WingSlope2: 16.8

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_423





OBJECTID (Perpendicular Ramp): 335

Name: CR_423

Address: 1895 NW Calkins Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.6

S4_RampCrossSlope: 1.3

S5_WingSlope1: 20.5


S6_WingSlope2: 12.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_117





OBJECTID (Perpendicular Ramp): 28

Name: CR_117

Address: 1019 SE Cass Ave

TruncDomes:

Comments: Non compliant ramp - no landing

D1_LandingDim1: 4.0

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.4

S4_RampCrossSlope: 1.4

S5_WingSlope1: 14.5


S6_WingSlope2: 12.1

S7_CounterSlope: 10.0

GutterSlope: 2.1

LipHeight:

CR_118





OBJECTID (Perpendicular Ramp): 29

Name: CR_118

Address: 1019 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 4.3

D3_RampWidth: 5.1

S1_LandingSlope1: 0.3

S2_LandingSlope2: 8.6

S3_RampSlope: 6.9

S4_RampCrossSlope: 4.8

S5_WingSlope1: 3.3


S6_WingSlope2: 11.1

S7_CounterSlope: 6.3

GutterSlope: 5.8

LipHeight:

CR_127





OBJECTID (Perpendicular Ramp): 38

Name: CR_127

Address: 527 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.3

D3_RampWidth: 4.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 2.3

S3_RampSlope: 8.4

S4_RampCrossSlope: 0.7

S5_WingSlope1: 16.2


S6_WingSlope2: 14.7

S7_CounterSlope: 8.0

GutterSlope: 0.5

LipHeight:

CR_162





OBJECTID (Perpendicular Ramp): 73

Name: CR_162

Address: 644 SE Cass Ave

TruncDomes:

Comments: On stephens

D1_LandingDim1: 5.0

D2_LandingDim2: 7.8

D3_RampWidth: 5.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 0.6

S3_RampSlope: 2.7

S4_RampCrossSlope: 1.2

S5_WingSlope1: 6.8


S6_WingSlope2: 8.9

S7_CounterSlope: 2.6

GutterSlope: 0.1

LipHeight:

CR_163





OBJECTID (Perpendicular Ramp): 74

Name: CR_163

Address: 644 SE Cass Ave

TruncDomes:

Comments: On cass

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 0.6

S3_RampSlope: 2.5

S4_RampCrossSlope: 0.6

S5_WingSlope1: 5.8


S6_WingSlope2: 5.1

S7_CounterSlope: 5.1

GutterSlope: 0.7

LipHeight: 0.1

CR_164





OBJECTID (Perpendicular Ramp): 75

Name: CR_164

Address: 644 SE Cass Ave

TruncDomes:

Comments: On cass

D1_LandingDim1: 5.0

D2_LandingDim2: 8.3

D3_RampWidth: 5.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 0.5

S3_RampSlope: 7.2

S4_RampCrossSlope: 1.3

S5_WingSlope1: 7.2


S6_WingSlope2: 11.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_165





OBJECTID (Perpendicular Ramp): 76

Name: CR_165

Address: 644 SE Cass Ave

TruncDomes: True

Comments: On stephens

D1_LandingDim1: 5.0

D2_LandingDim2: 5.8

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 1.4

S3_RampSlope: 7.7

S4_RampCrossSlope: 2.7

S5_WingSlope1: 10.3


S6_WingSlope2: 8.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_166





OBJECTID (Perpendicular Ramp): 77

Name: CR_166

Address: 841 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 5.5

D3_RampWidth: 2.8

S1_LandingSlope1: 0.5

S2_LandingSlope2: 0.6

S3_RampSlope: 10.4

S4_RampCrossSlope: 0.2

S5_WingSlope1: 11.9


S6_WingSlope2: 9.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_173





OBJECTID (Perpendicular Ramp): 84

Name: CR_173

Address: 920 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 4.0

D3_RampWidth: 5.2

S1_LandingSlope1: 4.6

S2_LandingSlope2: 1.6

S3_RampSlope: 11.8

S4_RampCrossSlope: 0.6

S5_WingSlope1: 39.0


S6_WingSlope2: 24.4

S7_CounterSlope: 16.6

GutterSlope: 1.3

LipHeight:

CR_174





OBJECTID (Perpendicular Ramp): 85

Name: CR_174

Address: 920 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.6

D3_RampWidth: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 0.2

S3_RampSlope: 3.1

S4_RampCrossSlope: 0.3

S5_WingSlope1: 3.3


S6_WingSlope2: 4.1

S7_CounterSlope: 5.5

GutterSlope: 0.1

LipHeight:

CR_231





OBJECTID (Perpendicular Ramp): 142

Name: CR_231

Address: 611 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 5.0

D3_RampWidth: 4.9

S1_LandingSlope1: 2.6

S2_LandingSlope2: 1.7

S3_RampSlope: 8.1

S4_RampCrossSlope: 2.9

S5_WingSlope1: 7.5


S6_WingSlope2: 11.0

S7_CounterSlope: -4.1

GutterSlope: 1.8

LipHeight:

CR_232





OBJECTID (Perpendicular Ramp): 143

Name: CR_232

Address: 611 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 0.4

S3_RampSlope: 5.8

S4_RampCrossSlope: 1.2

S5_WingSlope1: 10.1


S6_WingSlope2: 5.9

S7_CounterSlope: -6.3

GutterSlope: 1.3

LipHeight:

CR_233





OBJECTID (Perpendicular Ramp): 144

Name: CR_233

Address: 500 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 2.0

S3_RampSlope: 8.7

S4_RampCrossSlope: 1.7

S5_WingSlope1: 9.4

S6_WingSlope2: 11.3

S7_CounterSlope: 4.6

GutterSlope: 0.4

LipHeight:

CR_268





OBJECTID (Perpendicular Ramp): 179

Name: CR_268

Address: 644 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 3.1

S3_RampSlope: 1.5

S4_RampCrossSlope: 2.5

S5_WingSlope1: 1.6

S6_WingSlope2: 3.8

S7_CounterSlope: 8.6

GutterSlope: 2.6

LipHeight:

CR_269





OBJECTID (Perpendicular Ramp): 180

Name: CR_269

Address: 644 SE Cass Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 1.8

S3_RampSlope: 6.7

S4_RampCrossSlope: 0.2

S5_WingSlope1: 3.0


S6_WingSlope2: 8.5

S7_CounterSlope: 8.0

GutterSlope: 2.1

LipHeight:

CR_200





OBJECTID (Perpendicular Ramp): 111

Name: CR_200

Address: 222 NW Cecil Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.6

D2_LandingDim2: 5.3

D3_RampWidth: 5.3

S1_LandingSlope1: 4.4

S2_LandingSlope2: 3.3

S3_RampSlope: 10.0

S4_RampCrossSlope: 3.7

S5_WingSlope1: 8.3

S6_WingSlope2: 12.8

S7_CounterSlope: 4.9

GutterSlope: 3.8

LipHeight:

CR_287





OBJECTID (Perpendicular Ramp): 198

Name: CR_287

Address: 222 NW Cecil Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 2.9

D3_RampWidth: 5.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 6.0

S3_RampSlope: 7.6

S4_RampCrossSlope: 5.2

S5_WingSlope1: 9.5

S6_WingSlope2: 4.2

S7_CounterSlope: 4.3

GutterSlope: 5.4

LipHeight:

CR_513





OBJECTID (Perpendicular Ramp): 425

Name: CR_513

Address: 1074 NE Cedar St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.5

S4_RampCrossSlope: 3.8

S5_WingSlope1: 16.8

S6_WingSlope2: 10.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_846





OBJECTID (Unclassified Ramp): 21 **Address:** 775 SE Chadwick St

Name: CR_846

CR_847






OBJECTID (Unclassified Ramp): 22 **Address:** 762 SE Chadwick St

Name: CR_847

CR_570





OBJECTID (Perpendicular Ramp): 482

Name: CR_570

Address: 124 NE Channon Ave

TruncDomes:

Comments: On channon

D1_LandingDim1: 4.9

D2_LandingDim2: 2.5

D3_RampWidth: 5.1

S1_LandingSlope1: 2.7

S2_LandingSlope2: 5.1

S3_RampSlope: 10.0

S4_RampCrossSlope: 4.7

S5_WingSlope1: 10.0


S6_WingSlope2: 6.1

S7_CounterSlope: 9.4

GutterSlope: 3.7

LipHeight:

CR_571





OBJECTID (Perpendicular Ramp): 483

Name: CR_571

Address: 124 NE Channon Ave

TruncDomes:

Comments: On airport rd

D1_LandingDim1: 3.7

D2_LandingDim2: 5.3

D3_RampWidth: 4.3

S1_LandingSlope1: 0.7

S2_LandingSlope2: 5.1

S3_RampSlope: 9.0

S4_RampCrossSlope: 3.1

S5_WingSlope1: 12.9

S6_WingSlope2: 6.5

S7_CounterSlope: 10.8

GutterSlope: 4.7

LipHeight:

CR_887





OBJECTID (Unclassified Ramp): 62 **Address:** 526 NE Chestnut Ave

Name: CR_887

CR_518





OBJECTID (Perpendicular Ramp): 430

Name: CR_518

Address: 486 NE Chestnut Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.7

D2_LandingDim2: 3.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 1.5

S3_RampSlope: 8.7

S4_RampCrossSlope: 0.7

S5_WingSlope1: 6.3

S6_WingSlope2: 4.5

S7_CounterSlope: 10.8

GutterSlope:

LipHeight:

CR_519





OBJECTID (Perpendicular Ramp): 431

Name: CR_519

Address: 525 NE Chestnut Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.1

D2_LandingDim2: 4.3

D3_RampWidth: 4.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 5.9

S3_RampSlope: 7.5

S4_RampCrossSlope: 5.9

S5_WingSlope1: 13.1

S6_WingSlope2: 2.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_555





OBJECTID (Perpendicular Ramp): 467

Name: CR_555

Address: 245 NE Chestnut Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 3.5

S5_WingSlope1: 14.0

S6_WingSlope2: 19.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_556





OBJECTID (Perpendicular Ramp): 468

Name: CR_556

Address: 245 NE Chestnut Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 6.5

S5_WingSlope1: 17.8

S6_WingSlope2: 13.5

S7_CounterSlope:

GutterSlope:

LipHeight: 0.3

CR_557





OBJECTID (Perpendicular Ramp): 469

Name: CR_557

Address: 245 NE Chestnut Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.0

S4_RampCrossSlope: 3.5

S5_WingSlope1: 14.3


S6_WingSlope2: 14.8

S7_CounterSlope:

GutterSlope:

LipHeight: 0.3

CR_560



OBJECTID (Perpendicular Ramp): 472

Name: CR_560

Address: 485 NE Chestnut Ave

TruncDomes:

Comments: Onchestnut

D1_LandingDim1: 3.7

D2_LandingDim2: 3.5

D3_RampWidth: 4.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 4.6

S3_RampSlope: 7.3

S4_RampCrossSlope: 2.6

S5_WingSlope1: 15.2


S6_WingSlope2: 4.1

S7_CounterSlope: 7.3

GutterSlope: 3.3

LipHeight:

CR_561





OBJECTID (Perpendicular Ramp): 473

Name: CR_561

Address: 485 NE Chestnut Ave

TruncDomes:

Comments: On walnut

D1_LandingDim1: 3.3

D2_LandingDim2: 4.3

D3_RampWidth: 4.0

S1_LandingSlope1: 2.6

S2_LandingSlope2: 3.8

S3_RampSlope: 10.0

S4_RampCrossSlope: 3.4

S5_WingSlope1: 13.0

S6_WingSlope2: 3.6

S7_CounterSlope: 4.4

GutterSlope: 2.6

LipHeight:

CR_562





OBJECTID (Perpendicular Ramp): 474

Name: CR_562

Address: 565 NE Chestnut Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.7

D2_LandingDim2: 5.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 7.2

S3_RampSlope: 7.2

S4_RampCrossSlope: 7.2

S5_WingSlope1: 13.2

S6_WingSlope2: 2.0

S7_CounterSlope: 7.2

GutterSlope: 7.3

LipHeight:

CR_563





OBJECTID (Perpendicular Ramp): 475

Name: CR_563

Address: 526 NE Chestnut Ave

TruncDomes:

Comments: No landing/grade break

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.8

S4_RampCrossSlope: 1.2

S5_WingSlope1: 9.1

S6_WingSlope2: 5.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_109





OBJECTID (Perpendicular Ramp): 20

Name: CR_109

Address: 2200 SE Chinaberry Ave

TruncDomes:

Comments: On ramp

D1_LandingDim1: 4.6

D2_LandingDim2: 5.4

D3_RampWidth: 4.6

S1_LandingSlope1: 0.5

S2_LandingSlope2: 2.5

S3_RampSlope: 3.3

S4_RampCrossSlope: 1.6

S5_WingSlope1: 6.7

S6_WingSlope2: 2.5

S7_CounterSlope: 3.2

GutterSlope: 1.6

LipHeight:

CR_110





OBJECTID (Perpendicular Ramp): 21

Name: CR_110

Address: 2200 SE Chinaberry Ave

TruncDomes:

Comments: On chinaberry ave

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 2.1

S3_RampSlope: 3.1

S4_RampCrossSlope: 2.2

S5_WingSlope1: 8.1

S6_WingSlope2: 2.9

S7_CounterSlope: 2.4

GutterSlope: 1.6

LipHeight: 0.1

CR_229





OBJECTID (Perpendicular Ramp): 140

Name: CR_229

Address: 2201 SE Chinaberry Ave

TruncDomes:

Comments: On chinaberry

D1_LandingDim1: 4.8

D2_LandingDim2: 4.5

D3_RampWidth: 4.8

S1_LandingSlope1: 6.3

S2_LandingSlope2: 6.0

S3_RampSlope: 6.2

S4_RampCrossSlope: 4.6

S5_WingSlope1: 2.0


S6_WingSlope2: 13.9

S7_CounterSlope: 3.3

GutterSlope:

LipHeight:

CR_230





OBJECTID (Perpendicular Ramp): 141

Name: CR_230

Address: 2201 SE Chinaberry Ave

TruncDomes:

Comments: On Ramp St

D1_LandingDim1: 4.9

D2_LandingDim2: 6.0

D3_RampWidth: 4.9

S1_LandingSlope1: 5.4

S2_LandingSlope2: 7.0

S3_RampSlope: 5.9

S4_RampCrossSlope: 6.4

S5_WingSlope1: 3.3

S6_WingSlope2: 10.2

S7_CounterSlope: 2.9

GutterSlope: 5.0

LipHeight:

CR_550





OBJECTID (Perpendicular Ramp): 462

Name: CR_550

Address: 728 NE Church Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 3.5

D3_RampWidth: 5.2

S1_LandingSlope1: 0.9

S2_LandingSlope2: 3.3

S3_RampSlope: 8.5

S4_RampCrossSlope: 3.3

S5_WingSlope1: 5.3

S6_WingSlope2: 12.3

S7_CounterSlope: 7.4

GutterSlope: 3.4

LipHeight:

CR_799





OBJECTID (Parallel Ramp): 76

Name: CR_799

Address: 463 NE Clover Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.1

S2_LandingSlope2: 1.1

S3_RampCrossSlope1: 1.8

S4_RampSlope1: 6.4

S5_RampCrossSlope2: 0.7

S6_RampSlope2: 0.7

S7_CounterSlope: 0.1

GutterSlope: 1.7

LipHeight:

CR_816





OBJECTID (Parallel Ramp): 93

Name: CR_816

Address: 463 NE Clover Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 2.0

S3_RampCrossSlope1: 0.7

S4_RampSlope1: 2.7

S5_RampCrossSlope2: 2.1

S6_RampSlope2: 6.8

S7_CounterSlope: 1.2

GutterSlope: 2.9

LipHeight:

CR_377





OBJECTID (Perpendicular Ramp): 289

Name: CR_377

Address: 1945 NW Delridge Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.0

S4_RampCrossSlope: 6.3

S5_WingSlope1: 5.3


S6_WingSlope2: 15.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_378





OBJECTID (Perpendicular Ramp): 290

Name: CR_378

Address: 1945 NW Delridge Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.0

S4_RampCrossSlope: 3.1

S5_WingSlope1: 16.1


S6_WingSlope2: 9.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_464





OBJECTID (Perpendicular Ramp): 376

Name: CR_464

Address: 2025 NW Delridge Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.4

S4_RampCrossSlope: 3.5

S5_WingSlope1: 5.9

S6_WingSlope2: 14.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_465





OBJECTID (Perpendicular Ramp): 377

Name: CR_465

Address: 2025 NW Delridge Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 4.4

S5_WingSlope1: 16.2

S6_WingSlope2: 10.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_732





OBJECTID (Parallel Ramp): 9

Name: CR_732

Address: 2646 NE Diamond Lake Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 3.5

S3_RampCrossSlope1: 6.9

S4_RampSlope1: 1.5

S5_RampCrossSlope2: 0.8

S6_RampSlope2: 1.4

S7_CounterSlope: 4.1

GutterSlope: 3.7

LipHeight: 0.1

CR_733





OBJECTID (Parallel Ramp): 10

Name: CR_733

Address: 2646 NE Diamond Lake Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 5.9

S1_LandingSlope1: 2.0

S2_LandingSlope2: 0.2

S3_RampCrossSlope1: 1.8

S4_RampSlope1: 5.3

S5_RampCrossSlope2: 1.8

S6_RampSlope2: 3.4

S7_CounterSlope: -1.1

GutterSlope: 0.8

LipHeight: 0.1

CR_744





OBJECTID (Parallel Ramp): 21

Name: CR_744

Address: 2595 NE Diamond Lake Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.9

S1_LandingSlope1: 2.0

S2_LandingSlope2: 1.8

S3_RampCrossSlope1: 2.0

S4_RampSlope1: 5.5

S5_RampCrossSlope2: 3.6

S6_RampSlope2: 8.0

S7_CounterSlope: 5.9

GutterSlope: 1.0

LipHeight:

CR_745





OBJECTID (Parallel Ramp): 22

Name: CR_745

Address: 2595 NE Diamond Lake Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

S1_LandingSlope1: 3.0

S2_LandingSlope2: 1.1

S3_RampCrossSlope1: 1.7

S4_RampSlope1: 6.0

S5_RampCrossSlope2: 1.4

S6_RampSlope2: 5.4

S7_CounterSlope: 2.6

GutterSlope: 0.8

LipHeight:

CR_746





OBJECTID (Parallel Ramp): 23

Name: CR_746

Address: 2646 NE Diamond Lake Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 1.5

S3_RampCrossSlope1: 2.6

S4_RampSlope1: 6.8

S5_RampCrossSlope2: 2.7

S6_RampSlope2: 6.8

S7_CounterSlope: 6.2

GutterSlope: 3.9

LipHeight:

CR_333





OBJECTID (Perpendicular Ramp): 245

Name: CR_333

Address: 1207 NW Domenico Dr

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.6

S4_RampCrossSlope: 0.4

S5_WingSlope1: 10.4

S6_WingSlope2: 10.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_419





OBJECTID (Perpendicular Ramp): 331

Name: CR_419

Address: 1207 NW Domenico Dr

TruncDomes:

Comments: No landing. Retaining wall in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 2.5

S5_WingSlope1: 13.0


S6_WingSlope2: 22.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_433





OBJECTID (Perpendicular Ramp): 345

Name: CR_433

Address: 1480 NW Domenico Dr

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.9

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.9

S4_RampCrossSlope: 0.3

S5_WingSlope1: 10.6

S6_WingSlope2: 9.3

S7_CounterSlope: 0.6

GutterSlope:

LipHeight:

CR_107





OBJECTID (Perpendicular Ramp): 18

Name: CR_107

Address: 437 SE Dos Gatos Ct

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.7

S2_LandingSlope2: 1.3

S3_RampSlope: 5.1

S4_RampCrossSlope: 1.1

S5_WingSlope1: 2.7

S6_WingSlope2: 11.3

S7_CounterSlope: 0.6

GutterSlope: 2.3

LipHeight: 0.1

CR_227





OBJECTID (Perpendicular Ramp): 138

Name: CR_227

Address: 437 SE Dos Gatos Ct

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 5.6

S2_LandingSlope2: 0.5

S3_RampSlope: 1.6

S4_RampCrossSlope: 2.2

S5_WingSlope1: 3.7

S6_WingSlope2: 11.3

S7_CounterSlope: 2.6

GutterSlope: 0.8

LipHeight:

CR_90





OBJECTID (Perpendicular Ramp): 1

Name: CR_90

Address: 734 SE Douglas Ave

TruncDomes: True

Comments: On Douglas

D1_LandingDim1: 3.3

D2_LandingDim2: 6.8

D3_RampWidth: 3.3

S1_LandingSlope1: 4.6

S2_LandingSlope2: 0.6

S3_RampSlope: 1.2

S4_RampCrossSlope: 0.8

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope: 3.2

GutterSlope:

LipHeight:

CR_826






OBJECTID (Unclassified Ramp): 1 **Address:** 2583 NE Douglas Ave

Name: CR_826

CR_91





OBJECTID (Perpendicular Ramp): 2

Name: CR_91

Address: 734 SE Douglas Ave

TruncDomes: True

Comments: On rose

D1_LandingDim1: 2.9

D2_LandingDim2: 7.4

D3_RampWidth: 3.4

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.3

S3_RampSlope: 0.3

S4_RampCrossSlope: 2.3

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope: -1.3

GutterSlope:

LipHeight:

CR_92





OBJECTID (Perpendicular Ramp): 3

Name: CR_92

Address: 734 SE Douglas Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.5

D3_RampWidth: 4.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 1.4

S3_RampSlope: 2.5

S4_RampCrossSlope: 2.0

S5_WingSlope1: 1.7

S6_WingSlope2: 4.5

S7_CounterSlope: 4.5

GutterSlope: 1.7

LipHeight:

CR_726





OBJECTID (Parallel Ramp): 3

Name: CR_726

Address: 1135 SE Douglas Ave

TruncDomes:

Comments: Non uniform ramp slope. Hydrant at back of ramp overhanging travel path

D1_LandingDim1:

D2_LandingDim2: 6.1

S1_LandingSlope1: 1.7

S2_LandingSlope2: 1.4

S3_RampCrossSlope1:

S4_RampSlope1: 5.7

S5_RampCrossSlope2:


S6_RampSlope2: 2.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_727





OBJECTID (Parallel Ramp): 4

Name: CR_727

Address: 1446 SE Douglas Ave

TruncDomes:

Comments: Retaining wall in landing and wing

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 6.9

S2_LandingSlope2: 0.4

S3_RampCrossSlope1:

S4_RampSlope1: 6.0

S5_RampCrossSlope2:


S6_RampSlope2: 8.8

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_729


Deer Creek
SE Douglas Ave
SE Douglas Ave
SE Douglas Ave

CR_96





OBJECTID (Perpendicular Ramp): 7

Name: CR_96

Address: 900 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 11.5

D3_RampWidth: 5.2

S1_LandingSlope1: 0.8

S2_LandingSlope2: 0.2

S3_RampSlope: 5.0

S4_RampCrossSlope: 0.6

S5_WingSlope1: 4.0

S6_WingSlope2: 2.5

S7_CounterSlope: 4.5

GutterSlope: 0.4

LipHeight:

CR_730





OBJECTID (Parallel Ramp): 7

Name: CR_730

Address: 2083 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 7.1

S2_LandingSlope2: 1.1

S3_RampCrossSlope1:

S4_RampSlope1: 15.6

S5_RampCrossSlope2:


S6_RampSlope2: 9.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_97





OBJECTID (Perpendicular Ramp): 8

Name: CR_97

Address: 900 SE Douglas Ave

TruncDomes:

Comments: On main

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.6

S2_LandingSlope2: 1.2

S3_RampSlope: 3.1

S4_RampCrossSlope: 1.1

S5_WingSlope1: 0.5


S6_WingSlope2: 4.6

S7_CounterSlope: 3.4

GutterSlope: 1.7

LipHeight:

CR_98





OBJECTID (Perpendicular Ramp): 9

Name: CR_98

Address: 900 SE Douglas Ave

TruncDomes:

Comments: On Douglas

D1_LandingDim1: 5.0

D2_LandingDim2: 8.4

D3_RampWidth: 5.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 0.9

S3_RampSlope: 3.1

S4_RampCrossSlope: 0.6

S5_WingSlope1: 4.5


S6_WingSlope2: 2.9

S7_CounterSlope: 3.7

GutterSlope: 0.6

LipHeight:

CR_99





OBJECTID (Perpendicular Ramp): 10

Name: CR_99

Address: 900 SE Douglas Ave

TruncDomes:

Comments: Mid block ramp. No crossing

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.2

S3_RampSlope: 5.3

S4_RampCrossSlope: 1.3

S5_WingSlope1: 3.8


S6_WingSlope2: 6.5

S7_CounterSlope: 5.1

GutterSlope: 1.4

LipHeight:

CR_100





OBJECTID (Perpendicular Ramp): 11

Name: CR_100

Address: 1036 SE Douglas Ave

TruncDomes:

Comments: Mid block no crossing

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 0.6

S3_RampSlope: 5.8

S4_RampCrossSlope: 1.0

S5_WingSlope1: 7.1

S6_WingSlope2: 7.7

S7_CounterSlope: 5.2

GutterSlope: 0.8

LipHeight:

CR_101





OBJECTID (Perpendicular Ramp): 12

Name: CR_101

Address: 1105 SE Douglas Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 0.1

S3_RampSlope: 3.2

S4_RampCrossSlope: 0.2

S5_WingSlope1: 6.1


S6_WingSlope2: 5.3

S7_CounterSlope: 5.4

GutterSlope: 0.8

LipHeight:

CR_102





OBJECTID (Perpendicular Ramp): 13

Name: CR_102

Address: 1105 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1: 7.5

D2_LandingDim2: 4.2

D3_RampWidth: 7.5

S1_LandingSlope1: 0.4

S2_LandingSlope2: 1.2

S3_RampSlope: 3.7

S4_RampCrossSlope: 1.6

S5_WingSlope1: 10.6


S6_WingSlope2: 2.7

S7_CounterSlope: -0.8

GutterSlope: 2.3

LipHeight: 0.1

CR_103





OBJECTID (Perpendicular Ramp): 14

Name: CR_103

Address: 1105 SE Douglas Ave

TruncDomes: True

Comments: On douglas

D1_LandingDim1: 4.7

D2_LandingDim2: 6.8

D3_RampWidth: 4.7

S1_LandingSlope1: 0.6

S2_LandingSlope2: 0.3

S3_RampSlope: 3.4

S4_RampCrossSlope: 1.0

S5_WingSlope1: 5.8


S6_WingSlope2: 4.4

S7_CounterSlope: 1.3

GutterSlope: 0.8

LipHeight:

CR_104





OBJECTID (Perpendicular Ramp): 15

Name: CR_104

Address: 1175 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.1

S3_RampSlope: 4.9

S4_RampCrossSlope: 0.5

S5_WingSlope1: 3.7


S6_WingSlope2: 4.2

S7_CounterSlope: 5.4

GutterSlope: 0.5

LipHeight:

CR_105





OBJECTID (Perpendicular Ramp): 16

Name: CR_105

Address: 1307 SE Douglas Ave

TruncDomes: True

Comments: No north wing . Tree in wing

D1_LandingDim1: 4.3

D2_LandingDim2: 2.8

D3_RampWidth: 4.8

S1_LandingSlope1: 2.5

S2_LandingSlope2: 4.4

S3_RampSlope: 5.9

S4_RampCrossSlope: 4.0

S5_WingSlope1:


S6_WingSlope2: 8.5

S7_CounterSlope: 4.8

GutterSlope:

LipHeight:

CR_106





OBJECTID (Perpendicular Ramp): 17

Name: CR_106

Address: 1405 SE Douglas Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 6.3

S3_RampSlope: 4.9

S4_RampCrossSlope: 5.7

S5_WingSlope1: 2.4


S6_WingSlope2: 12.2

S7_CounterSlope: 5.1

GutterSlope: 6.2

LipHeight:

CR_740





OBJECTID (Parallel Ramp): 17

Name: CR_740

Address: 1446 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 0.4

S2_LandingSlope2: 4.5

S3_RampCrossSlope1:

S4_RampSlope1: 1.6

S5_RampCrossSlope2:

S6_RampSlope2: 10.1

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_742





OBJECTID (Parallel Ramp): 19

Name: CR_742

Address: 1894 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 6.0

S2_LandingSlope2: 3.3

S3_RampCrossSlope1:

S4_RampSlope1: 6.8

S5_RampCrossSlope2:


S6_RampSlope2: 14.8

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_743





OBJECTID (Parallel Ramp): 20

Name: CR_743

Address: 2114 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 10.2

S2_LandingSlope2: 10.2

S3_RampCrossSlope1:

S4_RampSlope1: 10.9

S5_RampCrossSlope2:


S6_RampSlope2: 32.4

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_853






OBJECTID (Unclassified Ramp): 28 **Address:** 2614 NE Douglas Ave

Name: CR_853

CR_215





OBJECTID (Perpendicular Ramp): 126

Name: CR_215

Address: 734 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.9

D3_RampWidth: 5.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 2.4

S3_RampSlope: 6.6

S4_RampCrossSlope: 3.1

S5_WingSlope1: 6.1


S6_WingSlope2: 4.8

S7_CounterSlope: 4.2

GutterSlope: 2.4

LipHeight: 0.3

CR_216





OBJECTID (Perpendicular Ramp): 127

Name: CR_216

Address: 734 SE Douglas Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.5

D2_LandingDim2: 5.0

D3_RampWidth: 4.9

S1_LandingSlope1: 0.2

S2_LandingSlope2: 0.6

S3_RampSlope: 4.5

S4_RampCrossSlope: 0.6

S5_WingSlope1: 4.9


S6_WingSlope2: 8.4

S7_CounterSlope: 2.8

GutterSlope: 1.6

LipHeight:

CR_219





OBJECTID (Perpendicular Ramp): 130

Name: CR_219

Address: 925 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 4.4

D3_RampWidth: 4.2

S1_LandingSlope1: 3.1

S2_LandingSlope2: 1.8

S3_RampSlope: 4.2

S4_RampCrossSlope: 1.1

S5_WingSlope1: 5.2

S6_WingSlope2: 2.7

S7_CounterSlope: 2.7

GutterSlope: 0.9

LipHeight:

CR_221





OBJECTID (Perpendicular Ramp): 132

Name: CR_221

Address: 1036 SE Douglas Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.9

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 1.2

S3_RampSlope: 5.1

S4_RampCrossSlope: 1.0

S5_WingSlope1: 6.0


S6_WingSlope2: 4.5

S7_CounterSlope: 3.7

GutterSlope: 0.8

LipHeight:

CR_222





OBJECTID (Perpendicular Ramp): 133

Name: CR_222

Address: 1124 SE Douglas Ave

TruncDomes: True

Comments: There is a power pole in the landing

D1_LandingDim1: 7.5

D2_LandingDim2: 4.1

D3_RampWidth: 7.5

S1_LandingSlope1: 0.6

S2_LandingSlope2: 0.9

S3_RampSlope: 7.3

S4_RampCrossSlope: 2.0

S5_WingSlope1: 6.3


S6_WingSlope2: 10.9

S7_CounterSlope: 3.4

GutterSlope: 2.2

LipHeight:

CR_223





OBJECTID (Perpendicular Ramp): 134

Name: CR_223

Address: 1105 SE Douglas Ave

TruncDomes: True

Comments: On Kane

D1_LandingDim1: 4.9

D2_LandingDim2: 4.6

D3_RampWidth: 4.9

S1_LandingSlope1: 0.4

S2_LandingSlope2: 0.8

S3_RampSlope: 5.0

S4_RampCrossSlope: 0.5

S5_WingSlope1: 6.0

S6_WingSlope2: 5.4

S7_CounterSlope: 1.7

GutterSlope: 0.5

LipHeight:

CR_224





OBJECTID (Perpendicular Ramp): 135

Name: CR_224

Address: 1157 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.7

D2_LandingDim2: 7.8

D3_RampWidth: 4.7

S1_LandingSlope1: 3.3

S2_LandingSlope2: 2.4

S3_RampSlope: 5.2

S4_RampCrossSlope: 2.5

S5_WingSlope1: 5.4


S6_WingSlope2: 1.4

S7_CounterSlope: 1.3

GutterSlope: 2.5

LipHeight:

CR_225





OBJECTID (Perpendicular Ramp): 136

Name: CR_225

Address: 1175 SE Douglas Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 4.9

S1_LandingSlope1: 0.1

S2_LandingSlope2: 0.8

S3_RampSlope: 4.2

S4_RampCrossSlope: 1.9

S5_WingSlope1: 1.5


S6_WingSlope2: 7.4

S7_CounterSlope: 3.4

GutterSlope: 2.1

LipHeight:

CR_226





OBJECTID (Perpendicular Ramp): 137

Name: CR_226

Address: 1238 SE Douglas Ave

TruncDomes: True

Comments: Power pole in wing

D1_LandingDim1: 4.7

D2_LandingDim2: 3.9

D3_RampWidth: 4.7

S1_LandingSlope1: 2.2

S2_LandingSlope2: 0.9

S3_RampSlope: 1.5

S4_RampCrossSlope: 0.8

S5_WingSlope1: 4.7

S6_WingSlope2: 2.4

S7_CounterSlope: 6.8

GutterSlope: 0.6

LipHeight:

CR_228





OBJECTID (Perpendicular Ramp): 139

Name: CR_228

Address: 2164 SE Douglas Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.3

S2_LandingSlope2: 3.6

S3_RampSlope: 10.5

S4_RampCrossSlope: 3.1

S5_WingSlope1: 10.3


S6_WingSlope2: 5.8

S7_CounterSlope: 6.3

GutterSlope: 0.8

LipHeight:

CR_757





OBJECTID (Parallel Ramp): 34

Name: CR_757

Address: 2403 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 2.2

S2_LandingSlope2: 0.5

S3_RampCrossSlope1: 1.8

S4_RampSlope1: 5.2

S5_RampCrossSlope2:

S6_RampSlope2:

S7_CounterSlope: 0.1

GutterSlope: 1.1

LipHeight:

CR_758





OBJECTID (Parallel Ramp): 35

Name: CR_758

Address: 2403 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.7

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 0.1

S3_RampCrossSlope1: 1.2

S4_RampSlope1: 1.3

S5_RampCrossSlope2: 1.9


S6_RampSlope2: 4.7

S7_CounterSlope: 2.3

GutterSlope: 0.7

LipHeight:

CR_760





OBJECTID (Parallel Ramp): 37

Name: CR_760

Address: 2995 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.2

S1_LandingSlope1: 0.7

S2_LandingSlope2: 1.4

S3_RampCrossSlope1: 0.3

S4_RampSlope1: 7.2

S5_RampCrossSlope2: 1.0

S6_RampSlope2: 8.3

S7_CounterSlope: 5.9

GutterSlope: 2.6

LipHeight:

CR_761





OBJECTID (Parallel Ramp): 38

Name: CR_761

Address: 2995 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 1.4

S2_LandingSlope2: 1.4

S3_RampCrossSlope1: 0.7

S4_RampSlope1: 1.0

S5_RampCrossSlope2: 1.8

S6_RampSlope2: 10.3

S7_CounterSlope: 0.8

GutterSlope: 1.3

LipHeight:

CR_863






OBJECTID (Unclassified Ramp): 38 **Address:** 2403 NW Edenbower Blvd

Name: CR_863

CR_762





OBJECTID (Parallel Ramp): 39

Name: CR_762

Address: 2995 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.7

D2_LandingDim2: 5.8

S1_LandingSlope1: 1.1

S2_LandingSlope2: 1.4

S3_RampCrossSlope1: 0.9

S4_RampSlope1: 0.3

S5_RampCrossSlope2: 0.2


S6_RampSlope2: 13.1

S7_CounterSlope: 2.6

GutterSlope: 1.3

LipHeight:

CR_770





OBJECTID (Parallel Ramp): 47

Name: CR_770

Address: 2579 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.9

S2_LandingSlope2: 1.0

S3_RampCrossSlope1: 2.8

S4_RampSlope1: 6.5

S5_RampCrossSlope2: 1.6


S6_RampSlope2: 6.0

S7_CounterSlope: 10.0

GutterSlope:

LipHeight:

CR_774





OBJECTID (Parallel Ramp): 51

Name: CR_774

Address: 2995 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.8

D2_LandingDim2: 5.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 2.8

S3_RampCrossSlope1: 1.2

S4_RampSlope1: 6.9

S5_RampCrossSlope2: 2.3

S6_RampSlope2: 10.5

S7_CounterSlope: 0.4

GutterSlope:

LipHeight:

CR_385





OBJECTID (Perpendicular Ramp): 297

Name: CR_385

Address: 2403 NW Edenbower Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 4.6

D3_RampWidth: 4.8

S1_LandingSlope1: 2.0

S2_LandingSlope2: 0.7

S3_RampSlope: 7.6

S4_RampCrossSlope: 1.2

S5_WingSlope1: 6.1

S6_WingSlope2: 6.6

S7_CounterSlope: 3.4

GutterSlope: 0.9

LipHeight:

CR_386





OBJECTID (Perpendicular Ramp): 298

Name: CR_386

Address: 2403 NW Edenbower Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 1.7

D3_RampWidth: 4.8

S1_LandingSlope1: 4.0

S2_LandingSlope2: 0.6

S3_RampSlope: 8.9

S4_RampCrossSlope: 0.5

S5_WingSlope1: 9.5


S6_WingSlope2: 6.8

S7_CounterSlope: 5.3

GutterSlope: 1.0

LipHeight:

CR_387





OBJECTID (Perpendicular Ramp): 299

Name: CR_387

Address: 2570 NW Edenbower Blvd

TruncDomes:

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 3.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 2.3

S3_RampSlope: 4.9

S4_RampCrossSlope: 2.6

S5_WingSlope1: 4.1

S6_WingSlope2: 8.8

S7_CounterSlope: 12.4

GutterSlope: 2.2

LipHeight:

CR_388





OBJECTID (Perpendicular Ramp): 300

Name: CR_388

Address: 2579 NW Edenbower Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 2.9

D3_RampWidth: 4.9

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.2

S3_RampSlope: 3.8

S4_RampCrossSlope: 1.0

S5_WingSlope1: 7.6


S6_WingSlope2: 7.4

S7_CounterSlope: 6.6

GutterSlope: 0.1

LipHeight:

CR_389





OBJECTID (Perpendicular Ramp): 301

Name: CR_389

Address: 2610 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 4.9

S1_LandingSlope1: 2.4

S2_LandingSlope2: 1.5

S3_RampSlope: 9.6

S4_RampCrossSlope: 0.5

S5_WingSlope1: 9.2

S6_WingSlope2: 10.0

S7_CounterSlope: 0.1

GutterSlope: 0.1

LipHeight:

CR_472





OBJECTID (Perpendicular Ramp): 384

Name: CR_472

Address: 2403 NW Edenbower Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.6

S4_RampCrossSlope: 3.0

S5_WingSlope1: 12.1

S6_WingSlope2: 6.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_473





OBJECTID (Perpendicular Ramp): 385

Name: CR_473

Address: 2403 NW Edenbower Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.1

S4_RampCrossSlope: 3.4

S5_WingSlope1: 6.0

S6_WingSlope2: 7.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_474





OBJECTID (Perpendicular Ramp): 386

Name: CR_474

Address: 2403 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 3.9

D3_RampWidth: 4.9

S1_LandingSlope1: 2.8

S2_LandingSlope2: 1.5

S3_RampSlope: 9.0

S4_RampCrossSlope: 2.0

S5_WingSlope1: 8.9

S6_WingSlope2: 11.0

S7_CounterSlope: -1.8

GutterSlope: 1.6

LipHeight:

CR_475





OBJECTID (Perpendicular Ramp): 387

Name: CR_475

Address: 2403 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 3.9

D3_RampWidth: 4.9

S1_LandingSlope1: 3.3

S2_LandingSlope2: 2.7

S3_RampSlope: 8.5

S4_RampCrossSlope: 1.5

S5_WingSlope1: 12.8

S6_WingSlope2: 8.1

S7_CounterSlope: -1.5

GutterSlope: 1.8

LipHeight:

CR_476





OBJECTID (Perpendicular Ramp): 388

Name: CR_476

Address: 2460 NW Edenbower Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 2.3

S5_WingSlope1: 15.2

S6_WingSlope2: 15.5

S7_CounterSlope:

GutterSlope:

LipHeight: 1.5

CR_477





OBJECTID (Perpendicular Ramp): 389

Name: CR_477

Address: 2460 NW Edenbower Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.1

S4_RampCrossSlope: 1.3

S5_WingSlope1: 13.6

S6_WingSlope2: 11.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_478





OBJECTID (Perpendicular Ramp): 390

Name: CR_478

Address: 2551 NW Edenbower Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.7

S4_RampCrossSlope: 0.5

S5_WingSlope1: 13.8

S6_WingSlope2: 19.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_479





OBJECTID (Perpendicular Ramp): 391

Name: CR_479

Address: 2551 NW Edenbower Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.2

S4_RampCrossSlope: 4.7

S5_WingSlope1: 16.3

S6_WingSlope2: 12.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_480





OBJECTID (Perpendicular Ramp): 392

Name: CR_480

Address: 2610 NW Edenbower Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.5

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 4.5

S3_RampSlope: 7.7

S4_RampCrossSlope: 4.1

S5_WingSlope1: 13.4


S6_WingSlope2: 6.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_739





OBJECTID (Parallel Ramp): 16

Name: CR_739

Address: 384 SE Ella St

TruncDomes: True

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.4

S3_RampCrossSlope1: 0.9

S4_RampSlope1: 3.3

S5_RampCrossSlope2: 0.8

S6_RampSlope2: 2.4

S7_CounterSlope: 5.7

GutterSlope: 0.6

LipHeight:

CR_866






OBJECTID (Unclassified Ramp): 41 **Address:** 109 Flangas Ave

Name: CR_866

CR_273





OBJECTID (Perpendicular Ramp): 184

Name: CR_273

Address: 865 SE Flint St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.4

S1_LandingSlope1: 0.2

S2_LandingSlope2: 0.4

S3_RampSlope: 12.2

S4_RampCrossSlope: 2.4

S5_WingSlope1: 9.5

S6_WingSlope2: 16.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_274





OBJECTID (Perpendicular Ramp): 185

Name: CR_274

Address: 864 SE Flint St

TruncDomes:

Comments: On flint

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 1.8

S3_RampSlope: 6.5

S4_RampCrossSlope: 0.5

S5_WingSlope1: 12.6

S6_WingSlope2: 8.4

S7_CounterSlope: 6.6

GutterSlope: 1.1

LipHeight:

CR_275





OBJECTID (Perpendicular Ramp): 186

Name: CR_275

Address: 864 SE Flint St

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 6.0

D3_RampWidth: 4.9

S1_LandingSlope1: 1.7

S2_LandingSlope2: 0.8

S3_RampSlope: 4.2

S4_RampCrossSlope: 0.7

S5_WingSlope1:

S6_WingSlope2: 16.0

S7_CounterSlope: 12.0

GutterSlope: 0.6

LipHeight:

CR_261





OBJECTID (Perpendicular Ramp): 172

Name: CR_261

Address: 641 SE Floed Ave

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.1

S4_RampCrossSlope: 3.4

S5_WingSlope1: 12.3

S6_WingSlope2: 8.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_262





OBJECTID (Perpendicular Ramp): 173

Name: CR_262

Address: 622 SE Floed Ave

TruncDomes: True

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1: 3.4

S2_LandingSlope2: 1.7

S3_RampSlope: 6.8

S4_RampCrossSlope: 1.8

S5_WingSlope1: 6.4


S6_WingSlope2: 10.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_709





OBJECTID (Perpendicular Ramp): 621

Name: CR_709

Address: 2113 W Foothill Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.6

S4_RampCrossSlope: 2.7

S5_WingSlope1: 18.7

S6_WingSlope2: 13.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_710





OBJECTID (Perpendicular Ramp): 622

Name: CR_710

Address: 2113 W Foothill Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 2.9

S5_WingSlope1: 20.7

S6_WingSlope2: 14.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_711





OBJECTID (Perpendicular Ramp): 623

Name: CR_711

Address: 700 W Francis St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 3.3

S5_WingSlope1: 8.8

S6_WingSlope2: 15.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_712





OBJECTID (Perpendicular Ramp): 624

Name: CR_712

Address: 700 W Francis St

TruncDomes: True

Comments:

D1_LandingDim1: 7.0

D2_LandingDim2: 4.0

D3_RampWidth: 7.0

S1_LandingSlope1: 3.6

S2_LandingSlope2: 3.9

S3_RampSlope: 13.6

S4_RampCrossSlope: 4.4

S5_WingSlope1: 8.2

S6_WingSlope2: 10.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_75





OBJECTID (Combination Ramp): 28

Name: CR_75

Address: 1191 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 3.4

D2_LandingDim2: 3.5

D3_RampWidth2: 5.5

D4_RampWidth3: 5.5

D5_RampWidth1: 3.9

S1_LandingSlope1: 0.8

S2_LandingSlope2: 8.3

S3_RampCrossSlope2: 1.7

S4_RampSlope2: 7.0

S5_RampCrossSlope3: 2.1

S6_RampSlope3: 13.3

S7_RampSlope1: 10.1

S8_RampCrossSlope1: 8.0

S9_WingSlope1: 3.8


S10_WingSlope2: 13.6

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_78





OBJECTID (Combination Ramp): 31

Name: CR_78

Address: 970 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 4.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 2.0

S3_RampCrossSlope2: 1.8

S4_RampSlope2: 1.0

S5_RampCrossSlope3: 2.3

S6_RampSlope3: 1.9

S7_RampSlope1: 6.5

S8_RampCrossSlope1: 1.8

S9_WingSlope1: 4.9

S10_WingSlope2: 8.5

S11_CounterSlope: 0.5

GutterSlope: 1.8

LipHeight:

CR_79





OBJECTID (Combination Ramp): 32

Name: CR_79

Address: 970 NW Garden Valley Blvd

TruncDomes: True

Comments: On garden valley

D1_LandingDim1: 6.0

D2_LandingDim2: 4.6

D3_RampWidth2: 6.7

D4_RampWidth3: 7.0

D5_RampWidth1: 6.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.2

S3_RampCrossSlope2: 1.4

S4_RampSlope2: 0.3

S5_RampCrossSlope3: 2.3

S6_RampSlope3: 0.1

S7_RampSlope1: 6.6

S8_RampCrossSlope1: 0.7

S9_WingSlope1: 5.5


S10_WingSlope2: 3.1

S11_CounterSlope: 4.7

GutterSlope: 0.2

LipHeight:

CR_80





OBJECTID (Combination Ramp): 33

Name: CR_80

Address: 970 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 7.6

D2_LandingDim2: 4.0

D3_RampWidth2: 6.5

D4_RampWidth3: 5.8

D5_RampWidth1: 8.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.9

S3_RampCrossSlope2: 1.8

S4_RampSlope2: 7.3

S5_RampCrossSlope3: 0.6

S6_RampSlope3: 7.7

S7_RampSlope1: 1.3

S8_RampCrossSlope1: 0.3

S9_WingSlope1: 5.8

S10_WingSlope2: 8.1

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_81





OBJECTID (Combination Ramp): 34

Name: CR_81

Address: 817 NE Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 5.1

S1_LandingSlope1: 2.5

S2_LandingSlope2: 0.6

S3_RampCrossSlope2: 1.9

S4_RampSlope2: 3.0

S5_RampCrossSlope3: 1.4

S6_RampSlope3: 5.2

S7_RampSlope1: 4.7

S8_RampCrossSlope1: 0.9

S9_WingSlope1: 5.9


S10_WingSlope2: 6.6

S11_CounterSlope: 3.2

GutterSlope: 0.8

LipHeight:

CR_37





OBJECTID (Bus Stop-Median): 37

Name: CR_37

Address: 940 NW Garden Valley Blvd

Comments:


D1_LandingDim1: 6.0

D2_LandingDim2: 10.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 1.3

CR_41





OBJECTID (Bus Stop-Median): 41

Name: CR_41

Address: 777 NW Garden Valley Blvd

Comments:


D1_LandingDim1: 5.0

D2_LandingDim2: 8.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 3.1

CR_783





OBJECTID (Parallel Ramp): 60

Name: CR_783

Address: 368 NE Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 5.5

S1_LandingSlope1: 1.8

S2_LandingSlope2: 4.1

S3_RampCrossSlope1: 0.1

S4_RampSlope1: 15.2

S5_RampCrossSlope2: 3.4


S6_RampSlope2: 2.2

S7_CounterSlope: 3.7

GutterSlope: 5.9

LipHeight:

CR_788





OBJECTID (Parallel Ramp): 65

Name: CR_788

Address: 250 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 5.1

S1_LandingSlope1: 2.8

S2_LandingSlope2: 1.6

S3_RampCrossSlope1: 4.4

S4_RampSlope1: 8.1

S5_RampCrossSlope2: 0.9


S6_RampSlope2: 7.1

S7_CounterSlope: 12.8

GutterSlope:

LipHeight:

CR_789





OBJECTID (Parallel Ramp): 66

Name: CR_789

Address: 180 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.4

S1_LandingSlope1: 3.6

S2_LandingSlope2: 1.4

S3_RampCrossSlope1: 3.6

S4_RampSlope1: 0.6

S5_RampCrossSlope2: 5.0

S6_RampSlope2: 6.5

S7_CounterSlope: 8.4

GutterSlope: 3.2

LipHeight:

CR_790





OBJECTID (Parallel Ramp): 67

Name: CR_790

Address: 350 NE Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 6.9

S1_LandingSlope1: 1.1

S2_LandingSlope2: 2.3

S3_RampCrossSlope1: 4.7

S4_RampSlope1: 0.4

S5_RampCrossSlope2:

S6_RampSlope2:

S7_CounterSlope: 1.3

GutterSlope: 2.5

LipHeight:

CR_791





OBJECTID (Parallel Ramp): 68

Name: CR_791

Address: 368 NE Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 5.3

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.6

S3_RampCrossSlope1:

S4_RampSlope1:

S5_RampCrossSlope2: 0.4

S6_RampSlope2: 8.4

S7_CounterSlope: 3.7

GutterSlope: 1.6

LipHeight:

CR_792





OBJECTID (Parallel Ramp): 69

Name: CR_792

Address: 368 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.1

S2_LandingSlope2: 2.8

S3_RampCrossSlope1: 1.2

S4_RampSlope1: 5.7

S5_RampCrossSlope2: 1.7


S6_RampSlope2: 9.6

S7_CounterSlope: 9.0

GutterSlope: 1.2

LipHeight:

CR_895





OBJECTID (Unclassified Ramp): 70 **Address:** 1820 NW Garden Valley Blvd

Name: CR_895

CR_896





OBJECTID (Unclassified Ramp): 71 **Address:** 428 NW Garden Valley Blvd

Name: CR_896

CR_897





OBJECTID (Unclassified Ramp): 72 **Address:** 327 NW Garden Valley Blvd

Name: CR_897

CR_898






OBJECTID (Unclassified Ramp): 73 **Address:** 227 NW Garden Valley Blvd

Name: CR_898

CR_899






OBJECTID (Unclassified Ramp): 74 **Address:** 238 NW Garden Valley Blvd

Name: CR_899

CR_900






OBJECTID (Unclassified Ramp): 75 **Address:** 247 NW Garden Valley Blvd

Name: CR_900

CR_901





OBJECTID (Unclassified Ramp): 76 **Address:** 248 NW Garden Valley Blvd

Name: CR_901

CR_902






OBJECTID (Unclassified Ramp): 77 **Address:** 287 NW Garden Valley Blvd

Name: CR_902

CR_903





OBJECTID (Unclassified Ramp): 78 **Address:** 347 NW Garden Valley Blvd

Name: CR_903

CR_906






OBJECTID (Unclassified Ramp): 81 **Address:** 326 NW Garden Valley Blvd

Name: CR_906

CR_907





OBJECTID (Unclassified Ramp): 82 **Address:** 278 NW Garden Valley Blvd

Name: CR_907

CR_908






OBJECTID (Unclassified Ramp): 83 **Address:** 227 NW Garden Valley Blvd

Name: CR_908

CR_909





OBJECTID (Unclassified Ramp): 84 **Address:** 316 NW Garden Valley Blvd

Name: CR_909

CR_910






OBJECTID (Unclassified Ramp): 85 **Address:** 817 NE Garden Valley Blvd

Name: CR_910

CR_809





OBJECTID (Parallel Ramp): 86

Name: CR_809

Address: 764 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 10.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 1.6

S3_RampCrossSlope1: 0.3

S4_RampSlope1: 7.3

S5_RampCrossSlope2: 1.5


S6_RampSlope2: 0.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_316





OBJECTID (Perpendicular Ramp): 227

Name: CR_316

Address: 1440 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 3.8

D3_RampWidth: 5.2

S1_LandingSlope1: 1.9

S2_LandingSlope2: 1.2

S3_RampSlope: 8.2

S4_RampCrossSlope: 0.3

S5_WingSlope1: 11.5

S6_WingSlope2: 8.3

S7_CounterSlope: 2.3

GutterSlope: 1.0

LipHeight:

CR_360





OBJECTID (Perpendicular Ramp): 272

Name: CR_360

Address: 1701 NW Garden Valley Blvd

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.7

S4_RampCrossSlope: 0.2

S5_WingSlope1: 12.2


S6_WingSlope2: 11.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_361





OBJECTID (Perpendicular Ramp): 273

Name: CR_361

Address: 1701 NW Garden Valley Blvd

TruncDomes:

Comments: Non compliant ramp no landing manhole in ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.0

S4_RampCrossSlope: 7.1

S5_WingSlope1: 11.6


S6_WingSlope2: 25.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_403





OBJECTID (Perpendicular Ramp): 315

Name: CR_403

Address: 1440 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 4.2

D3_RampWidth: 5.1

S1_LandingSlope1: 3.3

S2_LandingSlope2: 2.7

S3_RampSlope: 8.9

S4_RampCrossSlope: 4.0

S5_WingSlope1: 14.0

S6_WingSlope2: 7.9

S7_CounterSlope: 7.8

GutterSlope:

LipHeight: 1.0

CR_505





OBJECTID (Perpendicular Ramp): 417

Name: CR_505

Address: 692 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.6

D2_LandingDim2: 2.9

D3_RampWidth: 4.6

S1_LandingSlope1: 1.0

S2_LandingSlope2: 6.0

S3_RampSlope: 8.4

S4_RampCrossSlope: 5.5

S5_WingSlope1: 3.5

S6_WingSlope2: 14.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_531





OBJECTID (Perpendicular Ramp): 443

Name: CR_531

Address: 350 NE Garden Valley Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 5.3

S4_RampCrossSlope: 1.3

S5_WingSlope1: 8.3

S6_WingSlope2: 7.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_540





OBJECTID (Perpendicular Ramp): 452

Name: CR_540

Address: 1050 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 3.0

D3_RampWidth: 4.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 0.6

S3_RampSlope: 3.6

S4_RampCrossSlope: 0.5

S5_WingSlope1: 3.9

S6_WingSlope2: 7.1

S7_CounterSlope: 6.6

GutterSlope: 1.4

LipHeight:

CR_548





OBJECTID (Perpendicular Ramp): 460

Name: CR_548

Address: 711 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.7

D2_LandingDim2: 2.9

D3_RampWidth: 4.9

S1_LandingSlope1: 1.3

S2_LandingSlope2: 0.2

S3_RampSlope: 9.8

S4_RampCrossSlope: 0.7

S5_WingSlope1: 10.7


S6_WingSlope2: 8.3

S7_CounterSlope: 14.9

GutterSlope:

LipHeight:

CR_568





OBJECTID (Perpendicular Ramp): 480

Name: CR_568

Address: 250 NE Garden Valley Blvd

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 4.6

S5_WingSlope1: 24.1

S6_WingSlope2: 12.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_569





OBJECTID (Perpendicular Ramp): 481

Name: CR_569

Address: 250 NE Garden Valley Blvd

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.3

S4_RampCrossSlope: 0.7

S5_WingSlope1: 24.3

S6_WingSlope2: 14.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_574





OBJECTID (Perpendicular Ramp): 486

Name: CR_574

Address: 1820 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 3.8

D3_RampWidth: 3.8

S1_LandingSlope1: 2.3

S2_LandingSlope2: 0.6

S3_RampSlope: 12.9

S4_RampCrossSlope: 0.1

S5_WingSlope1: 10.1


S6_WingSlope2: 12.4

S7_CounterSlope: 0.2

GutterSlope: 1.7

LipHeight:

CR_575





OBJECTID (Perpendicular Ramp): 487

Name: CR_575

Address: 1740 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 3.1

D3_RampWidth: 5.0

S1_LandingSlope1: 2.3

S2_LandingSlope2: 5.8

S3_RampSlope: 12.0

S4_RampCrossSlope: 5.1

S5_WingSlope1: 13.3


S6_WingSlope2: 6.0

S7_CounterSlope: 10.3

GutterSlope: 4.4

LipHeight:

CR_576





OBJECTID (Perpendicular Ramp): 488

Name: CR_576

Address: 1820 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.5

S2_LandingSlope2: 0.2

S3_RampSlope: 9.5

S4_RampCrossSlope: 0.8

S5_WingSlope1: 10.4


S6_WingSlope2: 6.9

S7_CounterSlope: 8.2

GutterSlope: 1.4

LipHeight:

CR_577





OBJECTID (Perpendicular Ramp): 489

Name: CR_577

Address: 1820 NW Garden Valley Blvd

TruncDomes: True

Comments: Manhole in landing

D1_LandingDim1: 4.0

D2_LandingDim2: 4.1

D3_RampWidth: 4.0

S1_LandingSlope1: 3.4

S2_LandingSlope2: 1.5

S3_RampSlope: 8.9

S4_RampCrossSlope: 2.0

S5_WingSlope1: 13.2


S6_WingSlope2: 5.0

S7_CounterSlope: 8.5

GutterSlope: 0.9

LipHeight: 0.8

CR_578





OBJECTID (Perpendicular Ramp): 490

Name: CR_578

Address: 1740 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 3.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.6

S2_LandingSlope2: 3.1

S3_RampSlope: 13.4

S4_RampCrossSlope: 2.4

S5_WingSlope1: 6.0

S6_WingSlope2: 9.7

S7_CounterSlope: 6.1

GutterSlope: 2.7

LipHeight:

CR_579





OBJECTID (Perpendicular Ramp): 491

Name: CR_579

Address: 1632 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.8

D3_RampWidth: 5.0

S1_LandingSlope1: 3.3

S2_LandingSlope2: 0.2

S3_RampSlope: 12.4

S4_RampCrossSlope: 0.1

S5_WingSlope1: 12.2

S6_WingSlope2: 10.4

S7_CounterSlope: -2.3

GutterSlope: 0.5

LipHeight:

CR_580





OBJECTID (Perpendicular Ramp): 492

Name: CR_580

Address: 1600 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.3

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2: 0.7

S3_RampSlope: 11.7

S4_RampCrossSlope: 1.1

S5_WingSlope1: 10.5


S6_WingSlope2: 11.8

S7_CounterSlope: 6.5

GutterSlope: 1.1

LipHeight:

CR_581





OBJECTID (Perpendicular Ramp): 493

Name: CR_581

Address: 1495 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.1

D3_RampWidth: 5.0

S1_LandingSlope1: 0.1

S2_LandingSlope2: 2.0

S3_RampSlope: 7.6

S4_RampCrossSlope: 2.8

S5_WingSlope1: 10.7


S6_WingSlope2: 8.1

S7_CounterSlope: -2.2

GutterSlope: 2.5

LipHeight:

CR_582





OBJECTID (Perpendicular Ramp): 494

Name: CR_582

Address: 1430 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 1.1

S3_RampSlope: 11.2

S4_RampCrossSlope: 1.2

S5_WingSlope1: 9.8

S6_WingSlope2: 14.1

S7_CounterSlope: -2.9

GutterSlope: 1.2

LipHeight:

CR_583





OBJECTID (Perpendicular Ramp): 495

Name: CR_583

Address: 1122 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.6

D2_LandingDim2: 3.9

D3_RampWidth: 4.6

S1_LandingSlope1: 2.5

S2_LandingSlope2: 2.6

S3_RampSlope: 8.1

S4_RampCrossSlope: 1.2

S5_WingSlope1: 10.3

S6_WingSlope2: 8.4

S7_CounterSlope: -2.6

GutterSlope: 2.2

LipHeight: 0.3

CR_584





OBJECTID (Perpendicular Ramp): 496

Name: CR_584

Address: 1100 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 4.9

S1_LandingSlope1: 0.7

S2_LandingSlope2: 0.5

S3_RampSlope: 8.4

S4_RampCrossSlope: 0.5

S5_WingSlope1: 9.3


S6_WingSlope2: 11.6

S7_CounterSlope: 2.1

GutterSlope: 0.1

LipHeight: 0.3

CR_585





OBJECTID (Perpendicular Ramp): 497

Name: CR_585

Address: 930 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.9

D3_RampWidth: 4.0

S1_LandingSlope1: 4.0

S2_LandingSlope2: 2.8

S3_RampSlope: 7.8

S4_RampCrossSlope: 3.1

S5_WingSlope1: 4.8

S6_WingSlope2: 10.3

S7_CounterSlope: 4.8

GutterSlope: 1.9

LipHeight:

CR_586





OBJECTID (Perpendicular Ramp): 498

Name: CR_586

Address: 850 NW Garden Valley Blvd

TruncDomes:

Comments: On Estelle

D1_LandingDim1: 4.4

D2_LandingDim2: 4.0

D3_RampWidth: 4.4

S1_LandingSlope1: 8.1

S2_LandingSlope2: 9.1

S3_RampSlope: 13.6

S4_RampCrossSlope: 4.1

S5_WingSlope1: 12.5

S6_WingSlope2: 18.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_587





OBJECTID (Perpendicular Ramp): 499

Name: CR_587

Address: 850 NW Garden Valley Blvd

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 5.7

D2_LandingDim2: 4.2

D3_RampWidth: 4.6

S1_LandingSlope1: 0.1

S2_LandingSlope2: 7.3

S3_RampSlope: 10.5

S4_RampCrossSlope: 9.2

S5_WingSlope1: 4.2

S6_WingSlope2: 16.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_588





OBJECTID (Perpendicular Ramp): 500

Name: CR_588

Address: 801 NW Garden Valley Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.6

S4_RampCrossSlope: 1.5

S5_WingSlope1: 19.6


S6_WingSlope2: 17.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_589





OBJECTID (Perpendicular Ramp): 501

Name: CR_589

Address: 777 NW Garden Valley Blvd

TruncDomes:

Comments: On driveway

D1_LandingDim1: 3.7

D2_LandingDim2: 1.7

D3_RampWidth: 5.5

S1_LandingSlope1: 8.6

S2_LandingSlope2: 2.9

S3_RampSlope: 10.2

S4_RampCrossSlope: 1.2

S5_WingSlope1: 11.6


S6_WingSlope2: 12.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_590





OBJECTID (Perpendicular Ramp): 502

Name: CR_590

Address: 777 NW Garden Valley Blvd

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 3.0

D2_LandingDim2: 3.6

D3_RampWidth: 3.8

S1_LandingSlope1: 1.6

S2_LandingSlope2: 0.4

S3_RampSlope: 7.4

S4_RampCrossSlope: 2.9

S5_WingSlope1: 3.1


S6_WingSlope2: 9.1

S7_CounterSlope:

GutterSlope:

LipHeight: 0.3

CR_591





OBJECTID (Perpendicular Ramp): 503

Name: CR_591

Address: 760 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.2

D3_RampWidth: 5.0

S1_LandingSlope1: 0.5

S2_LandingSlope2: 2.5

S3_RampSlope: 6.1

S4_RampCrossSlope: 0.7

S5_WingSlope1: 1.2


S6_WingSlope2: 4.7

S7_CounterSlope: -5.0

GutterSlope: 0.2

LipHeight:

CR_592





OBJECTID (Perpendicular Ramp): 504

Name: CR_592

Address: 780 NW Garden Valley Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.6

S4_RampCrossSlope: 6.9

S5_WingSlope1: 3.6


S6_WingSlope2: 16.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_593





OBJECTID (Perpendicular Ramp): 505

Name: CR_593

Address: 777 NW Garden Valley Blvd

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 2.0

D2_LandingDim2: 3.7

D3_RampWidth: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 2.9

S3_RampSlope: 5.7

S4_RampCrossSlope: 2.7

S5_WingSlope1: 6.6


S6_WingSlope2: 2.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_594





OBJECTID (Perpendicular Ramp): 506

Name: CR_594

Address: 777 NW Garden Valley Blvd

TruncDomes:

Comments: On driveway

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 6.0

S1_LandingSlope1: 2.5

S2_LandingSlope2: 5.9

S3_RampSlope: 9.2

S4_RampCrossSlope: 3.2

S5_WingSlope1: 10.2

S6_WingSlope2: 4.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_595





OBJECTID (Perpendicular Ramp): 507

Name: CR_595

Address: 842 NW Garden Valley Blvd

TruncDomes:

Comments: No wings. In line landing

D1_LandingDim1: 6.0

D2_LandingDim2: 4.0

D3_RampWidth: 6.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 2.9

S3_RampSlope: 13.1

S4_RampCrossSlope: 3.4

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_596





OBJECTID (Perpendicular Ramp): 508

Name: CR_596

Address: 842 NW Garden Valley Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 1.6

S5_WingSlope1: 15.1


S6_WingSlope2: 4.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_597





OBJECTID (Perpendicular Ramp): 509

Name: CR_597

Address: 850 NW Garden Valley Blvd

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 5.0

D2_LandingDim2: 4.2

D3_RampWidth: 5.0

S1_LandingSlope1: 4.6

S2_LandingSlope2: 0.1

S3_RampSlope: 9.3

S4_RampCrossSlope: 0.3

S5_WingSlope1: 11.8


S6_WingSlope2: 10.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_598





OBJECTID (Perpendicular Ramp): 510

Name: CR_598

Address: 850 NW Garden Valley Blvd

TruncDomes:

Comments: On estelle

D1_LandingDim1: 5.3

D2_LandingDim2: 4.7

D3_RampWidth: 5.3

S1_LandingSlope1: 2.0

S2_LandingSlope2: 3.2

S3_RampSlope: 10.5

S4_RampCrossSlope: 4.3

S5_WingSlope1: 8.0


S6_WingSlope2: 12.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_599





OBJECTID (Perpendicular Ramp): 511

Name: CR_599

Address: 910 NW Garden Valley Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.6

S4_RampCrossSlope: 2.5

S5_WingSlope1: 25.8

S6_WingSlope2: 21.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_600





OBJECTID (Perpendicular Ramp): 512

Name: CR_600

Address: 250 NE Garden Valley Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.8

S4_RampCrossSlope: 2.4

S5_WingSlope1: 15.6

S6_WingSlope2: 27.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_601





OBJECTID (Perpendicular Ramp): 513

Name: CR_601

Address: 251 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 3.3

D2_LandingDim2: 2.3

D3_RampWidth: 3.3

S1_LandingSlope1: 1.8

S2_LandingSlope2: 3.1

S3_RampSlope: 14.9

S4_RampCrossSlope: 1.6

S5_WingSlope1: 43.7

S6_WingSlope2: 25.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_602





OBJECTID (Perpendicular Ramp): 514

Name: CR_602

Address: 251 NE Garden Valley Blvd

TruncDomes:

Comments: Traffic signal box in ramp. No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 5.8

S5_WingSlope1: 9.3

S6_WingSlope2: 18.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_603





OBJECTID (Perpendicular Ramp): 515

Name: CR_603

Address: 371 NE Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 2.8

D3_RampWidth: 4.2

S1_LandingSlope1: 1.0

S2_LandingSlope2: 5.4

S3_RampSlope: 12.5

S4_RampCrossSlope: 5.0

S5_WingSlope1: 9.7

S6_WingSlope2: 16.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_606





OBJECTID (Perpendicular Ramp): 518

Name: CR_606

Address: 333 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 3.0

D2_LandingDim2: 4.0

D3_RampWidth: 3.0

S1_LandingSlope1: 5.1

S2_LandingSlope2: 0.6

S3_RampSlope: 12.7

S4_RampCrossSlope: 2.2

S5_WingSlope1: 12.8

S6_WingSlope2: 12.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_607





OBJECTID (Perpendicular Ramp): 519

Name: CR_607

Address: 330 NE Garden Valley Blvd

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 7.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.7

S4_RampCrossSlope: 10.3

S5_WingSlope1: 20.6

S6_WingSlope2: 3.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_608





OBJECTID (Perpendicular Ramp): 520

Name: CR_608

Address: 158 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 3.4

D3_RampWidth: 4.2

S1_LandingSlope1: 1.8

S2_LandingSlope2: 5.7

S3_RampSlope: 10.3

S4_RampCrossSlope: 5.0

S5_WingSlope1: 13.0

S6_WingSlope2: 10.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_609





OBJECTID (Perpendicular Ramp): 521

Name: CR_609

Address: 158 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 3.6

D3_RampWidth: 4.3

S1_LandingSlope1: 0.9

S2_LandingSlope2: 5.7

S3_RampSlope: 6.4

S4_RampCrossSlope: 3.5

S5_WingSlope1: 4.6

S6_WingSlope2: 12.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_610





OBJECTID (Perpendicular Ramp): 522

Name: CR_610

Address: 817 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 3.0

D3_RampWidth: 3.9

S1_LandingSlope1: 0.6

S2_LandingSlope2: 22.0

S3_RampSlope: 0.7

S4_RampCrossSlope: 20.1

S5_WingSlope1: 10.0

S6_WingSlope2: 22.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_613





OBJECTID (Perpendicular Ramp): 525

Name: CR_613

Address: 1632 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 4.3

S3_RampSlope: 9.3

S4_RampCrossSlope: 3.9

S5_WingSlope1: 14.0

S6_WingSlope2: 7.2

S7_CounterSlope: 5.7

GutterSlope: 4.2

LipHeight:

CR_614





OBJECTID (Perpendicular Ramp): 526

Name: CR_614

Address: 1600 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 3.9

S1_LandingSlope1: 3.2

S2_LandingSlope2: 4.1

S3_RampSlope: 9.4

S4_RampCrossSlope: 1.9

S5_WingSlope1: 4.7

S6_WingSlope2: 11.4

S7_CounterSlope: 1.6

GutterSlope: 1.7

LipHeight:

CR_615





OBJECTID (Perpendicular Ramp): 527

Name: CR_615

Address: 1495 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.3

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 2.3

S3_RampSlope: 6.5

S4_RampCrossSlope: 3.2

S5_WingSlope1: 6.2


S6_WingSlope2: 10.5

S7_CounterSlope: -2.4

GutterSlope:

LipHeight:

CR_616





OBJECTID (Perpendicular Ramp): 528

Name: CR_616

Address: 1475 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 2.8

S3_RampSlope: 9.4

S4_RampCrossSlope: 3.9

S5_WingSlope1: 14.0

S6_WingSlope2: 7.2

S7_CounterSlope: -3.7

GutterSlope: 3.2

LipHeight:

CR_617





OBJECTID (Perpendicular Ramp): 529

Name: CR_617

Address: 1122 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 5.1

S1_LandingSlope1: 2.3

S2_LandingSlope2: 2.2

S3_RampSlope: 8.3

S4_RampCrossSlope: 1.4

S5_WingSlope1: 8.6


S6_WingSlope2: 9.4

S7_CounterSlope: 2.0

GutterSlope: 1.1

LipHeight:

CR_618





OBJECTID (Perpendicular Ramp): 530

Name: CR_618

Address: 1122 NW Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 2.0

S3_RampSlope: 8.9

S4_RampCrossSlope: 1.5

S5_WingSlope1: 10.5

S6_WingSlope2: 6.3

S7_CounterSlope: 0.3

GutterSlope: 1.0

LipHeight:

CR_619





OBJECTID (Perpendicular Ramp): 531

Name: CR_619

Address: 970 NW Garden Valley Blvd

TruncDomes: True

Comments: On goetz

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 0.3

S3_RampSlope: 7.8

S4_RampCrossSlope: 1.4

S5_WingSlope1:

S6_WingSlope2: 3.5

S7_CounterSlope: 3.8

GutterSlope:

LipHeight:

CR_620





OBJECTID (Perpendicular Ramp): 532

Name: CR_620

Address: 930 NW Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 4.6

S4_RampCrossSlope: 1.7

S5_WingSlope1: 4.0

S6_WingSlope2: 7.6

S7_CounterSlope: 0.4

GutterSlope: 3.8

LipHeight:

CR_621





OBJECTID (Perpendicular Ramp): 533

Name: CR_621

Address: 864 NW Garden Valley Blvd

TruncDomes:

Comments: On garden valley, too much traffic for s7

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.4

S2_LandingSlope2: 0.4

S3_RampSlope: 11.3

S4_RampCrossSlope: 0.7

S5_WingSlope1: 11.5

S6_WingSlope2: 12.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_622





OBJECTID (Perpendicular Ramp): 534

Name: CR_622

Address: 864 NW Garden Valley Blvd

TruncDomes:

Comments: On estelle

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 4.0

S2_LandingSlope2: 0.3

S3_RampSlope: 10.0

S4_RampCrossSlope:

S5_WingSlope1: 10.3

S6_WingSlope2: 10.1

S7_CounterSlope: 9.8

GutterSlope: 1.4

LipHeight:

CR_623





OBJECTID (Perpendicular Ramp): 535

Name: CR_623

Address: 798 NW Garden Valley Blvd

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.1

S4_RampCrossSlope: 4.8

S5_WingSlope1: 12.0


S6_WingSlope2: 19.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_624





OBJECTID (Perpendicular Ramp): 536

Name: CR_624

Address: 792 NW Garden Valley Blvd

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 3.1

D2_LandingDim2: 3.6

D3_RampWidth: 6.0

S1_LandingSlope1: 0.3

S2_LandingSlope2: 2.4

S3_RampSlope: 2.4

S4_RampCrossSlope: 1.8

S5_WingSlope1: 0.8


S6_WingSlope2: 5.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_625





OBJECTID (Perpendicular Ramp): 537

Name: CR_625

Address: 792 NW Garden Valley Blvd

TruncDomes:

Comments: On driveway

D1_LandingDim1: 3.0

D2_LandingDim2: 3.8

D3_RampWidth: 4.9

S1_LandingSlope1: 0.3

S2_LandingSlope2: 0.9

S3_RampSlope: 2.4

S4_RampCrossSlope: 1.0

S5_WingSlope1: 4.7


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_626





OBJECTID (Perpendicular Ramp): 538

Name: CR_626

Address: 792 NW Garden Valley Blvd

TruncDomes:

Comments: On driveway

D1_LandingDim1: 3.7

D2_LandingDim2: 2.3

D3_RampWidth: 4.3

S1_LandingSlope1: 0.6

S2_LandingSlope2:

S3_RampSlope: 1.5

S4_RampCrossSlope: 0.8

S5_WingSlope1: 3.6

S6_WingSlope2: 0.7

S7_CounterSlope: -1.8

GutterSlope: 0.3

LipHeight:

CR_627





OBJECTID (Perpendicular Ramp): 539

Name: CR_627

Address: 792 NW Garden Valley Blvd

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 3.9

D2_LandingDim2: 4.5

D3_RampWidth: 4.5

S1_LandingSlope1: 0.5

S2_LandingSlope2: 1.3

S3_RampSlope: 5.9

S4_RampCrossSlope: 0.2

S5_WingSlope1: 7.2

S6_WingSlope2: 1.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_628





OBJECTID (Perpendicular Ramp): 540

Name: CR_628

Address: 913 NW Garden Valley Blvd

TruncDomes:

Comments: On estelle

D1_LandingDim1: 4.9

D2_LandingDim2: 3.9

D3_RampWidth: 4.9

S1_LandingSlope1: 2.5

S2_LandingSlope2: 2.4

S3_RampSlope: 8.4

S4_RampCrossSlope: 1.4

S5_WingSlope1: 11.6

S6_WingSlope2: 11.3

S7_CounterSlope: 8.1


GutterSlope: 1.8

LipHeight:

CR_629


Burger King
Kelly Auto Parts
NW Garden Valley Blvd
Roseburg Senior Activity Center
Roseburg Public Library
Douglas County Museum
Douglas County Courthouse
Douglas County Annex
Douglas County Courthouse Annex
Douglas County Sheriff's Office
Douglas County Jail
Douglas County Fairgrounds
Douglas County Fairgrounds Exhibit Hall
Douglas County Fairgrounds Arena
Douglas County Fairgrounds Grandstand
Douglas County Fairgrounds Horse Barn
Douglas County Fairgrounds Livestock Barn
Douglas County Fairgrounds Poultry Barn
Douglas County Fairgrounds Rabbit Barn
Douglas County Fairgrounds Sheep Barn
Douglas County Fairgrounds Swine Barn
Douglas County Fairgrounds Cattle Barn
Douglas County Fairgrounds Dairy Barn
Douglas County Fairgrounds Goat Barn

CR_630





OBJECTID (Perpendicular Ramp): 542

Name: CR_630

Address: 929 NW Garden Valley Blvd

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.0

S4_RampCrossSlope: 1.3

S5_WingSlope1: 18.4

S6_WingSlope2: 17.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_631





OBJECTID (Perpendicular Ramp): 543

Name: CR_631

Address: 251 NE Garden Valley Blvd

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 0.4

S5_WingSlope1: 30.7

S6_WingSlope2: 28.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_632





OBJECTID (Perpendicular Ramp): 544

Name: CR_632

Address: 251 NE Garden Valley Blvd

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 5.0

D3_RampWidth: 3.5

S1_LandingSlope1: 0.1

S2_LandingSlope2: 3.3

S3_RampSlope: 17.4

S4_RampCrossSlope: 3.8

S5_WingSlope1: 19.5

S6_WingSlope2: 21.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_633





OBJECTID (Perpendicular Ramp): 545

Name: CR_633

Address: 330 NE Garden Valley Blvd

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.5

S4_RampCrossSlope: 5.5

S5_WingSlope1: 8.6

S6_WingSlope2: 20.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_634





OBJECTID (Perpendicular Ramp): 546

Name: CR_634

Address: 470 NE Garden Valley Blvd

TruncDomes: True

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.2

S4_RampCrossSlope: 2.3

S5_WingSlope1: 26.6

S6_WingSlope2: 7.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_636





OBJECTID (Perpendicular Ramp): 548

Name: CR_636

Address: 672 NE Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.3

S1_LandingSlope1: 1.1

S2_LandingSlope2: 1.3

S3_RampSlope: 6.5

S4_RampCrossSlope: 2.3

S5_WingSlope1: 10.3


S6_WingSlope2: 4.7

S7_CounterSlope: 1.2

GutterSlope:

LipHeight:

CR_637





OBJECTID (Perpendicular Ramp): 549

Name: CR_637

Address: 672 NE Garden Valley Blvd

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.5

D3_RampWidth: 5.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.2

S3_RampSlope: 6.2

S4_RampCrossSlope: 1.4

S5_WingSlope1: 9.2

S6_WingSlope2: 6.7

S7_CounterSlope: 5.6

GutterSlope: 1.6

LipHeight:

CR_793





OBJECTID (Parallel Ramp): 70

Name: CR_793

Address: 1673 NW Goetz St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 0.5

S3_RampCrossSlope1: 1.1

S4_RampSlope1: 7.1

S5_RampCrossSlope2: 0.7

S6_RampSlope2: 7.4

S7_CounterSlope: 2.6

GutterSlope: 1.4

LipHeight:

CR_830






OBJECTID (Unclassified Ramp): 5 **Address:** 1794 SE Hamilton St

Name: CR_830

CR_843





OBJECTID (Unclassified Ramp): 18 **Address:** 1794 SE Hamilton St

Name: CR_843

CR_651





OBJECTID (Perpendicular Ramp): 563

Name: CR_651

Address: 575 W Harrison St

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.6

S4_RampCrossSlope: 1.9

S5_WingSlope1: 23.2


S6_WingSlope2: 18.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_43





OBJECTID (Bus Stop-Median): 43

Name: CR_43

Address: 1051 W Harvard Ave

Comments:

D1_LandingDim1: 7.0

D2_LandingDim2: 8.0


S1_LandingSlope1: 3.6

S2_LandingSlope2: 0.8

CR_44


W Harvard Ave
W Harvard Ave
W Harvard Ave
W Harvard Ave
S Jackson St
S Jackson St
S Jackson St

CR_767





OBJECTID (Parallel Ramp): 44

Name: CR_767

Address: 1970 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 7.6

S1_LandingSlope1: 1.2

S2_LandingSlope2: 0.3

S3_RampCrossSlope1: 0.9

S4_RampSlope1: 5.0

S5_RampCrossSlope2: 1.1


S6_RampSlope2: 7.5

S7_CounterSlope: 2.8

GutterSlope: 0.2

LipHeight:

CR_46





OBJECTID (Bus Stop-Median): 46

Name: CR_46

Address: 1445 W Harvard Ave

Comments:


D1_LandingDim1: 11.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 3.3

S2_LandingSlope2: 0.5

CR_47





OBJECTID (Bus Stop-Median): 47

Name: CR_47

Address: 1937 W Harvard Ave

Comments:


D1_LandingDim1: 11.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 4.3

S2_LandingSlope2: 0.9

CR_913





OBJECTID (Unclassified Ramp): 88 **Address:** 1457 W Harvard Ave

Name: CR_913

CR_914





OBJECTID (Unclassified Ramp): 89 **Address:** 1614 W Harvard Ave

Name: CR_914

CR_915





OBJECTID (Unclassified Ramp): 90 **Address:** 2929 W Harvard Ave

Name: CR_915

CR_822





OBJECTID (Parallel Ramp): 99

Name: CR_822

Address: 1144 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.6

S2_LandingSlope2: 3.1

S3_RampCrossSlope1: 1.5

S4_RampSlope1: 4.5

S5_RampCrossSlope2: 2.0


S6_RampSlope2: 9.4

S7_CounterSlope: 8.1

GutterSlope: 2.0

LipHeight:

CR_823





OBJECTID (Parallel Ramp): 100

Name: CR_823

Address: 1320 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 5.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 0.6

S3_RampCrossSlope1: 1.9

S4_RampSlope1: 3.2

S5_RampCrossSlope2: 0.4

S6_RampSlope2: 6.3

S7_CounterSlope: 8.5

GutterSlope:

LipHeight:

CR_825





OBJECTID (Parallel Ramp): 102

Name: CR_825

Address: 1270 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.0

S2_LandingSlope2:

S3_RampCrossSlope1: 1.9

S4_RampSlope1: 4.8

S5_RampCrossSlope2: 0.9

S6_RampSlope2: 3.8

S7_CounterSlope: 4.3

GutterSlope:

LipHeight:

CR_325





OBJECTID (Perpendicular Ramp): 237

Name: CR_325

Address: 1970 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing, power pole at bow

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.5

S4_RampCrossSlope: 3.0

S5_WingSlope1: 15.9


S6_WingSlope2: 14.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_326



OBJECTID (Perpendicular Ramp): 238

Name: CR_326

Address: 1970 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 5.0

D3_RampWidth: 6.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.4

S3_RampSlope: 5.8

S4_RampCrossSlope: 1.3

S5_WingSlope1: 9.3

S6_WingSlope2: 5.1

S7_CounterSlope: 1.0

GutterSlope: 2.3

LipHeight:

CR_412





OBJECTID (Perpendicular Ramp): 324

Name: CR_412

Address: 1970 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.4

S4_RampCrossSlope: 2.6

S5_WingSlope1: 10.3


S6_WingSlope2: 17.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_650





OBJECTID (Perpendicular Ramp): 562

Name: CR_650

Address: 988 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.6

S4_RampCrossSlope: 6.3

S5_WingSlope1: 22.4


S6_WingSlope2: 22.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_652





OBJECTID (Perpendicular Ramp): 564

Name: CR_652

Address: 985 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.4

S4_RampCrossSlope: 1.5

S5_WingSlope1: 17.9


S6_WingSlope2: 14.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_653





OBJECTID (Perpendicular Ramp): 565

Name: CR_653

Address: 988 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.5

S4_RampCrossSlope: 0.4

S5_WingSlope1: 13.2

S6_WingSlope2: 14.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_654





OBJECTID (Perpendicular Ramp): 566

Name: CR_654

Address: 1221 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.2

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 1.4

S3_RampSlope: 8.1

S4_RampCrossSlope: 2.3

S5_WingSlope1: 11.6

S6_WingSlope2: 5.5

S7_CounterSlope: 5.5

GutterSlope: 3.7

LipHeight:

CR_655





OBJECTID (Perpendicular Ramp): 567

Name: CR_655

Address: 1539 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 0.2

S5_WingSlope1: 16.5

S6_WingSlope2: 12.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_656





OBJECTID (Perpendicular Ramp): 568

Name: CR_656

Address: 1539 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.4

S4_RampCrossSlope: 1.2

S5_WingSlope1: 14.1

S6_WingSlope2: 23.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_657





OBJECTID (Perpendicular Ramp): 569

Name: CR_657

Address: 1360 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 4.0

S4_RampCrossSlope: 0.2

S5_WingSlope1: 12.5

S6_WingSlope2: 13.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_658





OBJECTID (Perpendicular Ramp): 570

Name: CR_658

Address: 1257 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.9

S4_RampCrossSlope: 0.9

S5_WingSlope1: 19.3


S6_WingSlope2: 14.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_659





OBJECTID (Perpendicular Ramp): 571

Name: CR_659

Address: 1813 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.7

S4_RampCrossSlope: 0.3

S5_WingSlope1: 19.6


S6_WingSlope2: 16.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_660





OBJECTID (Perpendicular Ramp): 572

Name: CR_660

Address: 1813 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.9

S4_RampCrossSlope: 1.7

S5_WingSlope1: 10.5

S6_WingSlope2: 18.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_661





OBJECTID (Perpendicular Ramp): 573

Name: CR_661

Address: 1960 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.7

S4_RampCrossSlope: 2.1

S5_WingSlope1: 6.8

S6_WingSlope2: 10.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_662





OBJECTID (Perpendicular Ramp): 574

Name: CR_662

Address: 1887 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 4.0

S1_LandingSlope1: 5.2

S2_LandingSlope2: 0.1

S3_RampSlope: 12.4

S4_RampCrossSlope: 0.7

S5_WingSlope1: 7.6

S6_WingSlope2: 10.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_664





OBJECTID (Perpendicular Ramp): 576

Name: CR_664

Address: 2171 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 2.0

S3_RampSlope: 9.6

S4_RampCrossSlope: 1.8

S5_WingSlope1: 6.3

S6_WingSlope2: 8.3

S7_CounterSlope: 5.0

GutterSlope: 0.3

LipHeight:

CR_665





OBJECTID (Perpendicular Ramp): 577

Name: CR_665

Address: 2233 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 5.0

D3_RampWidth: 4.5

S1_LandingSlope1: 0.7

S2_LandingSlope2: 3.3

S3_RampSlope: 8.4

S4_RampCrossSlope: 2.3

S5_WingSlope1: 9.4

S6_WingSlope2: 3.6

S7_CounterSlope: 14.6

GutterSlope: 4.5

LipHeight:

CR_666





OBJECTID (Perpendicular Ramp): 578

Name: CR_666

Address: 2314 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 16.3

S4_RampCrossSlope: 5.7

S5_WingSlope1: 10.5

S6_WingSlope2: 14.7

S7_CounterSlope: 10.2

GutterSlope: 10.9

LipHeight:

CR_667





OBJECTID (Perpendicular Ramp): 579

Name: CR_667

Address: 2345 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.0

S4_RampCrossSlope: 1.8

S5_WingSlope1: 9.8

S6_WingSlope2: 15.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_668





OBJECTID (Perpendicular Ramp): 580

Name: CR_668

Address: 2345 W Harvard Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.3

S4_RampCrossSlope: 0.6

S5_WingSlope1: 7.3


S6_WingSlope2: 12.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_669


W Harvard Ave
W Harvard Ave
W Harvard Ave

CR_670





OBJECTID (Perpendicular Ramp): 582

Name: CR_670

Address: 2421 W Harvard Ave

TruncDomes: True

Comments: S1-2: landing with domes (running, cross).....S3-4, second panel .....S5-6, 3rd existing panel

D1_LandingDim1: 7.0

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1: 2.3

S2_LandingSlope2: 0.1

S3_RampSlope: 9.1

S4_RampCrossSlope: 0.9

S5_WingSlope1: 1.3


S6_WingSlope2: 2.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_671





OBJECTID (Perpendicular Ramp): 583

Name: CR_671

Address: 2525 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.0

S4_RampCrossSlope: 0.2

S5_WingSlope1: 21.3

S6_WingSlope2: 23.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_672





OBJECTID (Perpendicular Ramp): 584

Name: CR_672

Address: 2618 W Harvard Ave

TruncDomes: True

Comments: S1-2: landing with domes (running, cross).....S3-4, second panel .....S5-6, 3rd existing panel

D1_LandingDim1: 7.0

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 0.4

S3_RampSlope: 8.2

S4_RampCrossSlope:

S5_WingSlope1: 1.6

S6_WingSlope2: 0.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_673





OBJECTID (Perpendicular Ramp): 585

Name: CR_673

Address: 2639 W Harvard Ave

TruncDomes: True

Comments: S1-2: landing with domes (running, cross).....S3-4, second panel .....S5-6, 3rd existing panel

D1_LandingDim1: 7.0

D2_LandingDim2:

D3_RampWidth: 6.8

S1_LandingSlope1: 4.0

S2_LandingSlope2: 2.1

S3_RampSlope: 7.9

S4_RampCrossSlope: 1.5

S5_WingSlope1: 1.8


S6_WingSlope2: 2.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_689





OBJECTID (Perpendicular Ramp): 601

Name: CR_689

Address: 810 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.6

D3_RampWidth: 5.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 1.2

S3_RampSlope: 8.2

S4_RampCrossSlope: 1.3

S5_WingSlope1: 7.5

S6_WingSlope2: 9.6

S7_CounterSlope: 2.3

GutterSlope: 2.3

LipHeight:

CR_690





OBJECTID (Perpendicular Ramp): 602

Name: CR_690

Address: 797 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 1.2

S3_RampSlope: 7.3

S4_RampCrossSlope: 0.8

S5_WingSlope1: 6.9

S6_WingSlope2: 7.9

S7_CounterSlope: -2.1

GutterSlope: 1.8

LipHeight:

CR_691





OBJECTID (Perpendicular Ramp): 603

Name: CR_691

Address: 882 W Harvard Ave

TruncDomes:

Comments: Utility pole in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.2

S4_RampCrossSlope: 9.9

S5_WingSlope1: 3.8


S6_WingSlope2: 23.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_692





OBJECTID (Perpendicular Ramp): 604

Name: CR_692

Address: 881 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.4

S4_RampCrossSlope: 1.6

S5_WingSlope1: 21.9

S6_WingSlope2: 18.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_693





OBJECTID (Perpendicular Ramp): 605

Name: CR_693

Address: 910 W Harvard Ave

TruncDomes:

Comments: No landing. Utility pole in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.1

S4_RampCrossSlope: 6.9

S5_WingSlope1: 18.7

S6_WingSlope2: 2.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_694





OBJECTID (Perpendicular Ramp): 606

Name: CR_694

Address: 910 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.1

S4_RampCrossSlope: 2.9

S5_WingSlope1: 8.7

S6_WingSlope2: 7.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_695





OBJECTID (Perpendicular Ramp): 607

Name: CR_695

Address: 1123 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.7

S4_RampCrossSlope: 0.1

S5_WingSlope1: 18.7

S6_WingSlope2: 19.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_696





OBJECTID (Perpendicular Ramp): 608

Name: CR_696

Address: 1135 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.1

S4_RampCrossSlope: 0.3

S5_WingSlope1: 25.4


S6_WingSlope2: 25.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_697





OBJECTID (Perpendicular Ramp): 609

Name: CR_697

Address: 1425 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 7.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.6

S4_RampCrossSlope: 2.5

S5_WingSlope1: 19.3


S6_WingSlope2: 15.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_698





OBJECTID (Perpendicular Ramp): 610

Name: CR_698

Address: 1425 W Harvard Ave

TruncDomes:

Comments: No landing. Utility pole in landing/ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.9

S4_RampCrossSlope: 0.9

S5_WingSlope1: 17.7


S6_WingSlope2: 21.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_699





OBJECTID (Perpendicular Ramp): 611

Name: CR_699

Address: 1425 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.6

S4_RampCrossSlope: 3.1

S5_WingSlope1: 19.7

S6_WingSlope2: 15.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_700





OBJECTID (Perpendicular Ramp): 612

Name: CR_700

Address: 1425 W Harvard Ave

TruncDomes:

Comments: No landing. Utility pole in landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.6

S4_RampCrossSlope: 0.6

S5_WingSlope1: 18.2

S6_WingSlope2: 16.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_701





OBJECTID (Perpendicular Ramp): 613

Name: CR_701

Address: 1425 W Harvard Ave

TruncDomes:

Comments: No landing. Utility pole in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.2

S4_RampCrossSlope: 0.8

S5_WingSlope1: 13.5

S6_WingSlope2: 17.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_703





OBJECTID (Perpendicular Ramp): 615

Name: CR_703

Address: 1313 W Harvard Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.7

D3_RampWidth: 5.0

S1_LandingSlope1: 2.1

S2_LandingSlope2: 1.1

S3_RampSlope: 7.1

S4_RampCrossSlope: 0.2

S5_WingSlope1: 10.0


S6_WingSlope2: 8.6

S7_CounterSlope: 4.7

GutterSlope: 1.3

LipHeight:

CR_704





OBJECTID (Perpendicular Ramp): 616

Name: CR_704

Address: 1813 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.4

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.0

S4_RampCrossSlope: 2.2

S5_WingSlope1: 13.1


S6_WingSlope2: 15.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_705





OBJECTID (Perpendicular Ramp): 617

Name: CR_705

Address: 1813 W Harvard Ave

TruncDomes:

Comments: No landing. On Harvard

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.2

S4_RampCrossSlope: 3.0

S5_WingSlope1: 15.0


S6_WingSlope2: 10.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_706





OBJECTID (Perpendicular Ramp): 618

Name: CR_706

Address: 1813 W Harvard Ave

TruncDomes:

Comments: No landing. Pole in landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.9

S4_RampCrossSlope: 1.2

S5_WingSlope1: 14.8

S6_WingSlope2: 11.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_707





OBJECTID (Perpendicular Ramp): 619

Name: CR_707

Address: 1887 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.9

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.8

S4_RampCrossSlope: 2.3

S5_WingSlope1: 12.2

S6_WingSlope2: 7.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_708





OBJECTID (Perpendicular Ramp): 620

Name: CR_708

Address: 1887 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 6.0

D3_RampWidth: 4.0

S1_LandingSlope1: 4.3

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 2.9

S5_WingSlope1: 9.4

S6_WingSlope2: 15.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_713





OBJECTID (Perpendicular Ramp): 625

Name: CR_713

Address: 2428 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 12.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.1

S4_RampCrossSlope: 1.8

S5_WingSlope1: 20.4

S6_WingSlope2: 20.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_714





OBJECTID (Perpendicular Ramp): 626

Name: CR_714

Address: 2365 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 12.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.7

S4_RampCrossSlope: 0.4

S5_WingSlope1: 20.1


S6_WingSlope2: 12.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_715





OBJECTID (Perpendicular Ramp): 627

Name: CR_715

Address: 2460 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.7

S4_RampCrossSlope: 7.5

S5_WingSlope1: 21.7

S6_WingSlope2: 16.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_716





OBJECTID (Perpendicular Ramp): 628

Name: CR_716

Address: 2514 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.9

S4_RampCrossSlope: 3.5

S5_WingSlope1: 20.1


S6_WingSlope2: 26.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_717





OBJECTID (Perpendicular Ramp): 629

Name: CR_717

Address: 2556 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 2.5

S5_WingSlope1: 22.0


S6_WingSlope2: 19.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_718





OBJECTID (Perpendicular Ramp): 630

Name: CR_718

Address: 2581 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.7

S4_RampCrossSlope: 0.9

S5_WingSlope1: 26.4


S6_WingSlope2: 18.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_719





OBJECTID (Perpendicular Ramp): 631

Name: CR_719

Address: 2618 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 2.3

D3_RampWidth: 3.8

S1_LandingSlope1: 5.2

S2_LandingSlope2:

S3_RampSlope: 6.5

S4_RampCrossSlope: 1.7

S5_WingSlope1: 5.8

S6_WingSlope2: 12.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_720





OBJECTID (Perpendicular Ramp): 632

Name: CR_720

Address: 2657 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.4

S4_RampCrossSlope: 0.9

S5_WingSlope1: 27.6

S6_WingSlope2: 20.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_721





OBJECTID (Perpendicular Ramp): 633

Name: CR_721

Address: 2713 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.8

S4_RampCrossSlope: 0.1

S5_WingSlope1: 13.7

S6_WingSlope2: 27.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_722





OBJECTID (Perpendicular Ramp): 634

Name: CR_722

Address: 2713 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.4

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.3

S4_RampCrossSlope: 4.1

S5_WingSlope1: 4.4

S6_WingSlope2: 9.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_723





OBJECTID (Perpendicular Ramp): 635

Name: CR_723

Address: 2657 W Harvard Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 3.7

S5_WingSlope1: 8.7

S6_WingSlope2: 2.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_724



OBJECTID (Perpendicular Ramp): 636

Name: CR_724

Address: 1771 W Harvard Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_327





OBJECTID (Perpendicular Ramp): 239

Name: CR_327

Address: 1532 NW Harvey Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.9

S4_RampCrossSlope: 0.9

S5_WingSlope1: 21.0


S6_WingSlope2: 22.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_328





OBJECTID (Perpendicular Ramp): 240

Name: CR_328

Address: 1532 NW Harvey Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.3

S4_RampCrossSlope: 2.2

S5_WingSlope1: 23.9


S6_WingSlope2: 20.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_329





OBJECTID (Perpendicular Ramp): 241

Name: CR_329

Address: 1552 NW Harvey Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.0

S4_RampCrossSlope: 1.7

S5_WingSlope1: 7.2


S6_WingSlope2: 7.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_330





OBJECTID (Perpendicular Ramp): 242

Name: CR_330

Address: 1521 NW Harvey Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.7

S4_RampCrossSlope: 0.8

S5_WingSlope1: 6.2


S6_WingSlope2: 7.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_415





OBJECTID (Perpendicular Ramp): 327

Name: CR_415

Address: 1561 NW Harvey Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.9

S4_RampCrossSlope: 5.8

S5_WingSlope1: 24.6


S6_WingSlope2: 17.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_416





OBJECTID (Perpendicular Ramp): 328

Name: CR_416

Address: 1581 NW Harvey Ave

TruncDomes:

Comments: No landing. Hydrant in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 0.4

S5_WingSlope1: 24.3

S6_WingSlope2: 26.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_728





OBJECTID (Parallel Ramp): 5

Name: CR_728

Address: 371 SE Henry St

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 6.9

S2_LandingSlope2: 7.1

S3_RampCrossSlope1:

S4_RampSlope1: 16.6

S5_RampCrossSlope2:

S6_RampSlope2: 4.5

S7_CounterSlope:

GutterSlope:

LipHeight: 0.1

CR_741





OBJECTID (Parallel Ramp): 18

Name: CR_741

Address: 371 SE Henry St

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

S1_LandingSlope1: 3.8

S2_LandingSlope2: 5.3

S3_RampCrossSlope1:

S4_RampSlope1: 6.1

S5_RampCrossSlope2:


S6_RampSlope2: 147.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_83





OBJECTID (Combination Ramp): 36

Name: CR_83

Address: 422 Hewitt Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.4

D2_LandingDim2: 4.0

D3_RampWidth2: 4.1

D4_RampWidth3: 4.0

D5_RampWidth1: 6.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 0.6

S3_RampCrossSlope2: 2.0

S4_RampSlope2: 7.1

S5_RampCrossSlope3: 1.5

S6_RampSlope3: 1.8

S7_RampSlope1: 3.9

S8_RampCrossSlope1: 0.4

S9_WingSlope1: 8.6

S10_WingSlope2: 0.7

S11_CounterSlope: -2.7

GutterSlope: 2.4

LipHeight:

CR_814





OBJECTID (Parallel Ramp): 91

Name: CR_814

Address: 413 Hewitt Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 0.5

S3_RampCrossSlope1: 1.6

S4_RampSlope1: 5.4

S5_RampCrossSlope2: 1.2

S6_RampSlope2: 7.6

S7_CounterSlope: 2.2

GutterSlope:

LipHeight:

CR_511





OBJECTID (Perpendicular Ramp): 423

Name: CR_511

Address: 821 NW Highland St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.9

S4_RampCrossSlope: 1.3

S5_WingSlope1: 15.2

S6_WingSlope2: 14.6

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_512





OBJECTID (Perpendicular Ramp): 424

Name: CR_512

Address: 821 NW Highland St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.5

S4_RampCrossSlope: 5.1

S5_WingSlope1: 19.6


S6_WingSlope2: 10.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_82





OBJECTID (Combination Ramp): 35

Name: CR_82

Address: 415 Housley Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.6

D2_LandingDim2: 4.0

D3_RampWidth2: 8.0

D4_RampWidth3: 8.4

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 0.3

S3_RampCrossSlope2: 0.2

S4_RampSlope2: 8.0

S5_RampCrossSlope3: 1.7

S6_RampSlope3: 5.8

S7_RampSlope1: 7.6

S8_RampCrossSlope1: 1.2

S9_WingSlope1: 7.1

S10_WingSlope2: 8.2

S11_CounterSlope: 8.4

GutterSlope: 2.9

LipHeight:

CR_904






OBJECTID (Unclassified Ramp): 79 **Address:** 415 Housley Ave

Name: CR_904

CR_611





OBJECTID (Perpendicular Ramp): 523

Name: CR_611

Address: 415 Housley Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.5

S2_LandingSlope2: 5.6

S3_RampSlope: 7.2

S4_RampCrossSlope: 5.9

S5_WingSlope1: 15.1


S6_WingSlope2: 7.9

S7_CounterSlope: 2.8

GutterSlope: 4.6

LipHeight:

CR_862






OBJECTID (Unclassified Ramp): 37 **Address:** 1767 NW Hughwood Ave

Name: CR_862

CR_369





OBJECTID (Perpendicular Ramp): 281

Name: CR_369

Address: 1767 NW Hughwood Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 6.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.7

S2_LandingSlope2: 3.4

S3_RampSlope: 12.9

S4_RampCrossSlope: 2.1

S5_WingSlope1: 10.4


S6_WingSlope2: 14.5

S7_CounterSlope: 1.8

GutterSlope: 2.0

LipHeight:

CR_446





OBJECTID (Perpendicular Ramp): 358

Name: CR_446

Address: 1730 NW Hughwood Ave

TruncDomes: True

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 3.2

D3_RampWidth: 3.8

S1_LandingSlope1: 0.7

S2_LandingSlope2: 5.8

S3_RampSlope: 10.1

S4_RampCrossSlope: 4.7

S5_WingSlope1: 7.1

S6_WingSlope2: 14.4

S7_CounterSlope: 12.2

GutterSlope: 6.2

LipHeight:

CR_447





OBJECTID (Perpendicular Ramp): 359

Name: CR_447

Address: 1671 NW Hughwood Ct

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.9

S2_LandingSlope2: 4.6

S3_RampSlope: 8.2

S4_RampCrossSlope: 4.7

S5_WingSlope1: 13.8


S6_WingSlope2: 5.0

S7_CounterSlope: 9.7

GutterSlope: 2.0

LipHeight:

CR_453





OBJECTID (Perpendicular Ramp): 365

Name: CR_453

Address: 1730 NW Hughwood Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.5

D3_RampWidth: 4.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 2.3

S3_RampSlope: 4.8

S4_RampCrossSlope: 2.2

S5_WingSlope1: 17.3

S6_WingSlope2: 6.6

S7_CounterSlope: 2.9

GutterSlope: 3.7

LipHeight:

CR_454





OBJECTID (Perpendicular Ramp): 366

Name: CR_454

Address: 1750 NW Hughwood Ave

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 0.8

S3_RampSlope: 8.3

S4_RampCrossSlope: 0.9

S5_WingSlope1: 4.0


S6_WingSlope2: 8.5

S7_CounterSlope: 0.2

GutterSlope: 1.8

LipHeight:

CR_457





OBJECTID (Perpendicular Ramp): 369

Name: CR_457

Address: 1800 NW Hughwood Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 1.7

S4_RampCrossSlope: 11.2

S5_WingSlope1: 0.3


S6_WingSlope2: 23.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_458





OBJECTID (Perpendicular Ramp): 370

Name: CR_458

Address: 1800 NW Hughwood Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.4

S4_RampCrossSlope: 4.7

S5_WingSlope1: 12.9


S6_WingSlope2: 9.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_1





OBJECTID (Bus Stop-Median): 1

Name: CR_1

Address: 455 SE Jackson St

Comments: On jackson


D1_LandingDim1: 5.0


D2_LandingDim2: 5.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.4

CR_2





OBJECTID (Bus Stop-Median): 2

Name: CR_2

Address: 455 SE Jackson St

Comments: On washington


D1_LandingDim1: 5.8

D2_LandingDim2: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2:

CR_3





OBJECTID (Bus Stop-Median): 3

Name: CR_3

Address: 507 SE Jackson St

Comments: On washington


D1_LandingDim1: 6.0

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 0.9

CR_4





OBJECTID (Bus Stop-Median): 4

Name: CR_4

Address: 507 SE Jackson St

Comments: On jackson


D1_LandingDim1: 5.8

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.5

S2_LandingSlope2: 0.5

CR_93





OBJECTID (Perpendicular Ramp): 4

Name: CR_93

Address: 358 SE Jackson St

TruncDomes: True

Comments: On douglas

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.1

S2_LandingSlope2:

S3_RampSlope: 5.0

S4_RampCrossSlope: 0.3

S5_WingSlope1: 6.2


S6_WingSlope2: 5.1

S7_CounterSlope: 3.7

GutterSlope: 0.3

LipHeight:

CR_5





OBJECTID (Bus Stop-Median): 5

Name: CR_5

Address: 567 SE Jackson St

Comments: On jackson

D1_LandingDim1: 5.2

D2_LandingDim2: 5.0

S1_LandingSlope1: 2.3

S2_LandingSlope2: 0.7

CR_94





OBJECTID (Perpendicular Ramp): 5

Name: CR_94

Address: 358 SE Jackson St

TruncDomes:

Comments: On jackson

D1_LandingDim1: 4.0

D2_LandingDim2: 6.2

D3_RampWidth: 4.0

S1_LandingSlope1: 0.2

S2_LandingSlope2: 5.2

S3_RampSlope: 5.1

S4_RampCrossSlope: 4.3

S5_WingSlope1: 10.2


S6_WingSlope2: 2.5

S7_CounterSlope: 3.8

GutterSlope: 3.3

LipHeight:

CR_6





OBJECTID (Bus Stop-Median): 6

Name: CR_6

Address: 567 SE Jackson St

Comments: On oak

D1_LandingDim1: 5.3

D2_LandingDim2: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 1.1

CR_95





OBJECTID (Perpendicular Ramp): 6

Name: CR_95

Address: 358 SE Jackson St

TruncDomes: True

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.6

S2_LandingSlope2: 3.2

S3_RampSlope: 2.4

S4_RampCrossSlope: 2.4

S5_WingSlope1: 0.2


S6_WingSlope2: 7.3

S7_CounterSlope: 2.0

GutterSlope:

LipHeight:

CR_8





OBJECTID (Bus Stop-Median): 8

Name: CR_8

Address: 611 SE Jackson St

Comments: On jackson


D1_LandingDim1: 4.9

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 2.0

CR_18





OBJECTID (Bus Stop-Median): 18

Name: CR_18

Address: 455 SE Jackson St

Comments: On jackson

D1_LandingDim1: 5.2

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 3.3

CR_19





OBJECTID (Bus Stop-Median): 19

Name: CR_19

Address: 455 SE Jackson St

Comments: On washington


D1_LandingDim1: 5.3

D2_LandingDim2: 4.0

S1_LandingSlope1: 2.5

S2_LandingSlope2:

CR_20





OBJECTID (Bus Stop-Median): 20

Name: CR_20

Address: 506 SE Jackson St

Comments: On washington. Rock in landing


D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

S1_LandingSlope1: 3.4

S2_LandingSlope2: 0.6

CR_21





OBJECTID (Bus Stop-Median): 21

Name: CR_21

Address: 506 SE Jackson St

Comments: On jackson


D1_LandingDim1: 5.2


D2_LandingDim2: 4.0

S1_LandingSlope1: 0.5

S2_LandingSlope2: 1.4

CR_22





OBJECTID (Bus Stop-Median): 22

Name: CR_22

Address: 562 SE Jackson St

Comments: On jackson


D1_LandingDim1: 5.2

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 0.7

CR_111





OBJECTID (Perpendicular Ramp): 22

Name: CR_111

Address: 647 SE Jackson St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.4

S4_RampCrossSlope: 0.7

S5_WingSlope1: 11.2


S6_WingSlope2: 13.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_23





OBJECTID (Bus Stop-Median): 23

Name: CR_23

Address: 562 SE Jackson St

Comments: On oak


D1_LandingDim1: 5.7

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 0.9

CR_112





OBJECTID (Perpendicular Ramp): 23

Name: CR_112

Address: 709 SE Jackson St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.7

S4_RampCrossSlope: 1.4

S5_WingSlope1: 11.5


S6_WingSlope2: 12.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_113





OBJECTID (Perpendicular Ramp): 24

Name: CR_113

Address: 749 SE Jackson St

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 5.5

D3_RampWidth: 4.0

S1_LandingSlope1: 3.8

S2_LandingSlope2: 0.2

S3_RampSlope: 4.9

S4_RampCrossSlope: 0.2

S5_WingSlope1: 5.9


S6_WingSlope2: 4.8

S7_CounterSlope: 2.1

GutterSlope: 0.5

LipHeight:

CR_167





OBJECTID (Perpendicular Ramp): 78

Name: CR_167

Address: 709 SE Jackson St

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 7.0

D3_RampWidth: 2.4

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.4

S3_RampSlope: 11.3

S4_RampCrossSlope: 0.1

S5_WingSlope1: 10.7


S6_WingSlope2: 10.4

S7_CounterSlope: 4.0

GutterSlope: 0.8

LipHeight: 0.3

CR_168





OBJECTID (Perpendicular Ramp): 79

Name: CR_168

Address: 782 SE Jackson St

TruncDomes:

Comments: On jackson. Poles in wings

D1_LandingDim1: 5.3

D2_LandingDim2: 6.0

D3_RampWidth: 5.3

S1_LandingSlope1: 2.0

S2_LandingSlope2: 0.4

S3_RampSlope: 8.7

S4_RampCrossSlope: 1.4

S5_WingSlope1: 14.5

S6_WingSlope2: 9.4

S7_CounterSlope: 10.0

GutterSlope: 1.4

LipHeight:

CR_169





OBJECTID (Perpendicular Ramp): 80

Name: CR_169

Address: 782 SE Jackson St

TruncDomes:

Comments: On lane

D1_LandingDim1: 5.2

D2_LandingDim2: 5.4

D3_RampWidth: 5.2

S1_LandingSlope1: 0.4

S2_LandingSlope2: 1.0

S3_RampSlope: 8.6

S4_RampCrossSlope: 0.7

S5_WingSlope1: 9.5


S6_WingSlope2: 15.6

S7_CounterSlope: 5.5

GutterSlope: 2.9

LipHeight:

CR_217





OBJECTID (Perpendicular Ramp): 128

Name: CR_217

Address: 400 SE Jackson St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth: 5.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 2.4

S3_RampSlope: 4.5

S4_RampCrossSlope: 2.0

S5_WingSlope1: 3.2

S6_WingSlope2: 4.2

S7_CounterSlope: 4.2

GutterSlope: 2.4

LipHeight:

CR_218





OBJECTID (Perpendicular Ramp): 129

Name: CR_218

Address: 400 SE Jackson St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.6

D3_RampWidth: 5.0

S1_LandingSlope1: 0.3

S2_LandingSlope2: 0.4

S3_RampSlope: 4.4

S4_RampCrossSlope: 1.0

S5_WingSlope1: 4.2

S6_WingSlope2: 3.9

S7_CounterSlope: 3.5

GutterSlope: 0.6

LipHeight:

CR_73





OBJECTID (Combination Ramp): 26

Name: CR_73

Address: 1190 NE Junker Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.2

D2_LandingDim2: 3.9

D3_RampWidth2: 5.5

D4_RampWidth3: 5.5

D5_RampWidth1: 3.8

S1_LandingSlope1: 2.1

S2_LandingSlope2: 2.4

S3_RampCrossSlope2: 3.6

S4_RampSlope2: 13.6

S5_RampCrossSlope3: 3.6

S6_RampSlope3: 2.0

S7_RampSlope1: 6.5

S8_RampCrossSlope1: 2.4

S9_WingSlope1: 12.7

S10_WingSlope2: 5.4

S11_CounterSlope: 5.4

GutterSlope: 4.4

LipHeight:

CR_74





OBJECTID (Combination Ramp): 27

Name: CR_74

Address: 1190 NE Junker Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.2

D2_LandingDim2: 3.9

D3_RampWidth2: 5.8

D4_RampWidth3: 5.8

D5_RampWidth1: 4.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 20.8

S3_RampCrossSlope2: 4.5

S4_RampSlope2: 26.1

S5_RampCrossSlope3: 5.3

S6_RampSlope3: 12.3

S7_RampSlope1: 7.7

S8_RampCrossSlope1: 14.8

S9_WingSlope1: 21.3

S10_WingSlope2: 9.4

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_125





OBJECTID (Perpendicular Ramp): 36

Name: CR_125

Address: 803 SE Kane St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.4

S1_LandingSlope1: 9.0

S2_LandingSlope2: 2.7

S3_RampSlope: 6.4

S4_RampCrossSlope: 8.2

S5_WingSlope1: 10.3


S6_WingSlope2: 0.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_126





OBJECTID (Perpendicular Ramp): 37

Name: CR_126

Address: 803 SE Kane St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.6

S4_RampCrossSlope: 5.2

S5_WingSlope1: 19.2

S6_WingSlope2: 1.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_181





OBJECTID (Perpendicular Ramp): 92

Name: CR_181

Address: 759 SE Kane St

TruncDomes:

Comments: Built into driveway entrance

D1_LandingDim1: 4.7

D2_LandingDim2: 4.0

D3_RampWidth: 4.7

S1_LandingSlope1: 4.8

S2_LandingSlope2: 1.1

S3_RampSlope: 11.5

S4_RampCrossSlope: 0.8

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_340





OBJECTID (Perpendicular Ramp): 252

Name: CR_340

Address: 1605 NW Keasey St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.0

S4_RampCrossSlope: 6.2

S5_WingSlope1: 9.3


S6_WingSlope2: 17.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_341





OBJECTID (Perpendicular Ramp): 253

Name: CR_341

Address: 1601 NW Keasey St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.5

S4_RampCrossSlope: 0.6

S5_WingSlope1: 11.9


S6_WingSlope2: 6.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_345





OBJECTID (Perpendicular Ramp): 257

Name: CR_345

Address: 1711 NW Keasey St

TruncDomes: True

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 3.0

D3_RampWidth: 3.9

S1_LandingSlope1: 3.5

S2_LandingSlope2: 9.3

S3_RampSlope: 5.7

S4_RampCrossSlope: 6.0

S5_WingSlope1: 0.8


S6_WingSlope2: 12.0

S7_CounterSlope: 10.7

GutterSlope: 5.1

LipHeight:

CR_346





OBJECTID (Perpendicular Ramp): 258

Name: CR_346

Address: 1712 NW Keasey St

TruncDomes: True

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 3.0

D3_RampWidth: 3.8

S1_LandingSlope1: 2.6

S2_LandingSlope2: 9.4

S3_RampSlope: 9.2

S4_RampCrossSlope: 6.8

S5_WingSlope1: 4.9


S6_WingSlope2: 12.7

S7_CounterSlope: 11.7

GutterSlope: 3.7

LipHeight:

CR_347





OBJECTID (Perpendicular Ramp): 259

Name: CR_347

Address: 1541 NW Keasey St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.9

S4_RampCrossSlope: 0.9

S5_WingSlope1: 11.0


S6_WingSlope2: 14.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_348





OBJECTID (Perpendicular Ramp): 260

Name: CR_348

Address: 1531 NW Keasey St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 4.4

S5_WingSlope1: 12.7


S6_WingSlope2: 6.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_349





OBJECTID (Perpendicular Ramp): 261

Name: CR_349

Address: 1375 NW Keasey St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.1

S4_RampCrossSlope: 0.5

S5_WingSlope1: 8.0

S6_WingSlope2: 11.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_350





OBJECTID (Perpendicular Ramp): 262

Name: CR_350

Address: 1251 NW Keasey St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.6

S4_RampCrossSlope: 2.5

S5_WingSlope1: 10.2

S6_WingSlope2: 12.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_351





OBJECTID (Perpendicular Ramp): 263

Name: CR_351

Address: 1251 NW Keasey St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 4.8

S4_RampCrossSlope: 2.2

S5_WingSlope1: 13.7


S6_WingSlope2: 8.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_413





OBJECTID (Perpendicular Ramp): 325

Name: CR_413

Address: 1202 NW Keasey St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.9

S4_RampCrossSlope: 1.6

S5_WingSlope1: 12.4

S6_WingSlope2: 16.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_414





OBJECTID (Perpendicular Ramp): 326

Name: CR_414

Address: 1202 NW Keasey St

TruncDomes:

Comments: No landing.

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.2

S4_RampCrossSlope: 2.0

S5_WingSlope1: 12.2


S6_WingSlope2: 14.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_426





OBJECTID (Perpendicular Ramp): 338

Name: CR_426

Address: 1591 NW Keasey St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.1

S4_RampCrossSlope: 7.3

S5_WingSlope1: 20.0

S6_WingSlope2: 5.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_429





OBJECTID (Perpendicular Ramp): 341

Name: CR_429

Address: 1925 NW Keasey St

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.0

D3_RampWidth: 4.0

S1_LandingSlope1: 2.8

S2_LandingSlope2: 2.5

S3_RampSlope: 10.6

S4_RampCrossSlope: 2.0

S5_WingSlope1: 8.3

S6_WingSlope2: 11.2

S7_CounterSlope: 11.5

GutterSlope: 1.0

LipHeight:

CR_430





OBJECTID (Perpendicular Ramp): 342

Name: CR_430

Address: 1871 NW Keasey St

TruncDomes: True

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 2.9

D3_RampWidth: 3.9

S1_LandingSlope1: 2.3

S2_LandingSlope2: 7.9

S3_RampSlope: 7.2

S4_RampCrossSlope: 6.6

S5_WingSlope1: 2.9


S6_WingSlope2: 12.0

S7_CounterSlope: 13.0

GutterSlope: 3.8

LipHeight:

CR_431





OBJECTID (Perpendicular Ramp): 343

Name: CR_431

Address: 1572 NW Keasey St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.4

S4_RampCrossSlope: 1.3

S5_WingSlope1: 14.2


S6_WingSlope2: 21.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_432





OBJECTID (Perpendicular Ramp): 344

Name: CR_432

Address: 1562 NW Keasey St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 0.6

S5_WingSlope1: 13.3

S6_WingSlope2: 8.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_434





OBJECTID (Perpendicular Ramp): 346

Name: CR_434

Address: 1301 NW Keasey St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.1

S4_RampCrossSlope: 2.8

S5_WingSlope1: 16.0

S6_WingSlope2: 10.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_67





OBJECTID (Combination Ramp): 20

Name: CR_67

Address: 2335 NW Kline St

TruncDomes: True

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 3.9

D3_RampWidth2: 6.3

D4_RampWidth3: 5.9

D5_RampWidth1: 3.9

S1_LandingSlope1: 3.0

S2_LandingSlope2: 8.1

S3_RampCrossSlope2: 3.9

S4_RampSlope2: 15.4

S5_RampCrossSlope3: 0.9

S6_RampSlope3: 0.1

S7_RampSlope1: 1.8

S8_RampCrossSlope1: 6.5

S9_WingSlope1: 14.7


S10_WingSlope2: 1.6

S11_CounterSlope: 10.3

GutterSlope: 7.8

LipHeight:

CR_769





OBJECTID (Parallel Ramp): 46

Name: CR_769

Address: 1810 NW Kline St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.2

S3_RampCrossSlope1: 1.2

S4_RampSlope1: 2.6

S5_RampCrossSlope2: 1.2

S6_RampSlope2: 6.0

S7_CounterSlope: 10.6

GutterSlope: 0.8

LipHeight:

CR_872






OBJECTID (Unclassified Ramp): 47 **Address:** 2164 NW Kline St

Name: CR_872

CR_873





OBJECTID (Unclassified Ramp): 48 **Address:** 2165 NW Kline St

Name: CR_873

CR_874






OBJECTID (Unclassified Ramp): 49 **Address:** 2124 NW Kline St

Name: CR_874

CR_875






OBJECTID (Unclassified Ramp): 50 **Address:** 2046 NW Kline St

Name: CR_875

CR_876






OBJECTID (Unclassified Ramp): 51 **Address:** 1714 NW Kline St

Name: CR_876

CR_877






OBJECTID (Unclassified Ramp): 52 **Address:** 1690 NW Kline St

Name: CR_877

CR_339





OBJECTID (Perpendicular Ramp): 251

Name: CR_339

Address: 1613 NW Kline St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.7

S4_RampCrossSlope: 1.7

S5_WingSlope1: 10.9


S6_WingSlope2: 6.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_355





OBJECTID (Perpendicular Ramp): 267

Name: CR_355

Address: 1841 NW Kline St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.1

S4_RampCrossSlope: 2.5

S5_WingSlope1: 15.3


S6_WingSlope2: 12.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_356





OBJECTID (Perpendicular Ramp): 268

Name: CR_356

Address: 1919 NW Kline St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.2

S4_RampCrossSlope: 1.5

S5_WingSlope1: 15.7


S6_WingSlope2: 13.5

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_357





OBJECTID (Perpendicular Ramp): 269

Name: CR_357

Address: 1810 NW Kline St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.3

S4_RampCrossSlope: 3.7

S5_WingSlope1: 11.4


S6_WingSlope2: 22.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_358





OBJECTID (Perpendicular Ramp): 270

Name: CR_358

Address: 1714 NW Kline St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.3

S4_RampCrossSlope: 1.1

S5_WingSlope1: 14.4


S6_WingSlope2: 13.2

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_359





OBJECTID (Perpendicular Ramp): 271

Name: CR_359

Address: 1660 NW Kline St

TruncDomes:

Comments: Non compliant ramp no landing, catch basin at throats of ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.0

S4_RampCrossSlope: 0.3

S5_WingSlope1: 12.3


S6_WingSlope2: 14.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_362





OBJECTID (Perpendicular Ramp): 274

Name: CR_362

Address: 2365 NW Kline St

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 3.9

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.7

S3_RampSlope: 6.9

S4_RampCrossSlope: 5.5

S5_WingSlope1: 1.8

S6_WingSlope2: 13.0

S7_CounterSlope: 10.2

GutterSlope: 5.8

LipHeight:

CR_363





OBJECTID (Perpendicular Ramp): 275

Name: CR_363

Address: 2365 NW Kline St

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.2

D3_RampWidth: 4.0

S1_LandingSlope1: 2.8

S2_LandingSlope2: 12.2

S3_RampSlope: 8.9

S4_RampCrossSlope: 11.2

S5_WingSlope1: 17.7


S6_WingSlope2: 1.0

S7_CounterSlope: 13.1

GutterSlope: 10.4

LipHeight:

CR_425





OBJECTID (Perpendicular Ramp): 337

Name: CR_425

Address: 1613 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.5

S4_RampCrossSlope: 1.2

S5_WingSlope1: 13.7

S6_WingSlope2: 19.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_435





OBJECTID (Perpendicular Ramp): 347

Name: CR_435

Address: 2164 NW Kline St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 8.7

S3_RampSlope: 1.2

S4_RampCrossSlope: 6.9

S5_WingSlope1: 0.8


S6_WingSlope2: 13.2

S7_CounterSlope: 5.4

GutterSlope:

LipHeight:

CR_436





OBJECTID (Perpendicular Ramp): 348

Name: CR_436

Address: 2164 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.4

S4_RampCrossSlope: 2.2

S5_WingSlope1: 20.1

S6_WingSlope2: 10.2

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_437





OBJECTID (Perpendicular Ramp): 349

Name: CR_437

Address: 2165 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.4

S4_RampCrossSlope: 3.7

S5_WingSlope1: 12.1


S6_WingSlope2: 11.2

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_438





OBJECTID (Perpendicular Ramp): 350

Name: CR_438

Address: 2026 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.1

S4_RampCrossSlope: 1.6

S5_WingSlope1: 13.5


S6_WingSlope2: 18.0

S7_CounterSlope:

GutterSlope:

LipHeight: 0.5

CR_439





OBJECTID (Perpendicular Ramp): 351

Name: CR_439

Address: 1949 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.6

S4_RampCrossSlope: 10.3

S5_WingSlope1: 2.5


S6_WingSlope2: 18.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_440





OBJECTID (Perpendicular Ramp): 352

Name: CR_440

Address: 1949 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 0.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.8

S4_RampCrossSlope: 16.5

S5_WingSlope1: 18.2


S6_WingSlope2: 1.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_441





OBJECTID (Perpendicular Ramp): 353

Name: CR_441

Address: 2025 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.8

S4_RampCrossSlope: 1.8

S5_WingSlope1: 13.9

S6_WingSlope2: 17.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_443





OBJECTID (Perpendicular Ramp): 355

Name: CR_443

Address: 1690 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.1

S4_RampCrossSlope: 6.3

S5_WingSlope1: 21.3

S6_WingSlope2: 7.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_444





OBJECTID (Perpendicular Ramp): 356

Name: CR_444

Address: 1660 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.1

S4_RampCrossSlope: 3.4

S5_WingSlope1: 11.4


S6_WingSlope2: 13.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_445





OBJECTID (Perpendicular Ramp): 357

Name: CR_445

Address: 2335 NW Kline St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.6

S4_RampCrossSlope: 3.2

S5_WingSlope1: 15.8

S6_WingSlope2: 26.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_448





OBJECTID (Perpendicular Ramp): 360

Name: CR_448

Address: 2591 NW Kline St

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 4.9

S1_LandingSlope1: 1.6

S2_LandingSlope2: 18.9

S3_RampSlope: 5.7

S4_RampCrossSlope: 18.0

S5_WingSlope1: 23.2

S6_WingSlope2: 7.5

S7_CounterSlope: 8.4

GutterSlope: 14.6

LipHeight:

CR_449





OBJECTID (Perpendicular Ramp): 361

Name: CR_449

Address: 2591 NW Kline St

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 4.0

D3_RampWidth: 5.1

S1_LandingSlope1: 1.6

S2_LandingSlope2: 6.3

S3_RampSlope: 1.2

S4_RampCrossSlope: 3.3

S5_WingSlope1: 13.3


S6_WingSlope2: 6.8

S7_CounterSlope: 5.2

GutterSlope: 2.7

LipHeight:

CR_379





OBJECTID (Perpendicular Ramp): 291

Name: CR_379

Address: 1954 NW Lamont Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.6

S4_RampCrossSlope: 5.9

S5_WingSlope1: 3.4

S6_WingSlope2: 18.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_380





OBJECTID (Perpendicular Ramp): 292

Name: CR_380

Address: 1954 NW Lamont Ave

TruncDomes:

Comments: Non compliant ramp no landing, hydrant in ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.2

S4_RampCrossSlope: 4.6

S5_WingSlope1: 10.3


S6_WingSlope2: 11.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_859






OBJECTID (Unclassified Ramp): 34 **Address:** 1187 NW Lanaias Way

Name: CR_859

CR_860





OBJECTID (Unclassified Ramp): 35 **Address:** 1187 NW Lanaias Way

Name: CR_860

CR_869






OBJECTID (Unclassified Ramp): 44 **Address:** 1187 NW Lanaias Way

Name: CR_869

CR_870





OBJECTID (Unclassified Ramp): 45 **Address:** 1187 NW Lanaias Way

Name: CR_870

CR_323





OBJECTID (Perpendicular Ramp): 234

Name: CR_323

Address: 1187 NW Lanaias Way

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.8

S4_RampCrossSlope: 1.1

S5_WingSlope1: 19.9


S6_WingSlope2: 16.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_324





OBJECTID (Perpendicular Ramp): 235

Name: CR_324

Address: 1187 NW Lanaias Way

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.2

S4_RampCrossSlope: 1.4

S5_WingSlope1: 18.1

S6_WingSlope2: 25.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_410





OBJECTID (Perpendicular Ramp): 322

Name: CR_410

Address: 1187 NW Lanaias Way

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.2

S4_RampCrossSlope: 5.0

S5_WingSlope1: 18.0


S6_WingSlope2: 23.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_411





OBJECTID (Perpendicular Ramp): 323

Name: CR_411

Address: 1187 NW Lanaias Way

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.2

S4_RampCrossSlope: 0.3

S5_WingSlope1: 32.7


S6_WingSlope2: 27.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_832






OBJECTID (Unclassified Ramp): 7 **Address:** 725 SE Lane Ave

Name: CR_832

CR_833






OBJECTID (Unclassified Ramp): 8 **Address:** 725 SE Lane Ave

Name: CR_833

CR_834





OBJECTID (Unclassified Ramp): 9 **Address:** 1217 SE Lane Ave

Name: CR_834

CR_835





OBJECTID (Unclassified Ramp): 10 **Address:** 1149 SE Lane Ave

Name: CR_835

CR_836





OBJECTID (Unclassified Ramp): 11 **Address:** 1238 SE Lane Ave

Name: CR_836

CR_837






OBJECTID (Unclassified Ramp): 12 **Address:** 1238 SE Lane Ave

Name: CR_837

CR_844






OBJECTID (Unclassified Ramp): 19 **Address:** 725 SE Lane Ave

Name: CR_844

CR_845





OBJECTID (Unclassified Ramp): 20 **Address:** 725 SE Lane Ave

Name: CR_845

CR_848





OBJECTID (Unclassified Ramp): 23 **Address:** 1412 SE Lane Ave

Name: CR_848

CR_849






OBJECTID (Unclassified Ramp): 24 **Address:** 1412 SE Lane Ave

Name: CR_849

CR_114





OBJECTID (Perpendicular Ramp): 25

Name: CR_114

Address: 911 SE Lane Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.8

D3_RampWidth: 4.0

S1_LandingSlope1: 4.2

S2_LandingSlope2: 0.1

S3_RampSlope: 5.3

S4_RampCrossSlope: 1.2

S5_WingSlope1: 4.8


S6_WingSlope2: 7.2

S7_CounterSlope: 3.6

GutterSlope: 1.3

LipHeight:

CR_850






OBJECTID (Unclassified Ramp): 25 **Address:** 1452 SE Lane Ave

Name: CR_850

CR_123





OBJECTID (Perpendicular Ramp): 34

Name: CR_123

Address: 725 SE Lane Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 2.1

S3_RampSlope: 5.9

S4_RampCrossSlope: 1.3

S5_WingSlope1: 6.7

S6_WingSlope2: 7.1

S7_CounterSlope: 8.6

GutterSlope: 2.2

LipHeight:

CR_124





OBJECTID (Perpendicular Ramp): 35

Name: CR_124

Address: 808 SE Lane Ave

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.6

S4_RampCrossSlope: 3.8

S5_WingSlope1: 10.1

S6_WingSlope2: 15.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_170





OBJECTID (Perpendicular Ramp): 81

Name: CR_170

Address: 823 SE Lane Ave

TruncDomes:

Comments: Stair/planting structure in landing

D1_LandingDim1: 3.4

D2_LandingDim2: 1.9

D3_RampWidth: 3.4

S1_LandingSlope1: 0.7

S2_LandingSlope2: 2.3

S3_RampSlope: 7.5

S4_RampCrossSlope: 2.6

S5_WingSlope1: 8.5

S6_WingSlope2: 6.3

S7_CounterSlope: 9.9

GutterSlope: 0.7

LipHeight:

CR_171





OBJECTID (Perpendicular Ramp): 82

Name: CR_171

Address: 911 SE Lane Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 5.0

D3_RampWidth: 3.6

S1_LandingSlope1: 2.7

S2_LandingSlope2: 7.1

S3_RampSlope: 8.5

S4_RampCrossSlope: 2.9

S5_WingSlope1: 23.6


S6_WingSlope2: 25.4

S7_CounterSlope: 5.2

GutterSlope: 1.1

LipHeight:

CR_172





OBJECTID (Perpendicular Ramp): 83

Name: CR_172

Address: 911 SE Lane Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 4.0

D3_RampWidth: 4.3

S1_LandingSlope1: 3.3

S2_LandingSlope2: 5.3

S3_RampSlope: 8.6

S4_RampCrossSlope: 2.4

S5_WingSlope1: 19.5

S6_WingSlope2: 16.7

S7_CounterSlope: 8.8

GutterSlope: 1.2

LipHeight:

CR_178





OBJECTID (Perpendicular Ramp): 89

Name: CR_178

Address: 725 SE Lane Ave

TruncDomes:

Comments: Property corner in landing

D1_LandingDim1: 3.3

D2_LandingDim2: 4.0

D3_RampWidth: 3.3

S1_LandingSlope1: 2.8

S2_LandingSlope2: 1.6

S3_RampSlope: 9.1

S4_RampCrossSlope: 2.0

S5_WingSlope1: 11.3

S6_WingSlope2: 10.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_179





OBJECTID (Perpendicular Ramp): 90

Name: CR_179

Address: 808 SE Lane Ave

TruncDomes:

Comments: No obvious landing. Sign foundation in viable landing area

D1_LandingDim1: 2.9

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1: 4.0

S2_LandingSlope2: 0.6

S3_RampSlope: 9.7

S4_RampCrossSlope: 0.7

S5_WingSlope1: 10.0


S6_WingSlope2: 6.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_180





OBJECTID (Perpendicular Ramp): 91

Name: CR_180

Address: 1037 SE Lane Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 3.5

D3_RampWidth: 4.5

S1_LandingSlope1: 1.1

S2_LandingSlope2: 3.2

S3_RampSlope: 13.8

S4_RampCrossSlope: 15.1

S5_WingSlope1: 14.9


S6_WingSlope2: 15.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_868






OBJECTID (Unclassified Ramp): 43 **Address:** 1719 NW Le Mans St

Name: CR_868

CR_321





OBJECTID (Perpendicular Ramp): 232

Name: CR_321

Address: 1898 NW Le Mans St

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.8

S2_LandingSlope2: 1.8

S3_RampSlope: 13.3

S4_RampCrossSlope: 0.7

S5_WingSlope1: 8.4


S6_WingSlope2: 8.7

S7_CounterSlope: 6.3

GutterSlope: 0.4

LipHeight:

CR_353





OBJECTID (Perpendicular Ramp): 265

Name: CR_353

Address: 1898 NW Le Mans St

TruncDomes: True

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 3.0

D3_RampWidth: 3.9

S1_LandingSlope1: 1.2

S2_LandingSlope2: 2.4

S3_RampSlope: 8.7

S4_RampCrossSlope: 0.9

S5_WingSlope1: 2.0


S6_WingSlope2: 10.1

S7_CounterSlope: 10.4

GutterSlope: 0.7

LipHeight:

CR_354





OBJECTID (Perpendicular Ramp): 266

Name: CR_354

Address: 1898 NW Le Mans St

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 3.3

D3_RampWidth: 4.9

S1_LandingSlope1: 1.1

S2_LandingSlope2: 1.6

S3_RampSlope: 9.2

S4_RampCrossSlope: 1.6

S5_WingSlope1: 10.9

S6_WingSlope2: 3.3

S7_CounterSlope: 7.6

GutterSlope: 1.0

LipHeight:

CR_408





OBJECTID (Perpendicular Ramp): 320

Name: CR_408

Address: 1879 NW Le Mans St

TruncDomes:

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 3.3

D3_RampWidth: 5.1

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.7

S3_RampSlope: 5.7

S4_RampCrossSlope: 1.1

S5_WingSlope1: 5.2

S6_WingSlope2: 10.7

S7_CounterSlope: 9.9

GutterSlope: 0.6

LipHeight:

CR_77





OBJECTID (Combination Ramp): 30

Name: CR_77

Address: 1491 NE Lincoln St

TruncDomes:

Comments:

D1_LandingDim1: 3.6

D2_LandingDim2: 3.9

D3_RampWidth2: 6.0

D4_RampWidth3: 5.6

D5_RampWidth1: 4.0

S1_LandingSlope1: 2.5

S2_LandingSlope2: 10.0

S3_RampCrossSlope2: 3.0

S4_RampSlope2: 5.5

S5_RampCrossSlope3: 3.8

S6_RampSlope3: 18.9

S7_RampSlope1: 8.8

S8_RampCrossSlope1: 10.4

S9_WingSlope1: 0.6

S10_WingSlope2: 18.9

S11_CounterSlope: 5.3

GutterSlope: 7.3

LipHeight:

CR_890





OBJECTID (Unclassified Ramp): 65 **Address:** 1017 NE Lincoln St

Name: CR_890

CR_891





OBJECTID (Unclassified Ramp): 66 **Address:** 945 NE Lincoln St

Name: CR_891

CR_538





OBJECTID (Perpendicular Ramp): 450

Name: CR_538

Address: 1391 NE Lincoln St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 14.1

S5_WingSlope1: 22.4


S6_WingSlope2: 7.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_331





OBJECTID (Perpendicular Ramp): 243

Name: CR_331

Address: 1206 NW Littlewood Ct

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.8

S4_RampCrossSlope: 0.6

S5_WingSlope1: 24.0

S6_WingSlope2: 14.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_332





OBJECTID (Perpendicular Ramp): 244

Name: CR_332

Address: 1206 NW Littlewood Ct

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 0.9

S5_WingSlope1: 18.0


S6_WingSlope2: 15.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_417





OBJECTID (Perpendicular Ramp): 329

Name: CR_417

Address: 1205 NW Littlewood Ct

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.3

S4_RampCrossSlope: 0.6

S5_WingSlope1: 17.0


S6_WingSlope2: 11.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_418





OBJECTID (Perpendicular Ramp): 330

Name: CR_418

Address: 1206 NW Littlewood Ct

TruncDomes:

Comments: No landing. Hydrant in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.4

S4_RampCrossSlope: 0.8

S5_WingSlope1: 14.3


S6_WingSlope2: 13.4

S7_CounterSlope: 8.7

GutterSlope: 0.7

LipHeight: 1.0

CR_731





OBJECTID (Parallel Ramp): 8

Name: CR_731

Address: 2147 SE Lois St

TruncDomes:

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 5.2

S1_LandingSlope1: 6.1

S2_LandingSlope2: 3.6

S3_RampCrossSlope1: 1.3

S4_RampSlope1: 0.7

S5_RampCrossSlope2: 2.4

S6_RampSlope2: 11.1

S7_CounterSlope: 4.2

GutterSlope:

LipHeight:

CR_867





OBJECTID (Unclassified Ramp): 42 **Address:** 1504 Lookingglass Rd

Name: CR_867

CR_884





OBJECTID (Unclassified Ramp): 59 **Address:** 1504 Lookingglass Rd

Name: CR_884

CR_391





OBJECTID (Perpendicular Ramp): 303

Name: CR_391

Address: 1093 W Lookingglass Rd

TruncDomes: True

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 4.1

D3_RampWidth: 5.0

S1_LandingSlope1: 2.6

S2_LandingSlope2: 8.1

S3_RampSlope: 7.3

S4_RampCrossSlope: 7.3

S5_WingSlope1: 1.7


S6_WingSlope2: 18.6

S7_CounterSlope: 9.3

GutterSlope: 9.4

LipHeight:

CR_482





OBJECTID (Perpendicular Ramp): 394

Name: CR_482

Address: 1093 W Lookingglass Rd

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 3.9

D3_RampWidth: 5.1

S1_LandingSlope1: 1.5

S2_LandingSlope2: 3.6

S3_RampSlope: 7.1

S4_RampCrossSlope: 3.2

S5_WingSlope1: 6.8

S6_WingSlope2: 11.1

S7_CounterSlope: 7.8

GutterSlope: 1.5

LipHeight:

CR_337





OBJECTID (Perpendicular Ramp): 249

Name: CR_337

Address: 1610 NW Lynwood St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.9

S4_RampCrossSlope: 1.0

S5_WingSlope1: 17.9

S6_WingSlope2: 13.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_827






OBJECTID (Unclassified Ramp): 2 **Address:** 1112 SE Main St

Name: CR_827

CR_828






OBJECTID (Unclassified Ramp): 3 **Address:** 1446 SE Main St

Name: CR_828

CR_829





OBJECTID (Unclassified Ramp): 4 **Address:** 1446 SE Main St

Name: CR_829

CR_831






OBJECTID (Unclassified Ramp): 6 **Address:** 1826 SE Main St

Name: CR_831

CR_13





OBJECTID (Bus Stop-Median): 13

Name: CR_13

Address: 505 SE Main St

Comments: On main


D1_LandingDim1: 4.6

D2_LandingDim2: 5.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 1.0

CR_14





OBJECTID (Bus Stop-Median): 14

Name: CR_14

Address: 505 SE Main St

Comments: On Washington

D1_LandingDim1: 4.2

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.6

S2_LandingSlope2: 0.7

CR_839






OBJECTID (Unclassified Ramp): 14 **Address:** 1112 SE Main St

Name: CR_839

CR_15





OBJECTID (Bus Stop-Median): 15

Name: CR_15

Address: 448 SE Main St

Comments: On washington


D1_LandingDim1: 5.3

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.3

S2_LandingSlope2: 1.6

CR_840






OBJECTID (Unclassified Ramp): 15 **Address:** 1185 SE Main St

Name: CR_840

CR_16





OBJECTID (Bus Stop-Median): 16

Name: CR_16

Address: 448 SE Main St

Comments: On main

D1_LandingDim1: 5.2

D2_LandingDim2: 5.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.5

CR_841





OBJECTID (Unclassified Ramp): 16 **Address:** 1466 SE Main St

Name: CR_841

CR_842






OBJECTID (Unclassified Ramp): 17 **Address:** 1433 SE Main St

Name: CR_842

CR_115





OBJECTID (Perpendicular Ramp): 26

Name: CR_115

Address: 809 SE Main St

TruncDomes:

Comments:

D1_LandingDim1: 3.0

D2_LandingDim2: 2.0

D3_RampWidth: 3.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 3.9

S3_RampSlope: 8.0

S4_RampCrossSlope: 2.0

S5_WingSlope1: 14.7


S6_WingSlope2: 6.3

S7_CounterSlope: 8.2

GutterSlope: 0.2

LipHeight:

CR_116





OBJECTID (Perpendicular Ramp): 27

Name: CR_116

Address: 753 SE Main St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.5

S4_RampCrossSlope: 2.5

S5_WingSlope1: 15.4


S6_WingSlope2: 12.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_119





OBJECTID (Perpendicular Ramp): 30

Name: CR_119

Address: 1185 SE Main St

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 13.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.7

S4_RampCrossSlope: 2.1

S5_WingSlope1: 15.6


S6_WingSlope2: 20.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_120





OBJECTID (Perpendicular Ramp): 31

Name: CR_120

Address: 1185 SE Main St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 2.5

S4_RampCrossSlope: 5.5

S5_WingSlope1: 17.2

S6_WingSlope2: 6.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_121





OBJECTID (Perpendicular Ramp): 32

Name: CR_121

Address: 1337 SE Main St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 0.4

S4_RampCrossSlope: 2.6

S5_WingSlope1: 13.1

S6_WingSlope2: 6.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_122





OBJECTID (Perpendicular Ramp): 33

Name: CR_122

Address: 1566 SE Main St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 8.3

S5_WingSlope1: 0.9

S6_WingSlope2: 12.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_175





OBJECTID (Perpendicular Ramp): 86

Name: CR_175

Address: 1185 SE Main St

TruncDomes:

Comments: On orcutt

D1_LandingDim1: 5.9

D2_LandingDim2: 4.4

D3_RampWidth: 3.2

S1_LandingSlope1: 4.0

S2_LandingSlope2: 4.3

S3_RampSlope: 13.2

S4_RampCrossSlope: 5.7

S5_WingSlope1: 21.0

S6_WingSlope2: 22.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_176





OBJECTID (Perpendicular Ramp): 87

Name: CR_176

Address: 1366 SE Main St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.2

S1_LandingSlope1: 8.4

S2_LandingSlope2: 4.2

S3_RampSlope: 6.4

S4_RampCrossSlope: 8.7

S5_WingSlope1: 19.4


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_220





OBJECTID (Perpendicular Ramp): 131

Name: CR_220

Address: 419 SE Main St

TruncDomes: True

Comments: Clean Living Honns sign at 3.5' from back of landing. Room for4' landing adjacent

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.3

S2_LandingSlope2: 0.1

S3_RampSlope: 4.8

S4_RampCrossSlope: 0.3

S5_WingSlope1: 4.9


S6_WingSlope2: 5.3

S7_CounterSlope: 1.0

GutterSlope: 0.1

LipHeight:

CR_886






OBJECTID (Unclassified Ramp): 61 **Address:** 712 NE Meadow Ave

Name: CR_886

CR_892





OBJECTID (Unclassified Ramp): 67 **Address:** 691 NE Meadow Ave

Name: CR_892

CR_800





OBJECTID (Parallel Ramp): 77

Name: CR_800

Address: 482 NE Meadow Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.3

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 0.2

S3_RampCrossSlope1: 2.3

S4_RampSlope1: 7.2

S5_RampCrossSlope2: 1.4

S6_RampSlope2: 4.8

S7_CounterSlope: 1.6

GutterSlope: 1.2

LipHeight:

CR_801





OBJECTID (Parallel Ramp): 78

Name: CR_801

Address: 482 NE Meadow Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 2.5

S3_RampCrossSlope1: 1.8

S4_RampSlope1: 0.3

S5_RampCrossSlope2: 1.3


S6_RampSlope2: 7.5

S7_CounterSlope: -1.6

GutterSlope: 1.8

LipHeight:

CR_184





OBJECTID (Perpendicular Ramp): 95

Name: CR_184

Address: 927 SE Mill St

TruncDomes:

Comments:

D1_LandingDim1: 3.4

D2_LandingDim2: 4.0

D3_RampWidth: 3.4

S1_LandingSlope1: 2.3

S2_LandingSlope2: 1.5

S3_RampSlope: 10.2

S4_RampCrossSlope: 1.8

S5_WingSlope1: 23.1


S6_WingSlope2: 21.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_838





OBJECTID (Unclassified Ramp): 13 **Address:** 805 SE Mosher Ave

Name: CR_838

CR_747





OBJECTID (Parallel Ramp): 24

Name: CR_747

Address: 185 SE Mosher Ave

TruncDomes:

Comments: On mosher

D1_LandingDim1: 4.5

D2_LandingDim2: 4.0

S1_LandingSlope1: 7.8

S2_LandingSlope2: 0.5

S3_RampCrossSlope1: 5.0

S4_RampSlope1: 8.7

S5_RampCrossSlope2: 6.7


S6_RampSlope2: 7.7

S7_CounterSlope: 9.1

GutterSlope: 1.4

LipHeight:

CR_856





OBJECTID (Unclassified Ramp): 31 **Address:** 104 SE Mosher Ave

Name: CR_856

CR_182





OBJECTID (Perpendicular Ramp): 93

Name: CR_182

Address: 747 SE Mosher Ave

TruncDomes:

Comments: Potential Landing in owners lot

D1_LandingDim1: 4.2

D2_LandingDim2:

D3_RampWidth: 5.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 5.0

S4_RampCrossSlope: 0.3

S5_WingSlope1: 15.3


S6_WingSlope2: 8.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_183





OBJECTID (Perpendicular Ramp): 94

Name: CR_183

Address: 511 SE Mosher Ave

TruncDomes:

Comments: Retaining wall in viable landing area

D1_LandingDim1: 4.6

D2_LandingDim2: 2.0

D3_RampWidth: 4.6

S1_LandingSlope1: 4.2

S2_LandingSlope2: 0.9

S3_RampSlope: 7.8

S4_RampCrossSlope: 0.2

S5_WingSlope1: 12.5


S6_WingSlope2: 14.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_186





OBJECTID (Perpendicular Ramp): 97

Name: CR_186

Address: 233 SE Mosher Ave

TruncDomes:

Comments: No paved ramp. Potential gravel area usage

D1_LandingDim1: 3.5

D2_LandingDim2: 3.5

D3_RampWidth: 4.4

S1_LandingSlope1: 3.6

S2_LandingSlope2: 1.6

S3_RampSlope: 9.9

S4_RampCrossSlope: 1.3

S5_WingSlope1: 10.5


S6_WingSlope2: 5.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_187





OBJECTID (Perpendicular Ramp): 98

Name: CR_187

Address: 233 SE Mosher Ave

TruncDomes:

Comments: On flint

D1_LandingDim1: 6.0

D2_LandingDim2: 5.1

D3_RampWidth: 4.6

S1_LandingSlope1: 2.4

S2_LandingSlope2: 1.2

S3_RampSlope: 11.4

S4_RampCrossSlope: 3.1

S5_WingSlope1: 11.2

S6_WingSlope2: 9.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_188





OBJECTID (Perpendicular Ramp): 99

Name: CR_188

Address: 233 SE Mosher Ave

TruncDomes:

Comments: On mosher

D1_LandingDim1: 5.4

D2_LandingDim2: 6.0

D3_RampWidth: 5.4

S1_LandingSlope1: 2.1

S2_LandingSlope2: 1.9

S3_RampSlope: 11.0

S4_RampCrossSlope: 1.3

S5_WingSlope1: 13.7


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_189





OBJECTID (Perpendicular Ramp): 100

Name: CR_189

Address: 202 SE Mosher Ave

TruncDomes:

Comments: No wings

D1_LandingDim1: 6.1

D2_LandingDim2: 5.7

D3_RampWidth: 4.5

S1_LandingSlope1: 8.0

S2_LandingSlope2: 3.5

S3_RampSlope: 10.4

S4_RampCrossSlope: 2.3

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_190





OBJECTID (Perpendicular Ramp): 101

Name: CR_190

Address: 185 SE Mosher Ave

TruncDomes:

Comments: On fullerton

D1_LandingDim1: 6.0

D2_LandingDim2: 6.5

D3_RampWidth: 4.2

S1_LandingSlope1: 1.5

S2_LandingSlope2: 4.3

S3_RampSlope: 12.7

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2: 8.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_191





OBJECTID (Perpendicular Ramp): 102

Name: CR_191

Address: 185 SE Mosher Ave

TruncDomes:

Comments: On mosher

D1_LandingDim1: 4.3

D2_LandingDim2: 6.0

D3_RampWidth: 4.3

S1_LandingSlope1: 2.6

S2_LandingSlope2: 4.0

S3_RampSlope: 13.1

S4_RampCrossSlope: 3.4

S5_WingSlope1: 11.0


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_236





OBJECTID (Perpendicular Ramp): 147

Name: CR_236

Address: 605 SE Mosher Ave

TruncDomes:

Comments:

D1_LandingDim1: 2.5

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.5

S4_RampCrossSlope: 1.2

S5_WingSlope1: 11.2

S6_WingSlope2: 9.1

S7_CounterSlope: 3.1

GutterSlope: 0.2

LipHeight:

CR_276





OBJECTID (Perpendicular Ramp): 187

Name: CR_276

Address: 185 SE Mosher Ave

TruncDomes:

Comments: On mosher

D1_LandingDim1: 4.0

D2_LandingDim2: 6.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.2

S2_LandingSlope2: 3.1

S3_RampSlope: 3.9

S4_RampCrossSlope: 2.0

S5_WingSlope1: 11.7

S6_WingSlope2:

S7_CounterSlope: 11.6

GutterSlope: 0.8

LipHeight:

CR_277





OBJECTID (Perpendicular Ramp): 188

Name: CR_277

Address: 185 SE Mosher Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.4

D2_LandingDim2: 5.1

D3_RampWidth: 4.4

S1_LandingSlope1: 1.4

S2_LandingSlope2: 0.3

S3_RampSlope: 6.9

S4_RampCrossSlope: 0.3

S5_WingSlope1: 9.4


S6_WingSlope2: 13.8

S7_CounterSlope: 8.1

GutterSlope:

LipHeight:

CR_754





OBJECTID (Parallel Ramp): 31

Name: CR_754

Address: 1447 NW Mulholland Dr

TruncDomes: True

Comments:

D1_LandingDim1: 3.9

D2_LandingDim2: 4.4

S1_LandingSlope1: 3.3

S2_LandingSlope2: 1.9

S3_RampCrossSlope1: 2.3

S4_RampSlope1: 8.0

S5_RampCrossSlope2: 2.3


S6_RampSlope2: 3.5

S7_CounterSlope: 2.3

GutterSlope: 1.5

LipHeight:

CR_755





OBJECTID (Parallel Ramp): 32

Name: CR_755

Address: 1447 NW Mulholland Dr

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 3.8

D2_LandingDim2: 6.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 0.3

S3_RampCrossSlope1: 1.6

S4_RampSlope1: 6.2

S5_RampCrossSlope2: 2.8


S6_RampSlope2: 6.3

S7_CounterSlope: 5.5

GutterSlope: 0.1

LipHeight:

CR_779





OBJECTID (Parallel Ramp): 56

Name: CR_779

Address: 1447 NW Mulholland Dr

TruncDomes: True

Comments: On mulholland

D1_LandingDim1: 4.1

D2_LandingDim2: 5.6

S1_LandingSlope1: 3.9

S2_LandingSlope2: 2.9

S3_RampCrossSlope1: 1.3

S4_RampSlope1: 11.3

S5_RampCrossSlope2: 2.2

S6_RampSlope2: 6.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_202





OBJECTID (Perpendicular Ramp): 113

Name: CR_202

Address: 1941 NW Mulholland Dr

TruncDomes:

Comments: No ramp.

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.4

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 5.8

S4_RampCrossSlope: 3.6

S5_WingSlope1: 7.0

S6_WingSlope2: 9.9

S7_CounterSlope: 17.6

GutterSlope:

LipHeight:

CR_289





OBJECTID (Perpendicular Ramp): 200

Name: CR_289

Address: 1950 NW Mulholland Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 2.8

D3_RampWidth: 4.9

S1_LandingSlope1: 2.0

S2_LandingSlope2: 1.7

S3_RampSlope: 6.6

S4_RampCrossSlope: 1.0

S5_WingSlope1: 9.6

S6_WingSlope2: 11.2

S7_CounterSlope: 2.5

GutterSlope: 0.6

LipHeight:

CR_308





OBJECTID (Perpendicular Ramp): 219

Name: CR_308

Address: 1669 NW Mulholland Dr

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.6

S4_RampCrossSlope: 1.9

S5_WingSlope1: 20.8

S6_WingSlope2: 11.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_309





OBJECTID (Perpendicular Ramp): 220

Name: CR_309

Address: 1669 NW Mulholland Dr

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.0

S4_RampCrossSlope: 0.3

S5_WingSlope1: 18.0

S6_WingSlope2: 13.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_310





OBJECTID (Perpendicular Ramp): 221

Name: CR_310

Address: 1569 NW Mulholland Dr

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.0

S4_RampCrossSlope: 4.9

S5_WingSlope1: 14.5

S6_WingSlope2: 11.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_493





OBJECTID (Perpendicular Ramp): 405

Name: CR_493

Address: 1669 NW Mulholland Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.9

S4_RampCrossSlope: 4.4

S5_WingSlope1: 12.1

S6_WingSlope2: 17.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_494





OBJECTID (Perpendicular Ramp): 406

Name: CR_494

Address: 1669 NW Mulholland Dr

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.3

S4_RampCrossSlope: 4.0

S5_WingSlope1: 22.3


S6_WingSlope2: 25.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_495





OBJECTID (Perpendicular Ramp): 407

Name: CR_495

Address: 1609 NW Mulholland Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.6

S4_RampCrossSlope: 6.7

S5_WingSlope1: 7.5

S6_WingSlope2: 22.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_393





OBJECTID (Perpendicular Ramp): 305

Name: CR_393

Address: 110 Navajo Ave

TruncDomes:

Comments: Broad st Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.4

S4_RampCrossSlope: 0.5

S5_WingSlope1: 6.5

S6_WingSlope2: 11.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_484





OBJECTID (Perpendicular Ramp): 396

Name: CR_484

Address: 109 Navajo Ave

TruncDomes:

Comments: Broad. No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.8

S4_RampCrossSlope: 8.1

S5_WingSlope1: 1.4

S6_WingSlope2: 15.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_7





OBJECTID (Bus Stop-Median): 7

Name: CR_7

Address: 949 SE Oak Ave

Comments: On oak


D1_LandingDim1: 5.1


D2_LandingDim2: 5.0

S1_LandingSlope1: 0.1

S2_LandingSlope2: 1.0

CR_9





OBJECTID (Bus Stop-Median): 9

Name: CR_9

Address: 1022 SE Oak Ave

Comments: On main


D1_LandingDim1: 5.1

D2_LandingDim2: 5.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 0.4

CR_10





OBJECTID (Bus Stop-Median): 10

Name: CR_10

Address: 1022 SE Oak Ave

Comments: On Oak


D1_LandingDim1: 5.3

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 2.5

CR_11





OBJECTID (Bus Stop-Median): 11

Name: CR_11

Address: 1022 SE Oak Ave

Comments: On Oak


D1_LandingDim1: 4.5

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.3

S2_LandingSlope2: 1.3

CR_12





OBJECTID (Bus Stop-Median): 12

Name: CR_12

Address: 1022 SE Oak Ave

Comments: On main

D1_LandingDim1: 4.9

D2_LandingDim2: 5.0

S1_LandingSlope1: 0.1

S2_LandingSlope2: 0.5

CR_24





OBJECTID (Bus Stop-Median): 24

Name: CR_24

Address: 835 SE Oak Ave

Comments: On oak

D1_LandingDim1: 5.7

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 1.9

CR_25





OBJECTID (Bus Stop-Median): 25

Name: CR_25

Address: 835 SE Oak Ave

Comments: On jackson


D1_LandingDim1: 6.4


D2_LandingDim2: 4.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.1

CR_26





OBJECTID (Bus Stop-Median): 26

Name: CR_26

Address: 949 SE Oak Ave

Comments: On main


D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 0.4

CR_27





OBJECTID (Bus Stop-Median): 27

Name: CR_27

Address: 949 SE Oak Ave

Comments: On oak


D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

S1_LandingSlope1: 0.3

S2_LandingSlope2: 0.2

CR_28





OBJECTID (Bus Stop-Median): 28

Name: CR_28

Address: 950 SE Oak Ave

Comments: On oak


D1_LandingDim1: 4.8

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 0.7

CR_29





OBJECTID (Bus Stop-Median): 29

Name: CR_29

Address: 950 SE Oak Ave

Comments: On main


D1_LandingDim1: 4.8

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 0.5

CR_506





OBJECTID (Perpendicular Ramp): 418

Name: CR_506

Address: 678 NE Oakland Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.4

D3_RampWidth: 5.0

S1_LandingSlope1: 2.1

S2_LandingSlope2: 0.9

S3_RampSlope: 9.7

S4_RampCrossSlope: 0.8

S5_WingSlope1: 10.1


S6_WingSlope2: 10.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_507





OBJECTID (Perpendicular Ramp): 419

Name: CR_507

Address: 678 NE Oakland Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 3.4

D3_RampWidth: 5.2

S1_LandingSlope1: 1.6

S2_LandingSlope2: 4.8

S3_RampSlope: 8.4

S4_RampCrossSlope: 3.1

S5_WingSlope1: 7.7


S6_WingSlope2: 11.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_51





OBJECTID (Combination Ramp): 4

Name: CR_51

Address: 868 SE Parrott St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.8

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 2.4

S2_LandingSlope2: 1.0

S3_RampCrossSlope2: 1.0

S4_RampSlope2: 4.2

S5_RampCrossSlope3: 5.5

S6_RampSlope3: 19.9

S7_RampSlope1: 5.5

S8_RampCrossSlope1: 1.8

S9_WingSlope1: 6.6

S10_WingSlope2: 10.9

S11_CounterSlope: 5.0

GutterSlope: 1.3

LipHeight:

CR_185





OBJECTID (Perpendicular Ramp): 96

Name: CR_185

Address: 868 SE Parrott St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.5

S4_RampCrossSlope: 4.4

S5_WingSlope1: 17.9

S6_WingSlope2: 23.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_272





OBJECTID (Perpendicular Ramp): 183

Name: CR_272

Address: 868 SE Parrott St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.9

S3_RampSlope: 7.9

S4_RampCrossSlope: 0.1

S5_WingSlope1: 7.8

S6_WingSlope2: 9.3

S7_CounterSlope: 5.9

GutterSlope: 0.2

LipHeight:

CR_663





OBJECTID (Perpendicular Ramp): 575

Name: CR_663

Address: 622 W Pilger St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.9

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.1

S4_RampCrossSlope: 2.7

S5_WingSlope1: 5.9

S6_WingSlope2: 12.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_49





OBJECTID (Combination Ramp): 2

Name: CR_49

Address: 1268 SE Pine St

TruncDomes: True

Comments: North of intersection 10'

D1_LandingDim1: 5.9

D2_LandingDim2: 5.6

D3_RampWidth2: 5.6

D4_RampWidth3: 5.6

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 1.0

S3_RampCrossSlope2: 1.9

S4_RampSlope2: 4.2

S5_RampCrossSlope3: 1.9

S6_RampSlope3: 6.9

S7_RampSlope1: 5.1

S8_RampCrossSlope1: 0.2

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope: 9.5

GutterSlope:

LipHeight:

CR_55





OBJECTID (Combination Ramp): 8

Name: CR_55

Address: 1268 SE Pine St

TruncDomes: True

Comments:

D1_LandingDim1: 6.0

D2_LandingDim2: 6.0

D3_RampWidth2: 5.9

D4_RampWidth3: 6.1

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 0.8

S3_RampCrossSlope2: 2.4

S4_RampSlope2: 6.1

S5_RampCrossSlope3: 4.0

S6_RampSlope3: 5.1

S7_RampSlope1: 10.4

S8_RampCrossSlope1: 0.3

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope: 0.6

LipHeight:

CR_56





OBJECTID (Combination Ramp): 9

Name: CR_56

Address: 1466 SE Pine St

TruncDomes: True

Comments:

D1_LandingDim1: 6.0

D2_LandingDim2: 6.0

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 3.2

S3_RampCrossSlope2: 2.9

S4_RampSlope2: 3.4

S5_RampCrossSlope3: 4.3

S6_RampSlope3: 8.8

S7_RampSlope1: 9.1

S8_RampCrossSlope1: 1.8

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope: -2.0

GutterSlope: 0.5

LipHeight:

CR_17





OBJECTID (Bus Stop-Median): 17

Name: CR_17

Address: 847 SE Pine St

Comments:


D1_LandingDim1: 8.0

D2_LandingDim2: 5.0

S1_LandingSlope1: 2.6

S2_LandingSlope2: 4.0

CR_128





OBJECTID (Perpendicular Ramp): 39

Name: CR_128

Address: 752 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 0.7

S3_RampSlope: 9.3

S4_RampCrossSlope: 0.9

S5_WingSlope1: 10.0


S6_WingSlope2: 7.0

S7_CounterSlope: -2.1

GutterSlope: 0.2

LipHeight: 0.1

CR_129





OBJECTID (Perpendicular Ramp): 40

Name: CR_129

Address: 811 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.5

D3_RampWidth: 5.0

S1_LandingSlope1: 2.7

S2_LandingSlope2: 0.7

S3_RampSlope: 10.0

S4_RampCrossSlope: 0.2

S5_WingSlope1: 13.2

S6_WingSlope2: 7.8

S7_CounterSlope: 0.5

GutterSlope: 1.1

LipHeight: 0.1

CR_130





OBJECTID (Perpendicular Ramp): 41

Name: CR_130

Address: 908 SE Pine St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1: 5.0

D2_LandingDim2: 1.0

D3_RampWidth: 5.0

S1_LandingSlope1: 7.6

S2_LandingSlope2: 1.4

S3_RampSlope: 10.5

S4_RampCrossSlope:

S5_WingSlope1: 10.2


S6_WingSlope2: 5.5

S7_CounterSlope: 8.2

GutterSlope:

LipHeight:

CR_131





OBJECTID (Perpendicular Ramp): 42

Name: CR_131

Address: 866 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 1.0

D3_RampWidth: 3.8

S1_LandingSlope1: 3.4

S2_LandingSlope2: 0.6

S3_RampSlope: 8.6

S4_RampCrossSlope: 0.1

S5_WingSlope1: 11.5

S6_WingSlope2: 8.1

S7_CounterSlope: 6.0

GutterSlope: 1.9

LipHeight:

CR_132





OBJECTID (Perpendicular Ramp): 43

Name: CR_132

Address: 967 SE Pine St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1: 3.6

D2_LandingDim2: 1.0

D3_RampWidth: 3.6

S1_LandingSlope1: 3.4

S2_LandingSlope2: 0.6

S3_RampSlope: 5.4

S4_RampCrossSlope: 1.7

S5_WingSlope1: 11.8

S6_WingSlope2: 8.7

S7_CounterSlope: 7.9

GutterSlope: 2.5

LipHeight:

CR_133





OBJECTID (Perpendicular Ramp): 44

Name: CR_133

Address: 1006 SE Pine St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1: 3.5

D2_LandingDim2: 0.2

D3_RampWidth: 2.8

S1_LandingSlope1: 7.0

S2_LandingSlope2: 1.4

S3_RampSlope: 9.9

S4_RampCrossSlope: 0.4

S5_WingSlope1: 10.2


S6_WingSlope2: 10.2

S7_CounterSlope: 7.9

GutterSlope: 0.5

LipHeight:

CR_134





OBJECTID (Perpendicular Ramp): 45

Name: CR_134

Address: 1135 SE Pine St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1: 6.0

D2_LandingDim2: 1.6

D3_RampWidth: 6.0

S1_LandingSlope1: 2.7

S2_LandingSlope2: 1.1

S3_RampSlope: 7.8

S4_RampCrossSlope: 1.0

S5_WingSlope1: 8.6


S6_WingSlope2: 11.6

S7_CounterSlope: 10.7

GutterSlope:

LipHeight:

CR_135





OBJECTID (Perpendicular Ramp): 46

Name: CR_135

Address: 1208 SE Pine St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1: 1.0

D2_LandingDim2: 1.7

D3_RampWidth: 4.1

S1_LandingSlope1: 2.4

S2_LandingSlope2: 3.0

S3_RampSlope: 11.6

S4_RampCrossSlope: 1.3

S5_WingSlope1: 15.7


S6_WingSlope2: 13.5

S7_CounterSlope: 7.8

GutterSlope: 1.0

LipHeight:

CR_136





OBJECTID (Perpendicular Ramp): 47

Name: CR_136

Address: 1268 SE Pine St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1: 6.0

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1: 3.5

S2_LandingSlope2: 2.6

S3_RampSlope: 12.6

S4_RampCrossSlope: 0.3

S5_WingSlope1: 18.0

S6_WingSlope2: 17.8

S7_CounterSlope: 8.8

GutterSlope: 0.8

LipHeight:

CR_137





OBJECTID (Perpendicular Ramp): 48

Name: CR_137

Address: 1304 SE Pine St

TruncDomes:

Comments: Hydrant and property adjacent to landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.9

S4_RampCrossSlope: 1.3

S5_WingSlope1: 15.4


S6_WingSlope2: 14.0

S7_CounterSlope: 6.7

GutterSlope: 1.0

LipHeight: 0.3

CR_138





OBJECTID (Perpendicular Ramp): 49

Name: CR_138

Address: 1353 SE Pine St

TruncDomes:

Comments: Hydrant and property adjacent to landing

D1_LandingDim1: 2.9

D2_LandingDim2: 1.3

D3_RampWidth: 4.3

S1_LandingSlope1: 3.5

S2_LandingSlope2: 2.2

S3_RampSlope: 12.1

S4_RampCrossSlope: 2.2

S5_WingSlope1: 13.4


S6_WingSlope2: 11.5

S7_CounterSlope: 8.1

GutterSlope: 0.6

LipHeight: 0.3

CR_139





OBJECTID (Perpendicular Ramp): 50

Name: CR_139

Address: 1405 SE Pine St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.4

S4_RampCrossSlope: 0.1

S5_WingSlope1: 13.3

S6_WingSlope2: 11.0

S7_CounterSlope: 7.0

GutterSlope: 0.2

LipHeight:

CR_140





OBJECTID (Perpendicular Ramp): 51

Name: CR_140

Address: 1466 SE Pine St

TruncDomes: True

Comments: About 10' N of Burke. At crosswalk

D1_LandingDim1: 5.0

D2_LandingDim2: 5.9

D3_RampWidth: 5.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 2.1

S3_RampSlope: 10.9

S4_RampCrossSlope: 1.6

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope: 4.5

GutterSlope: 0.9

LipHeight: 0.1

CR_141





OBJECTID (Perpendicular Ramp): 52

Name: CR_141

Address: 1466 SE Pine St

TruncDomes:

Comments: Property adjacent to ramp

D1_LandingDim1: 6.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.5

S1_LandingSlope1: 1.5

S2_LandingSlope2: 0.8

S3_RampSlope: 6.5

S4_RampCrossSlope: 1.4

S5_WingSlope1: 8.1

S6_WingSlope2: 6.0

S7_CounterSlope: 3.3

GutterSlope: 1.6

LipHeight:

CR_142





OBJECTID (Perpendicular Ramp): 53

Name: CR_142

Address: 1508 SE Pine St

TruncDomes:

Comments: Property adjacent to landing. No landing area. Non compliant

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.1

S4_RampCrossSlope:

S5_WingSlope1: 15.6


S6_WingSlope2: 10.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_234





OBJECTID (Perpendicular Ramp): 145

Name: CR_234

Address: 752 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 4.6

D3_RampWidth: 4.8

S1_LandingSlope1: 2.2

S2_LandingSlope2: 1.9

S3_RampSlope: 9.7

S4_RampCrossSlope: 0.7

S5_WingSlope1: 10.0


S6_WingSlope2: 13.6

S7_CounterSlope: -5.1

GutterSlope: 2.9

LipHeight:

CR_235





OBJECTID (Perpendicular Ramp): 146

Name: CR_235

Address: 811 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 4.9

S1_LandingSlope1: 2.8

S2_LandingSlope2: 1.5

S3_RampSlope: 8.2

S4_RampCrossSlope: 0.1

S5_WingSlope1: 10.4


S6_WingSlope2: 11.3

S7_CounterSlope: 4.0

GutterSlope: 0.3

LipHeight:

CR_237





OBJECTID (Perpendicular Ramp): 148

Name: CR_237

Address: 866 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 15.6

S4_RampCrossSlope: 2.5

S5_WingSlope1: 10.6

S6_WingSlope2: 15.3

S7_CounterSlope: 7.2

GutterSlope: 2.7

LipHeight:

CR_238





OBJECTID (Perpendicular Ramp): 149

Name: CR_238

Address: 967 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 3.0

D2_LandingDim2: 2.4

D3_RampWidth: 3.0

S1_LandingSlope1: 2.8

S2_LandingSlope2: 4.5

S3_RampSlope: 15.8

S4_RampCrossSlope: 5.3

S5_WingSlope1: 7.3

S6_WingSlope2: 15.5

S7_CounterSlope: 4.2

GutterSlope: 5.1

LipHeight:

CR_239





OBJECTID (Perpendicular Ramp): 150

Name: CR_239

Address: 1003 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 3.5

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 3.0

S3_RampSlope: 8.2

S4_RampCrossSlope: 1.0

S5_WingSlope1: 12.6

S6_WingSlope2: 10.4

S7_CounterSlope: 2.2

GutterSlope: 0.4

LipHeight:

CR_240





OBJECTID (Perpendicular Ramp): 151

Name: CR_240

Address: 1135 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 3.3

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 15.4

S4_RampCrossSlope: 5.2

S5_WingSlope1: 10.0

S6_WingSlope2: 17.3

S7_CounterSlope: 0.4

GutterSlope: 6.6

LipHeight:

CR_241





OBJECTID (Perpendicular Ramp): 152

Name: CR_241

Address: 1207 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 3.0

D2_LandingDim2: 3.0

D3_RampWidth: 3.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 4.3

S3_RampSlope: 13.0

S4_RampCrossSlope: 2.2

S5_WingSlope1: 13.0


S6_WingSlope2: 10.8

S7_CounterSlope: 0.3

GutterSlope: 2.8

LipHeight:

CR_242





OBJECTID (Perpendicular Ramp): 153

Name: CR_242

Address: 1268 SE Pine St

TruncDomes:

Comments: Power pole at back of walk

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.5

S4_RampCrossSlope: 2.9

S5_WingSlope1: 9.2


S6_WingSlope2: 11.7

S7_CounterSlope: 2.4

GutterSlope: 2.4

LipHeight:

CR_243





OBJECTID (Perpendicular Ramp): 154

Name: CR_243

Address: 1303 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 3.5

S1_LandingSlope1: 2.6

S2_LandingSlope2: 1.3

S3_RampSlope: 13.0

S4_RampCrossSlope: 1.1

S5_WingSlope1: 10.6


S6_WingSlope2: 14.6

S7_CounterSlope: 2.3

GutterSlope: 0.2

LipHeight:

CR_244





OBJECTID (Perpendicular Ramp): 155

Name: CR_244

Address: 1353 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 5.3

S3_RampSlope: 10.9

S4_RampCrossSlope: 5.3

S5_WingSlope1: 7.6

S6_WingSlope2: 13.5

S7_CounterSlope: -0.4

GutterSlope: 7.9

LipHeight:

CR_245





OBJECTID (Perpendicular Ramp): 156

Name: CR_245

Address: 1405 SE Pine St

TruncDomes:

Comments: 5' between sign pole and fence

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 5.0

S3_RampSlope: 3.6

S4_RampCrossSlope: 0.4

S5_WingSlope1: 12.4


S6_WingSlope2: 6.5

S7_CounterSlope: 2.0

GutterSlope: 1.6

LipHeight:

CR_246





OBJECTID (Perpendicular Ramp): 157

Name: CR_246

Address: 1466 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 6.0

D2_LandingDim2: 3.4

D3_RampWidth: 5.0

S1_LandingSlope1: 3.2

S2_LandingSlope2: 5.9

S3_RampSlope: 14.1

S4_RampCrossSlope: 3.7

S5_WingSlope1: 10.5

S6_WingSlope2: 15.5

S7_CounterSlope: 1.3

GutterSlope: 4.1

LipHeight:

CR_247





OBJECTID (Perpendicular Ramp): 158

Name: CR_247

Address: 1507 SE Pine St

TruncDomes:

Comments: Catch basin at bottom of ramp

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 2.1

S3_RampSlope: 13.9

S4_RampCrossSlope: 2.3

S5_WingSlope1: 16.0

S6_WingSlope2: 13.1

S7_CounterSlope: 3.5

GutterSlope: 3.6

LipHeight:

CR_248





OBJECTID (Perpendicular Ramp): 159

Name: CR_248

Address: 1568 SE Pine St

TruncDomes:

Comments:

D1_LandingDim1: 6.0

D2_LandingDim2: 6.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 4.3

S3_RampSlope: 11.6

S4_RampCrossSlope:

S5_WingSlope1: 12.1

S6_WingSlope2: 9.9

S7_CounterSlope: 0.8

GutterSlope: 1.7

LipHeight:

CR_759





OBJECTID (Parallel Ramp): 36

Name: CR_759

Address: 1137 Plateau Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.4

D2_LandingDim2: 6.5

S1_LandingSlope1: 0.6

S2_LandingSlope2: 0.1

S3_RampCrossSlope1: 2.4

S4_RampSlope1: 6.4

S5_RampCrossSlope2:

S6_RampSlope2: 4.1

S7_CounterSlope: 3.0

GutterSlope: 1.0

LipHeight:

CR_771





OBJECTID (Parallel Ramp): 48

Name: CR_771

Address: 1136 NW Plateau Dr

TruncDomes:

Comments:

D1_LandingDim1: 6.3

D2_LandingDim2: 6.6

S1_LandingSlope1: 0.4

S2_LandingSlope2: 0.9

S3_RampCrossSlope1: 0.8

S4_RampSlope1: 4.7

S5_RampCrossSlope2: 0.7

S6_RampSlope2: 7.0

S7_CounterSlope: 3.0

GutterSlope: 0.7

LipHeight:

CR_772





OBJECTID (Parallel Ramp): 49

Name: CR_772

Address: 513 Plateau Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.8

D2_LandingDim2: 6.5

S1_LandingSlope1: 2.1

S2_LandingSlope2: 0.7

S3_RampCrossSlope1: 1.8

S4_RampSlope1: 8.8

S5_RampCrossSlope2: 2.3

S6_RampSlope2: 6.5

S7_CounterSlope: 3.8

GutterSlope: 0.8

LipHeight:

CR_773





OBJECTID (Parallel Ramp): 50

Name: CR_773

Address: 513 Plateau Dr

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 6.2

S1_LandingSlope1: 1.7

S2_LandingSlope2: 1.9

S3_RampCrossSlope1: 0.4

S4_RampSlope1: 3.8

S5_RampCrossSlope2: 0.4

S6_RampSlope2: 6.9

S7_CounterSlope: 1.3

GutterSlope: 1.4

LipHeight:

CR_878






OBJECTID (Unclassified Ramp): 53 **Address:** 1132 Plateau Dr

Name: CR_878

CR_66





OBJECTID (Combination Ramp): 19

Name: CR_66

Address: 1531 NW Primrose Ln

TruncDomes:

Comments:

D1_LandingDim1: 2.9

D2_LandingDim2: 3.9

D3_RampWidth2: 5.7

D4_RampWidth3: 6.0

D5_RampWidth1: 4.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 3.5

S3_RampCrossSlope2: 2.2

S4_RampSlope2: 2.1

S5_RampCrossSlope3: 1.2

S6_RampSlope3: 6.0

S7_RampSlope1: 9.9

S8_RampCrossSlope1: 0.8

S9_WingSlope1: 4.3


S10_WingSlope2: 6.5

S11_CounterSlope: 7.6

GutterSlope: 1.4

LipHeight:

CR_871






OBJECTID (Unclassified Ramp): 46 **Address:** 1522 NW Randall Ct

Name: CR_871

CR_342





OBJECTID (Perpendicular Ramp): 254

Name: CR_342

Address: 1523 NW Randall Ct

TruncDomes: True

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 3.5

D3_RampWidth: 3.9

S1_LandingSlope1: 3.2

S2_LandingSlope2: 5.9

S3_RampSlope: 5.9

S4_RampCrossSlope: 5.7

S5_WingSlope1: 13.2

S6_WingSlope2: 2.2

S7_CounterSlope: 11.9

GutterSlope: 6.5

LipHeight:

CR_343





OBJECTID (Perpendicular Ramp): 255

Name: CR_343

Address: 1522 NW Randall Ct

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 3.9

S1_LandingSlope1: 7.9

S2_LandingSlope2: 1.4

S3_RampSlope: 10.3

S4_RampCrossSlope: 1.2

S5_WingSlope1: 7.6

S6_WingSlope2: 9.5

S7_CounterSlope: 8.9

GutterSlope: 2.6

LipHeight:

CR_427





OBJECTID (Perpendicular Ramp): 339

Name: CR_427

Address: 1522 NW Randall Ct

TruncDomes: True

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 4.0

D3_RampWidth: 3.8

S1_LandingSlope1: 2.4

S2_LandingSlope2: 3.6

S3_RampSlope: 11.6

S4_RampCrossSlope: 2.2

S5_WingSlope1: 7.0


S6_WingSlope2: 12.3

S7_CounterSlope: 9.6

GutterSlope: 2.2

LipHeight:

CR_384





OBJECTID (Perpendicular Ramp): 296

Name: CR_384

Address: NW Renann Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 4.8

S4_RampCrossSlope: 1.4

S5_WingSlope1: 7.3


S6_WingSlope2: 3.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_471





OBJECTID (Perpendicular Ramp): 383

Name: CR_471

Address: NW Renann Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.0

S4_RampCrossSlope: 5.5

S5_WingSlope1: 5.3

S6_WingSlope2: 5.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_143





OBJECTID (Perpendicular Ramp): 54

Name: CR_143

Address: 553 SE Rice St

TruncDomes:

Comments: No landing area. Non compliant.

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 18.7

S4_RampCrossSlope:

S5_WingSlope1: 22.2


S6_WingSlope2: 27.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_177





OBJECTID (Perpendicular Ramp): 88

Name: CR_177

Address: 1129 SE Rice Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 4.2

D3_RampWidth: 4.5

S1_LandingSlope1: 0.6

S2_LandingSlope2: 1.7

S3_RampSlope: 2.3

S4_RampCrossSlope: 1.7

S5_WingSlope1: 1.6

S6_WingSlope2: 3.0

S7_CounterSlope: 11.8

GutterSlope: 1.9

LipHeight:

CR_249





OBJECTID (Perpendicular Ramp): 160

Name: CR_249

Address: 629 SE Rice St

TruncDomes:

Comments: No landing, non-compliant

D1_LandingDim1: 4.0

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.9

S4_RampCrossSlope: 2.4

S5_WingSlope1: 15.4

S6_WingSlope2: 11.7

S7_CounterSlope: 3.2

GutterSlope: 2.2

LipHeight:

CR_250





OBJECTID (Perpendicular Ramp): 161

Name: CR_250

Address: 553 SE Rice St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.1

S4_RampCrossSlope: 1.1

S5_WingSlope1: 12.6

S6_WingSlope2: 6.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_854





OBJECTID (Unclassified Ramp): 29 **Address:** 643 NE Rifle Range St

Name: CR_854

CR_420





OBJECTID (Perpendicular Ramp): 332

Name: CR_420

Address: 1749 NW Riverview Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.7

S4_RampCrossSlope: 2.1

S5_WingSlope1: 17.4

S6_WingSlope2: 14.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_539





OBJECTID (Perpendicular Ramp): 451

Name: CR_539

Address: 1401 NE Rocky Ridge Dr

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 5.6

S4_RampCrossSlope: 3.2

S5_WingSlope1: 3.7

S6_WingSlope2: 11.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_781





OBJECTID (Parallel Ramp): 58

Name: CR_781

Address: 660 NE Roseland Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.8

S3_RampCrossSlope1: 1.3

S4_RampSlope1: 7.9

S5_RampCrossSlope2: 1.5

S6_RampSlope2: 6.2

S7_CounterSlope: 8.7

GutterSlope: 0.8

LipHeight:

CR_509





OBJECTID (Perpendicular Ramp): 421

Name: CR_509

Address: 660 NE Roseland Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.8

D3_RampWidth: 5.0

S1_LandingSlope1: 2.6

S2_LandingSlope2: 10.2

S3_RampSlope: 6.6

S4_RampCrossSlope: 9.6

S5_WingSlope1: 0.2

S6_WingSlope2: 14.8

S7_CounterSlope: 9.7

GutterSlope: 7.6

LipHeight:

CR_552





OBJECTID (Perpendicular Ramp): 464

Name: CR_552

Address: 660 NE Roseland Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 5.1

D3_RampWidth: 5.1

S1_LandingSlope1: 2.5

S2_LandingSlope2: 5.1

S3_RampSlope: 6.0

S4_RampCrossSlope: 4.2

S5_WingSlope1: 9.5

S6_WingSlope2: 3.3

S7_CounterSlope: 8.9

GutterSlope: 3.8

LipHeight:

CR_76





OBJECTID (Combination Ramp): 29

Name: CR_76

Address: 1191 NE Ross Ave

TruncDomes:

Comments:

D1_LandingDim1: 3.6

D2_LandingDim2: 4.0

D3_RampWidth2: 5.0

D4_RampWidth3: 6.0

D5_RampWidth1: 4.0

S1_LandingSlope1: 0.7

S2_LandingSlope2: 2.3

S3_RampCrossSlope2: 2.6

S4_RampSlope2: 9.7

S5_RampCrossSlope3: 0.3

S6_RampSlope3: 1.0

S7_RampSlope1: 11.1

S8_RampCrossSlope1: 2.8

S9_WingSlope1: 11.2


S10_WingSlope2: 2.0

S11_CounterSlope: 5.5

GutterSlope: 3.4

LipHeight:

CR_795





OBJECTID (Parallel Ramp): 72

Name: CR_795

Address: 417 NE Russell Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.4

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 1.3

S3_RampCrossSlope1: 1.9

S4_RampSlope1: 7.2

S5_RampCrossSlope2: 0.6

S6_RampSlope2: 5.8

S7_CounterSlope: 3.6

GutterSlope: 1.4

LipHeight:

CR_813





OBJECTID (Parallel Ramp): 90

Name: CR_813

Address: 417 NE Russell Ave

TruncDomes: True

Comments:

D1_LandingDim1: 5.3

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 1.5

S3_RampCrossSlope1: 0.7

S4_RampSlope1: 9.1

S5_RampCrossSlope2: 0.3

S6_RampSlope2: 7.6

S7_CounterSlope: -6.4

GutterSlope: 1.0

LipHeight:

CR_62





OBJECTID (Combination Ramp): 15

Name: CR_62

Address: 102 Shadow Ranch Ln

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth2: 5.8

D4_RampWidth3: 6.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 0.2

S3_RampCrossSlope2: 3.5

S4_RampSlope2: 4.0

S5_RampCrossSlope3: 0.4

S6_RampSlope3: 1.2

S7_RampSlope1: 9.1

S8_RampCrossSlope1: 0.1

S9_WingSlope1: 10.7

S10_WingSlope2: 8.2

S11_CounterSlope: 6.5

GutterSlope: 0.6

LipHeight:

CR_63





OBJECTID (Combination Ramp): 16

Name: CR_63

Address: 102 Shadow Ranch Ln

TruncDomes: True

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 4.1

D3_RampWidth2: 6.3

D4_RampWidth3: 5.8

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 2.8

S3_RampCrossSlope2: 1.7

S4_RampSlope2: 3.4

S5_RampCrossSlope3: 3.7

S6_RampSlope3: 8.0

S7_RampSlope1: 7.2

S8_RampCrossSlope1: 2.3

S9_WingSlope1: 6.4

S10_WingSlope2: 9.4

S11_CounterSlope: 5.4

GutterSlope: 1.7

LipHeight:

CR_70





OBJECTID (Combination Ramp): 23

Name: CR_70

Address: 102 Shadow Ranch Ln

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.5

D3_RampWidth2: 3.5

D4_RampWidth3: 3.5

D5_RampWidth1: 5.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 0.7

S3_RampCrossSlope2: 2.3

S4_RampSlope2: 7.7

S5_RampCrossSlope3: 1.8

S6_RampSlope3: 3.3

S7_RampSlope1: 10.2

S8_RampCrossSlope1: 0.4

S9_WingSlope1: 12.1

S10_WingSlope2: 10.4

S11_CounterSlope: 11.5

GutterSlope: 0.2

LipHeight:

CR_485





OBJECTID (Perpendicular Ramp): 397

Name: CR_485

Address: 102 Shadow Ranch Ln

TruncDomes:

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 5.0

D3_RampWidth: 5.1

S1_LandingSlope1: 1.7

S2_LandingSlope2: 0.7

S3_RampSlope: 9.7

S4_RampCrossSlope: 1.3

S5_WingSlope1: 14.5

S6_WingSlope2: 8.9

S7_CounterSlope: 8.7

GutterSlope: 1.2

LipHeight:

CR_646





OBJECTID (Perpendicular Ramp): 558

Name: CR_646

Address: 846 NE Shambrook Ave

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 7.4

S3_RampSlope: 7.3

S4_RampCrossSlope: 1.8

S5_WingSlope1: 10.9

S6_WingSlope2: 10.9

S7_CounterSlope: 11.1

GutterSlope: 3.2

LipHeight:

CR_647





OBJECTID (Perpendicular Ramp): 559

Name: CR_647

Address: 846 NE Shambrook Ave

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.7

S4_RampCrossSlope: 11.0

S5_WingSlope1: 27.9


S6_WingSlope2: 3.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_270





OBJECTID (Perpendicular Ramp): 181

Name: CR_270

Address: 863 SE Sheridan St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.4

S4_RampCrossSlope: 1.7

S5_WingSlope1: 16.9


S6_WingSlope2: 14.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_271





OBJECTID (Perpendicular Ramp): 182

Name: CR_271

Address: 863 SE Sheridan St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth: 8.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 1.0

S3_RampSlope: 8.3

S4_RampCrossSlope: 0.8

S5_WingSlope1: 7.2

S6_WingSlope2: 6.2

S7_CounterSlope: 8.5

GutterSlope: 0.1

LipHeight:

CR_725





OBJECTID (Parallel Ramp): 2

Name: CR_725

Address: 404 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.7

D2_LandingDim2: 8.7

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.0

S3_RampCrossSlope1: 0.5

S4_RampSlope1: 3.6

S5_RampCrossSlope2: 0.4

S6_RampSlope2: 4.1

S7_CounterSlope: 0.5

GutterSlope: 0.4

LipHeight:

CR_50





OBJECTID (Combination Ramp): 3

Name: CR_50

Address: 970 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.7

D2_LandingDim2: 4.0

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1: 4.7

S1_LandingSlope1: 1.9

S2_LandingSlope2: 2.3

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1: 5.1

S8_RampCrossSlope1: 2.8

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_57





OBJECTID (Combination Ramp): 10

Name: CR_57

Address: 1011 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 3.3

D2_LandingDim2: 3.5

D3_RampWidth2: 5.6

D4_RampWidth3: 6.6

D5_RampWidth1: 4.8

S1_LandingSlope1: 0.2

S2_LandingSlope2: 1.4

S3_RampCrossSlope2: 0.2

S4_RampSlope2: 6.1

S5_RampCrossSlope3: 0.2

S6_RampSlope3: 6.7

S7_RampSlope1: 10.9

S8_RampCrossSlope1: 2.8

S9_WingSlope1: 9.2

S10_WingSlope2: 9.0

S11_CounterSlope: 5.7

GutterSlope: 1.7

LipHeight:

CR_734





OBJECTID (Parallel Ramp): 11

Name: CR_734

Address: 1209 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 5.8

S1_LandingSlope1: 1.4

S2_LandingSlope2: 2.6

S3_RampCrossSlope1: 2.3

S4_RampSlope1: 16.3

S5_RampCrossSlope2: 4.2

S6_RampSlope2: 11.7

S7_CounterSlope: -1.6

GutterSlope:

LipHeight:

CR_735





OBJECTID (Parallel Ramp): 12

Name: CR_735

Address: 1118 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.7

D2_LandingDim2: 5.5

S1_LandingSlope1: 2.2

S2_LandingSlope2: 0.7

S3_RampCrossSlope1: 4.5

S4_RampSlope1: 13.6

S5_RampCrossSlope2: 0.6

S6_RampSlope2: 8.8

S7_CounterSlope: -1.2

GutterSlope: 0.9

LipHeight: 1.0

CR_736





OBJECTID (Parallel Ramp): 13

Name: CR_736

Address: 1731 NE Stephens St

TruncDomes: True

Comments: Electric box in ramp with lip > .25

D1_LandingDim1: 5.2

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 2.2

S3_RampCrossSlope1: 2.1

S4_RampSlope1: 6.7

S5_RampCrossSlope2: 1.2

S6_RampSlope2: 3.8

S7_CounterSlope: 3.4

GutterSlope: 1.7

LipHeight: 0.3

CR_737





OBJECTID (Parallel Ramp): 14

Name: CR_737

Address: 1731 NE Stephens St

TruncDomes: True

Comments: Poles in wings

D1_LandingDim1: 5.2

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.7

S2_LandingSlope2: 2.3

S3_RampCrossSlope1: 2.5

S4_RampSlope1: 5.3

S5_RampCrossSlope2: 2.0


S6_RampSlope2: 7.0

S7_CounterSlope: 0.5

GutterSlope:

LipHeight:

CR_738





OBJECTID (Parallel Ramp): 15

Name: CR_738

Address: 404 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.4

D2_LandingDim2: 7.0

S1_LandingSlope1:

S2_LandingSlope2: 0.1

S3_RampCrossSlope1: 1.0

S4_RampSlope1: 2.1

S5_RampCrossSlope2: 0.1

S6_RampSlope2: 3.5

S7_CounterSlope: -1.2

GutterSlope: 0.4

LipHeight:

CR_855





OBJECTID (Unclassified Ramp): 30 **Address:** 1627 SE Stephens St

Name: CR_855

CR_84





OBJECTID (Combination Ramp): 37

Name: CR_84

Address: 1200 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 4.1

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 5.1

S1_LandingSlope1: 1.1

S2_LandingSlope2: 1.5

S3_RampCrossSlope2: 0.9

S4_RampSlope2: 6.6

S5_RampCrossSlope3: 1.9

S6_RampSlope3: 1.2

S7_RampSlope1: 4.9

S8_RampCrossSlope1: 0.1

S9_WingSlope1: 4.5

S10_WingSlope2: 7.6

S11_CounterSlope: 1.6

GutterSlope: 0.2

LipHeight:

CR_38





OBJECTID (Bus Stop-Median): 38

Name: CR_38

Address: 3050 NE Stephens St

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 12.0

S1_LandingSlope1: 3.5

S2_LandingSlope2: 2.7

CR_85





OBJECTID (Combination Ramp): 38

Name: CR_85

Address: 1183 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 2.2

S3_RampCrossSlope2: 0.4

S4_RampSlope2: 9.0

S5_RampCrossSlope3: 1.2

S6_RampSlope3: 10.2

S7_RampSlope1: 0.8

S8_RampCrossSlope1: 1.6

S9_WingSlope1: 6.9

S10_WingSlope2: 9.4

S11_CounterSlope: 3.6

GutterSlope: 2.7

LipHeight:

CR_39





OBJECTID (Bus Stop-Median): 39

Name: CR_39

Address: 2360 NE Stephens St

Comments:

D1_LandingDim1: 9.0

D2_LandingDim2: 10.0

S1_LandingSlope1: 3.7

S2_LandingSlope2: 1.0

CR_86





OBJECTID (Combination Ramp): 39

Name: CR_86

Address: 1183 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 0.2

S3_RampCrossSlope2: 3.4

S4_RampSlope2: 5.8

S5_RampCrossSlope3: 1.8

S6_RampSlope3: 5.3

S7_RampSlope1: 8.9

S8_RampCrossSlope1: 0.2

S9_WingSlope1: 9.5


S10_WingSlope2: 0.6

S11_CounterSlope: 5.1

GutterSlope:

LipHeight:

CR_864






OBJECTID (Unclassified Ramp): 39 **Address:** 3329 NE Stephens St

Name: CR_864

CR_40





OBJECTID (Bus Stop-Median): 40

Name: CR_40

Address: 2388 NE Stephens St

Comments:

D1_LandingDim1: 7.0

D2_LandingDim2: 12.0

S1_LandingSlope1: 4.3

S2_LandingSlope2: 1.0

CR_87





OBJECTID (Combination Ramp): 40

Name: CR_87

Address: 1053 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 4.1

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 3.8

S1_LandingSlope1: 1.2

S2_LandingSlope2: 7.9

S3_RampCrossSlope2: 3.6

S4_RampSlope2: 0.9

S5_RampCrossSlope3: 1.6

S6_RampSlope3: 13.4

S7_RampSlope1: 4.6

S8_RampCrossSlope1: 5.8

S9_WingSlope1: 1.8

S10_WingSlope2: 11.3

S11_CounterSlope: 0.9

GutterSlope: 7.9

LipHeight:

CR_865





OBJECTID (Unclassified Ramp): 40 **Address:** 3329 NE Stephens St

Name: CR_865

CR_88





OBJECTID (Combination Ramp): 41

Name: CR_88

Address: 1062 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 3.8

D2_LandingDim2: 4.0

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 4.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 4.2

S3_RampCrossSlope2: 1.0

S4_RampSlope2: 1.9

S5_RampCrossSlope3: 3.8

S6_RampSlope3: 10.5

S7_RampSlope1: 5.2

S8_RampCrossSlope1: 2.3

S9_WingSlope1: 3.0


S10_WingSlope2: 12.1

S11_CounterSlope: 4.4

GutterSlope: 3.5

LipHeight:

CR_42





OBJECTID (Bus Stop-Median): 42

Name: CR_42

Address: 3050 NE Stephens St

Comments:


D1_LandingDim1: 4.5

D2_LandingDim2: 8.0

S1_LandingSlope1: 3.3

S2_LandingSlope2: 1.6

CR_45





OBJECTID (Bus Stop-Median): 45

Name: CR_45

Address: 1227 NE Stephens St

Comments:


D1_LandingDim1: 11.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 3.9

CR_879





OBJECTID (Unclassified Ramp): 54 **Address:** 3357 NE Stephens St

Name: CR_879

CR_144





OBJECTID (Perpendicular Ramp): 55

Name: CR_144

Address: 1627 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 10.9

D2_LandingDim2: 6.0

D3_RampWidth: 7.9

S1_LandingSlope1: 1.8

S2_LandingSlope2: 2.9

S3_RampSlope: 6.4

S4_RampCrossSlope: 2.7

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope: 8.8

GutterSlope: 2.2

LipHeight: 0.5

CR_880





OBJECTID (Unclassified Ramp): 55 **Address:** 3357 NE Stephens St

Name: CR_880

CR_145





OBJECTID (Perpendicular Ramp): 56

Name: CR_145

Address: 1615 SE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 3.1

S3_RampSlope: 8.6

S4_RampCrossSlope: 2.5

S5_WingSlope1: 13.8


S6_WingSlope2: 9.3

S7_CounterSlope: 6.3

GutterSlope: 3.1

LipHeight:

CR_881





OBJECTID (Unclassified Ramp): 56 **Address:** 3357 NE Stephens St

Name: CR_881

CR_146





OBJECTID (Perpendicular Ramp): 57

Name: CR_146

Address: 1604 SE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.3

D2_LandingDim2: 3.9

D3_RampWidth: 5.3

S1_LandingSlope1: 1.5

S2_LandingSlope2: 2.4

S3_RampSlope: 9.2

S4_RampCrossSlope: 2.8

S5_WingSlope1: 13.4

S6_WingSlope2: 10.6

S7_CounterSlope: 3.9

GutterSlope: 3.0

LipHeight:

CR_147





OBJECTID (Perpendicular Ramp): 58

Name: CR_147

Address: 1501 SE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 4.1

D3_RampWidth: 5.2

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.7

S3_RampSlope: 8.4

S4_RampCrossSlope: 0.2

S5_WingSlope1: 7.6


S6_WingSlope2: 8.3

S7_CounterSlope: 8.3

GutterSlope: 0.6

LipHeight:

CR_148





OBJECTID (Perpendicular Ramp): 59

Name: CR_148

Address: 1502 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 6.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.7

S2_LandingSlope2: 1.3

S3_RampSlope: 8.5

S4_RampCrossSlope: 2.1

S5_WingSlope1: 12.6

S6_WingSlope2: 10.7

S7_CounterSlope: 8.1

GutterSlope: 1.2

LipHeight: 0.6

CR_149





OBJECTID (Perpendicular Ramp): 60

Name: CR_149

Address: 1457 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 9.1

D2_LandingDim2: 6.5

D3_RampWidth: 8.0

S1_LandingSlope1: 2.1

S2_LandingSlope2: 0.6

S3_RampSlope: 5.8

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope: 6.8

GutterSlope: 1.3

LipHeight: 0.5

CR_150





OBJECTID (Perpendicular Ramp): 61

Name: CR_150

Address: 1405 SE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.1

S2_LandingSlope2: 5.0

S3_RampSlope: 7.8

S4_RampCrossSlope: 4.2

S5_WingSlope1: 6.1

S6_WingSlope2: 9.6

S7_CounterSlope: 6.8

GutterSlope: 4.0

LipHeight:

CR_151





OBJECTID (Perpendicular Ramp): 62

Name: CR_151

Address: 1410 SE Stephens St

TruncDomes:

Comments: Property adjacent to landing

D1_LandingDim1: 4.6

D2_LandingDim2: 3.7

D3_RampWidth: 4.6

S1_LandingSlope1: 2.5

S2_LandingSlope2: 2.2

S3_RampSlope: 8.5

S4_RampCrossSlope: 1.4

S5_WingSlope1: 10.6

S6_WingSlope2: 7.6

S7_CounterSlope: 3.8

GutterSlope: 1.6

LipHeight:

CR_152





OBJECTID (Perpendicular Ramp): 63

Name: CR_152

Address: 1316 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 8.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.1

S2_LandingSlope2: 2.9

S3_RampSlope: 9.2

S4_RampCrossSlope: 3.4

S5_WingSlope1: 11.2

S6_WingSlope2: 10.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_888





OBJECTID (Unclassified Ramp): 63 **Address:** 1067 NE Stephens St

Name: CR_888

CR_153





OBJECTID (Perpendicular Ramp): 64

Name: CR_153

Address: 1316 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 2.6

S3_RampSlope: 7.6

S4_RampCrossSlope: 4.1

S5_WingSlope1: 13.7

S6_WingSlope2: 14.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_889





OBJECTID (Unclassified Ramp): 64 **Address:** 1107 NE Stephens St

Name: CR_889

CR_154





OBJECTID (Perpendicular Ramp): 65

Name: CR_154

Address: 1316 SE Stephens St

TruncDomes: True

Comments: About 10' north of Haynes at crossing

D1_LandingDim1: 7.0

D2_LandingDim2: 6.5

D3_RampWidth: 6.0

S1_LandingSlope1: 3.9

S2_LandingSlope2: 3.4

S3_RampSlope: 4.4

S4_RampCrossSlope: 2.9

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_155





OBJECTID (Perpendicular Ramp): 66

Name: CR_155

Address: 1209 SE Stephens St

TruncDomes:

Comments: No landing under 2%

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 5.1

S4_RampCrossSlope: 7.2

S5_WingSlope1: 4.6

S6_WingSlope2: 15.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_156





OBJECTID (Perpendicular Ramp): 67

Name: CR_156

Address: 1117 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 8.0

D2_LandingDim2: 6.0

D3_RampWidth: 8.0

S1_LandingSlope1: 3.7

S2_LandingSlope2: 1.2

S3_RampSlope: 3.8

S4_RampCrossSlope: 1.2

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_157





OBJECTID (Perpendicular Ramp): 68

Name: CR_157

Address: 1110 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 3.1

S2_LandingSlope2: 5.3

S3_RampSlope: 7.9

S4_RampCrossSlope: 4.4

S5_WingSlope1: 6.1

S6_WingSlope2: 14.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_158





OBJECTID (Perpendicular Ramp): 69

Name: CR_158

Address: 909 SE Stephens St

TruncDomes: True

Comments: Sign and parking lot in landing

D1_LandingDim1: 4.0

D2_LandingDim2: 2.2

D3_RampWidth: 4.0

S1_LandingSlope1: 4.1

S2_LandingSlope2: 1.0

S3_RampSlope: 11.4

S4_RampCrossSlope: 0.8

S5_WingSlope1: 11.6

S6_WingSlope2: 10.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_159





OBJECTID (Perpendicular Ramp): 70

Name: CR_159

Address: 853 SE Stephens St

TruncDomes:

Comments: Landing area in adjacent property lot

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 3.0

S1_LandingSlope1: 0.2

S2_LandingSlope2: 4.0

S3_RampSlope: 12.6

S4_RampCrossSlope: 3.5

S5_WingSlope1: 12.5

S6_WingSlope2: 14.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_160





OBJECTID (Perpendicular Ramp): 71

Name: CR_160

Address: 805 SE Stephens St

TruncDomes:

Comments: Building in landing area

D1_LandingDim1: 5.0

D2_LandingDim2: 3.8

D3_RampWidth: 5.0

S1_LandingSlope1: 3.3

S2_LandingSlope2: 1.1

S3_RampSlope: 10.0

S4_RampCrossSlope: 0.7

S5_WingSlope1: 9.7

S6_WingSlope2: 9.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_794





OBJECTID (Parallel Ramp): 71

Name: CR_794

Address: 3030 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.9

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 2.0

S3_RampCrossSlope1:

S4_RampSlope1:

S5_RampCrossSlope2: 1.5


S6_RampSlope2: 8.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_161





OBJECTID (Perpendicular Ramp): 72

Name: CR_161

Address: 761 SE Stephens St

TruncDomes:

Comments: Ped signal in landing area

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 4.9

S1_LandingSlope1: 2.5

S2_LandingSlope2:

S3_RampSlope: 7.7

S4_RampCrossSlope: 0.6

S5_WingSlope1: 5.1

S6_WingSlope2: 10.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_796





OBJECTID (Parallel Ramp): 73

Name: CR_796

Address: 2360 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 9.0

D2_LandingDim2: 4.4

S1_LandingSlope1: 1.1

S2_LandingSlope2: 0.8

S3_RampCrossSlope1: 2.1

S4_RampSlope1: 6.6

S5_RampCrossSlope2: 2.4

S6_RampSlope2: 6.4

S7_CounterSlope: 1.0

GutterSlope: 0.7

LipHeight:

CR_797





OBJECTID (Parallel Ramp): 74

Name: CR_797

Address: 2371 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 9.0

D2_LandingDim2: 4.5

S1_LandingSlope1: 0.9

S2_LandingSlope2: 0.4

S3_RampCrossSlope1: 1.3

S4_RampSlope1: 7.5

S5_RampCrossSlope2: 0.1

S6_RampSlope2: 7.3

S7_CounterSlope: 1.4

GutterSlope: 0.4

LipHeight:

CR_798





OBJECTID (Parallel Ramp): 75

Name: CR_798

Address: 2340 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.7

S1_LandingSlope1: 4.1

S2_LandingSlope2: 5.0

S3_RampCrossSlope1: 7.2

S4_RampSlope1: 8.8

S5_RampCrossSlope2: 3.0

S6_RampSlope2: 14.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_802





OBJECTID (Parallel Ramp): 79

Name: CR_802

Address: 2198 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 1.5

S3_RampCrossSlope1: 1.3

S4_RampSlope1: 6.9

S5_RampCrossSlope2: 1.7

S6_RampSlope2: 4.8

S7_CounterSlope: 5.6

GutterSlope: 2.3

LipHeight:

CR_803





OBJECTID (Parallel Ramp): 80

Name: CR_803

Address: 2165 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.1

S2_LandingSlope2: 0.7

S3_RampCrossSlope1: 0.1

S4_RampSlope1: 0.5

S5_RampCrossSlope2: 0.8

S6_RampSlope2: 12.7

S7_CounterSlope: -4.6

GutterSlope: 2.6

LipHeight:

CR_905





OBJECTID (Unclassified Ramp): 80 **Address:** 3030 NE Stephens St

Name: CR_905

CR_804





OBJECTID (Parallel Ramp): 81

Name: CR_804

Address: 2130 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 2.6

S3_RampCrossSlope1: 3.2

S4_RampSlope1: 3.9

S5_RampCrossSlope2: 0.3


S6_RampSlope2: 8.5

S7_CounterSlope: -2.7

GutterSlope: 2.3

LipHeight:

CR_805





OBJECTID (Parallel Ramp): 82

Name: CR_805

Address: 1970 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 1.4

S3_RampCrossSlope1: 1.1

S4_RampSlope1: 11.3

S5_RampCrossSlope2: 1.1


S6_RampSlope2: 0.9

S7_CounterSlope: 2.7

GutterSlope: 1.3

LipHeight:

CR_806





OBJECTID (Parallel Ramp): 83

Name: CR_806

Address: 2010 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 1.3

S3_RampCrossSlope1: 2.1

S4_RampSlope1: 8.0

S5_RampCrossSlope2: 1.1

S6_RampSlope2: 7.3

S7_CounterSlope: -7.6

GutterSlope: 1.9

LipHeight:

CR_807





OBJECTID (Parallel Ramp): 84

Name: CR_807

Address: 1771 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 0.5

S3_RampCrossSlope1: 1.6

S4_RampSlope1: 2.5

S5_RampCrossSlope2: 2.3


S6_RampSlope2: 5.7

S7_CounterSlope: 4.2

GutterSlope: 3.5

LipHeight:

CR_808





OBJECTID (Parallel Ramp): 85

Name: CR_808

Address: 1771 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 4.2

S2_LandingSlope2: 1.3

S3_RampCrossSlope1: 2.5

S4_RampSlope1: 8.6

S5_RampCrossSlope2: 1.6

S6_RampSlope2: 0.8

S7_CounterSlope: 0.2

GutterSlope: 3.3

LipHeight:

CR_911






OBJECTID (Unclassified Ramp): 86 **Address:** 978 NE Stephens St

Name: CR_911

CR_810





OBJECTID (Parallel Ramp): 87

Name: CR_810

Address: 1390 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 6.3

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.2

S3_RampCrossSlope1: 1.7

S4_RampSlope1: 5.4

S5_RampCrossSlope2: 2.3


S6_RampSlope2: 5.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_811





OBJECTID (Parallel Ramp): 88

Name: CR_811

Address: 3030 NE Stephens St

TruncDomes: True

Comments: Exactly 4' from boc to signal pole base

D1_LandingDim1: 6.5

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 1.8

S3_RampCrossSlope1: 1.2

S4_RampSlope1: 8.3

S5_RampCrossSlope2: 1.3

S6_RampSlope2: 0.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_812





OBJECTID (Parallel Ramp): 89

Name: CR_812

Address: 2821 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.1

D2_LandingDim2: 7.0

S1_LandingSlope1: 2.4

S2_LandingSlope2: 1.6

S3_RampCrossSlope1: 0.8

S4_RampSlope1: 7.3

S5_RampCrossSlope2: 1.9


S6_RampSlope2: 3.3

S7_CounterSlope: -3.0

GutterSlope: 1.4

LipHeight:

CR_815





OBJECTID (Parallel Ramp): 92

Name: CR_815

Address: 2340 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 1.6

S3_RampCrossSlope1:

S4_RampSlope1:

S5_RampCrossSlope2: 2.6

S6_RampSlope2: 11.6

S7_CounterSlope: 3.3

GutterSlope: 0.2

LipHeight:

CR_817





OBJECTID (Parallel Ramp): 94

Name: CR_817

Address: 2210 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.3

S1_LandingSlope1: 0.2

S2_LandingSlope2: 1.1

S3_RampCrossSlope1:

S4_RampSlope1: 6.2

S5_RampCrossSlope2: 0.9


S6_RampSlope2: 6.6

S7_CounterSlope: -1.3

GutterSlope: 1.1

LipHeight:

CR_818





OBJECTID (Parallel Ramp): 95

Name: CR_818

Address: 2174 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.4

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 2.9

S3_RampCrossSlope1: 0.4

S4_RampSlope1: 10.5

S5_RampCrossSlope2: 1.9

S6_RampSlope2: 1.9

S7_CounterSlope: 3.7

GutterSlope: 3.2

LipHeight:

CR_819





OBJECTID (Parallel Ramp): 96

Name: CR_819

Address: 2161 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 6.8

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.1

S3_RampCrossSlope1: 1.5

S4_RampSlope1: 5.0

S5_RampCrossSlope2: 2.1

S6_RampSlope2: 3.9

S7_CounterSlope: -6.0

GutterSlope: 1.8

LipHeight:

CR_820





OBJECTID (Parallel Ramp): 97

Name: CR_820

Address: 1810 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 7.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 1.1

S3_RampCrossSlope1: 1.9

S4_RampSlope1: 5.7

S5_RampCrossSlope2: 0.1


S6_RampSlope2: 9.3

S7_CounterSlope: 5.3

GutterSlope: 1.0

LipHeight:

CR_821





OBJECTID (Parallel Ramp): 98

Name: CR_821

Address: 1771 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.8

S1_LandingSlope1: 1.6

S2_LandingSlope2: 1.3

S3_RampCrossSlope1: 0.5

S4_RampSlope1: 8.8

S5_RampCrossSlope2: 0.7


S6_RampSlope2: 0.3

S7_CounterSlope: 0.7

GutterSlope: 2.1

LipHeight:

CR_824





OBJECTID (Parallel Ramp): 101

Name: CR_824

Address: 1275 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 6.5

S1_LandingSlope1: 3.2

S2_LandingSlope2: 1.9

S3_RampCrossSlope1: 2.9

S4_RampSlope1: 7.1

S5_RampCrossSlope2: 3.6

S6_RampSlope2: 11.5

S7_CounterSlope: 3.6

GutterSlope:

LipHeight:

CR_251





OBJECTID (Perpendicular Ramp): 162

Name: CR_251

Address: 1604 SE Stephens St

TruncDomes:

Comments: Non compliant

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.7

S4_RampCrossSlope: 0.4

S5_WingSlope1: 17.5

S6_WingSlope2: 17.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_252





OBJECTID (Perpendicular Ramp): 163

Name: CR_252

Address: 1543 SE Stephens St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.2

S4_RampCrossSlope: 6.1

S5_WingSlope1: 6.7

S6_WingSlope2: 20.5

S7_CounterSlope:

GutterSlope:

LipHeight: 0.5

CR_253





OBJECTID (Perpendicular Ramp): 164

Name: CR_253

Address: 1457 SE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 8.0

D2_LandingDim2: 6.5

D3_RampWidth: 8.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 1.1

S3_RampSlope: 0.1

S4_RampCrossSlope: 0.9

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope: 7.6

GutterSlope: 0.9

LipHeight:

CR_254





OBJECTID (Perpendicular Ramp): 165

Name: CR_254

Address: 1457 SE Stephens St

TruncDomes: True

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.9

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 2.4

S5_WingSlope1: 11.0


S6_WingSlope2: 6.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_255





OBJECTID (Perpendicular Ramp): 166

Name: CR_255

Address: 1457 SE Stephens St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.3

S4_RampCrossSlope: 1.2

S5_WingSlope1: 13.1

S6_WingSlope2: 16.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_256





OBJECTID (Perpendicular Ramp): 167

Name: CR_256

Address: 1351 SE Stephens St

TruncDomes:

Comments: Non compliant ramp - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.5

S4_RampCrossSlope: 2.5

S5_WingSlope1: 17.2


S6_WingSlope2: 6.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_257





OBJECTID (Perpendicular Ramp): 168

Name: CR_257

Address: 1358 SE Stephens St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.2

S4_RampCrossSlope: 0.8

S5_WingSlope1: 10.0

S6_WingSlope2: 14.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_258





OBJECTID (Perpendicular Ramp): 169

Name: CR_258

Address: 1316 SE Stephens St

TruncDomes: True

Comments: Mi block crossing

D1_LandingDim1: 6.0

D2_LandingDim2: 6.8

D3_RampWidth: 6.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.8

S3_RampSlope: 0.6

S4_RampCrossSlope: 0.6

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope: 7.9

GutterSlope: 0.3

LipHeight:

CR_259





OBJECTID (Perpendicular Ramp): 170

Name: CR_259

Address: 1259 SE Stephens St

TruncDomes:

Comments: Non compliant ramp - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.0

S4_RampCrossSlope: 3.8

S5_WingSlope1: 31.3

S6_WingSlope2: 22.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_260





OBJECTID (Perpendicular Ramp): 171

Name: CR_260

Address: 1243 SE Stephens St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.3

S4_RampCrossSlope: 3.3

S5_WingSlope1: 27.9

S6_WingSlope2: 32.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_263





OBJECTID (Perpendicular Ramp): 174

Name: CR_263

Address: 1117 SE Stephens St

TruncDomes: True

Comments: Mid block crossing

D1_LandingDim1: 8.0

D2_LandingDim2: 6.5

D3_RampWidth: 8.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 0.3

S3_RampSlope: 2.2

S4_RampCrossSlope: 0.2

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope: 12.7

GutterSlope: 0.9

LipHeight:

CR_264





OBJECTID (Perpendicular Ramp): 175

Name: CR_264

Address: 912 SE Stephens St

TruncDomes: True

Comments: Non compliant ramp, no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.9

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.1

S4_RampCrossSlope: 1.3

S5_WingSlope1: 8.6

S6_WingSlope2: 8.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_265





OBJECTID (Perpendicular Ramp): 176

Name: CR_265

Address: 864 SE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 0.3

S3_RampSlope: 8.7

S4_RampCrossSlope: 0.1

S5_WingSlope1: 4.4

S6_WingSlope2: 7.7

S7_CounterSlope: 10.9

GutterSlope: 0.2

LipHeight:

CR_266





OBJECTID (Perpendicular Ramp): 177

Name: CR_266

Address: 810 SE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.7

S2_LandingSlope2: 0.3

S3_RampSlope: 3.5

S4_RampCrossSlope: 0.7

S5_WingSlope1: 5.3


S6_WingSlope2: 4.2

S7_CounterSlope: 8.3

GutterSlope: 0.1

LipHeight:

CR_267





OBJECTID (Perpendicular Ramp): 178

Name: CR_267

Address: 750 SE Stephens St

TruncDomes:

Comments: Traffic signal in landing

D1_LandingDim1: 5.0

D2_LandingDim2: 3.5

D3_RampWidth: 5.0

S1_LandingSlope1: 2.0

S2_LandingSlope2: 0.6

S3_RampSlope: 5.8

S4_RampCrossSlope: 2.3

S5_WingSlope1: 7.1

S6_WingSlope2: 11.9

S7_CounterSlope: 12.4

GutterSlope: 2.9

LipHeight:

CR_283





OBJECTID (Perpendicular Ramp): 194

Name: CR_283

Address: 1731 NE Stephens St

TruncDomes: True

Comments: Exactly 4' to base of signal pole from bow curb, .4' uneven concrete for signal pole

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.8

S3_RampSlope: 8.4

S4_RampCrossSlope:

S5_WingSlope1: 9.9


S6_WingSlope2: 7.0

S7_CounterSlope: -3.9

GutterSlope: 0.3

LipHeight:

CR_390





OBJECTID (Perpendicular Ramp): 302

Name: CR_390

Address: 3353 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.8

D3_RampWidth: 5.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 2.5

S3_RampSlope: 5.9

S4_RampCrossSlope: 2.7

S5_WingSlope1: 12.1

S6_WingSlope2: 4.2

S7_CounterSlope: 7.7

GutterSlope: 2.9

LipHeight:

CR_481





OBJECTID (Perpendicular Ramp): 393

Name: CR_481

Address: 3357 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 5.4

D3_RampWidth: 4.9

S1_LandingSlope1: 4.7

S2_LandingSlope2: 3.1

S3_RampSlope: 8.9

S4_RampCrossSlope: 3.4

S5_WingSlope1: 12.2


S6_WingSlope2: 8.5

S7_CounterSlope: 9.4

GutterSlope: 2.7

LipHeight:

CR_520





OBJECTID (Perpendicular Ramp): 432

Name: CR_520

Address: 1107 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.6

S3_RampSlope: 6.5

S4_RampCrossSlope: 2.5

S5_WingSlope1: 4.9

S6_WingSlope2: 9.2

S7_CounterSlope: 3.3

GutterSlope: 2.5

LipHeight:

CR_564





OBJECTID (Perpendicular Ramp): 476

Name: CR_564

Address: 1107 NE Stephens St

TruncDomes: True

Comments: On chestnut

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 2.2

S3_RampSlope: 8.3

S4_RampCrossSlope: 2.4

S5_WingSlope1: 13.2

S6_WingSlope2: 6.0

S7_CounterSlope: 1.0

GutterSlope: 3.1

LipHeight:

CR_565





OBJECTID (Perpendicular Ramp): 477

Name: CR_565

Address: 1107 NE Stephens St

TruncDomes: True

Comments: On stephens

D1_LandingDim1: 4.9

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.7

S2_LandingSlope2: 2.8

S3_RampSlope: 8.5

S4_RampCrossSlope: 2.3

S5_WingSlope1: 10.4


S6_WingSlope2: 1.7

S7_CounterSlope: 0.1

GutterSlope: 2.5

LipHeight:

CR_604





OBJECTID (Perpendicular Ramp): 516

Name: CR_604

Address: 1400 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 6.0

D2_LandingDim2: 4.5

D3_RampWidth: 6.0

S1_LandingSlope1: 4.5

S2_LandingSlope2: 2.6

S3_RampSlope: 8.5

S4_RampCrossSlope: 1.8

S5_WingSlope1: 10.2


S6_WingSlope2: 12.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_605





OBJECTID (Perpendicular Ramp): 517

Name: CR_605

Address: 1390 NE Stephens St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.4

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.0

S4_RampCrossSlope: 0.7

S5_WingSlope1: 16.0

S6_WingSlope2: 14.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_612





OBJECTID (Perpendicular Ramp): 524

Name: CR_612

Address: 2821 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 4.1

D3_RampWidth: 6.4

S1_LandingSlope1: 1.1

S2_LandingSlope2: 2.0

S3_RampSlope: 8.4

S4_RampCrossSlope: 2.0

S5_WingSlope1: 8.7


S6_WingSlope2: 9.3

S7_CounterSlope: 4.1

GutterSlope: 0.6

LipHeight:

CR_635





OBJECTID (Perpendicular Ramp): 547

Name: CR_635

Address: 1390 NE Stephens St

TruncDomes:

Comments: Non compliant - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.6

S4_RampCrossSlope: 0.3

S5_WingSlope1: 8.8


S6_WingSlope2: 4.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_638





OBJECTID (Perpendicular Ramp): 550

Name: CR_638

Address: 1494 NE Stephens St

TruncDomes:

Comments: On stephens

D1_LandingDim1: 4.4

D2_LandingDim2: 4.9

D3_RampWidth: 4.4

S1_LandingSlope1: 3.6

S2_LandingSlope2: 2.2

S3_RampSlope: 9.9

S4_RampCrossSlope: 0.9

S5_WingSlope1: 10.8


S6_WingSlope2: 10.0

S7_CounterSlope: 7.2

GutterSlope: 2.6

LipHeight:

CR_639





OBJECTID (Perpendicular Ramp): 551

Name: CR_639

Address: 1494 NE Stephens St

TruncDomes:

Comments: On oakland

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.2

S2_LandingSlope2: 3.1

S3_RampSlope: 6.9

S4_RampCrossSlope: 3.8

S5_WingSlope1: 8.6


S6_WingSlope2: 9.8

S7_CounterSlope: 6.1

GutterSlope: 2.5

LipHeight:

CR_640





OBJECTID (Perpendicular Ramp): 552

Name: CR_640

Address: 1494 NE Stephens St

TruncDomes:

Comments: On oakland

D1_LandingDim1: 5.1

D2_LandingDim2: 3.7

D3_RampWidth: 5.1

S1_LandingSlope1: 2.3

S2_LandingSlope2: 3.5

S3_RampSlope: 10.6

S4_RampCrossSlope: 2.0

S5_WingSlope1: 12.2


S6_WingSlope2: 8.7

S7_CounterSlope: 3.1

GutterSlope: 1.7

LipHeight:

CR_641





OBJECTID (Perpendicular Ramp): 553

Name: CR_641

Address: 1494 NE Stephens St

TruncDomes:

Comments: On stephens

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 4.0

S3_RampSlope: 9.7

S4_RampCrossSlope: 3.4

S5_WingSlope1: 7.5

S6_WingSlope2: 9.3

S7_CounterSlope: 6.2

GutterSlope: 2.7

LipHeight:

CR_642





OBJECTID (Perpendicular Ramp): 554

Name: CR_642

Address: 1200 NE Stephens St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1: 7.9

S2_LandingSlope2: 4.3

S3_RampSlope: 4.1

S4_RampCrossSlope: 17.2

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight: 0.3

CR_643





OBJECTID (Perpendicular Ramp): 555

Name: CR_643

Address: 1157 NE Stephens St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.7

S1_LandingSlope1: 12.0

S2_LandingSlope2: 3.3

S3_RampSlope: 19.7

S4_RampCrossSlope: 6.6

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_644





OBJECTID (Perpendicular Ramp): 556

Name: CR_644

Address: 1157 NE Stephens St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 3.9

S5_WingSlope1: 9.9


S6_WingSlope2: 21.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_674





OBJECTID (Perpendicular Ramp): 586

Name: CR_674

Address: 1590 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.7

S2_LandingSlope2: 1.7

S3_RampSlope: 11.0

S4_RampCrossSlope: 3.0

S5_WingSlope1: 12.3


S6_WingSlope2: 14.4

S7_CounterSlope: 1.6

GutterSlope: 1.9

LipHeight:

CR_675





OBJECTID (Perpendicular Ramp): 587

Name: CR_675

Address: 1539 NE Stephens St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.0

D3_RampWidth: 5.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 7.7

S3_RampSlope: 10.4

S4_RampCrossSlope: 6.9

S5_WingSlope1: 14.5


S6_WingSlope2: 5.1

S7_CounterSlope: 2.9

GutterSlope: 4.0

LipHeight:

CR_676





OBJECTID (Perpendicular Ramp): 588

Name: CR_676

Address: 1520 NE Stephens St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.8

S4_RampCrossSlope: 0.9

S5_WingSlope1: 19.0


S6_WingSlope2: 5.7

S7_CounterSlope:

GutterSlope:

LipHeight: 1.2

CR_677





OBJECTID (Perpendicular Ramp): 589

Name: CR_677

Address: 1494 NE Stephens St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.0

S4_RampCrossSlope: 1.2

S5_WingSlope1: 9.8

S6_WingSlope2: 10.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_678





OBJECTID (Perpendicular Ramp): 590

Name: CR_678

Address: 1339 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 4.0

D3_RampWidth: 4.9

S1_LandingSlope1: 2.4

S2_LandingSlope2:

S3_RampSlope: 8.2

S4_RampCrossSlope: 1.6

S5_WingSlope1: 6.0

S6_WingSlope2: 11.9

S7_CounterSlope: 0.8

GutterSlope: 1.1

LipHeight:

CR_679





OBJECTID (Perpendicular Ramp): 591

Name: CR_679

Address: 1337 NE Stephens St

TruncDomes: True

Comments:

D1_LandingDim1: 4.8

D2_LandingDim2: 4.0

D3_RampWidth: 4.8

S1_LandingSlope1: 2.9

S2_LandingSlope2: 2.0

S3_RampSlope: 8.6

S4_RampCrossSlope: 2.4

S5_WingSlope1: 10.5

S6_WingSlope2: 10.0

S7_CounterSlope: 5.0

GutterSlope: 0.3

LipHeight:

CR_680





OBJECTID (Perpendicular Ramp): 592

Name: CR_680

Address: 1275 NE Stephens St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.8

S4_RampCrossSlope: 4.1

S5_WingSlope1: 20.4

S6_WingSlope2: 14.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_681





OBJECTID (Perpendicular Ramp): 593

Name: CR_681

Address: 1082 NE Stephens St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 1.4

S5_WingSlope1: 13.2

S6_WingSlope2: 12.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_682





OBJECTID (Perpendicular Ramp): 594

Name: CR_682

Address: 1053 NE Stephens St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.7

S4_RampCrossSlope: 4.9

S5_WingSlope1: 20.6

S6_WingSlope2: 11.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_683





OBJECTID (Perpendicular Ramp): 595

Name: CR_683

Address: 988 NE Stephens St

TruncDomes:

Comments: No landing. Power pole in landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 2.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.7

S4_RampCrossSlope: 3.9

S5_WingSlope1: 17.0


S6_WingSlope2: 17.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_687





OBJECTID (Perpendicular Ramp): 599

Name: CR_687

Address: 440 NE Stephens St

TruncDomes:

Comments: No landing. Power pole in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.2

S4_RampCrossSlope: 3.9

S5_WingSlope1: 10.8

S6_WingSlope2: 17.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_688





OBJECTID (Perpendicular Ramp): 600

Name: CR_688

Address: 440 NE Stephens St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 3.6

S4_RampCrossSlope: 6.8

S5_WingSlope1: 6.5


S6_WingSlope2: 18.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_52





OBJECTID (Combination Ramp): 5

Name: CR_52

Address: 2900 NW Stewart Pkwy

TruncDomes: True

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 3.9

D3_RampWidth2: 6.9

D4_RampWidth3: 6.9

D5_RampWidth1: 5.0

S1_LandingSlope1: 0.6

S2_LandingSlope2: 0.1

S3_RampCrossSlope2: 0.6

S4_RampSlope2: 1.5

S5_RampCrossSlope3: 0.2

S6_RampSlope3: 6.3

S7_RampSlope1: 10.2

S8_RampCrossSlope1: 0.3

S9_WingSlope1: 5.9


S10_WingSlope2: 8.6

S11_CounterSlope: 1.1

GutterSlope: 1.6

LipHeight:

CR_53





OBJECTID (Combination Ramp): 6

Name: CR_53

Address: 2424 NW Stewart Pkwy

TruncDomes: True

Comments: On stewart

D1_LandingDim1: 5.0

D2_LandingDim2: 3.8

D3_RampWidth2: 7.0

D4_RampWidth3: 7.0

D5_RampWidth1: 5.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 1.5

S3_RampCrossSlope2: 2.4

S4_RampSlope2: 3.4

S5_RampCrossSlope3: 1.4

S6_RampSlope3: 4.2

S7_RampSlope1: 7.3

S8_RampCrossSlope1: 2.5

S9_WingSlope1: 6.5


S10_WingSlope2: 8.9

S11_CounterSlope: 2.8

GutterSlope: 3.0

LipHeight:

CR_58





OBJECTID (Combination Ramp): 11

Name: CR_58

Address: 3000 NW Stewart Pkwy

TruncDomes: True

Comments:

D1_LandingDim1: 5.3

D2_LandingDim2: 3.9

D3_RampWidth2: 6.0

D4_RampWidth3: 6.0

D5_RampWidth1: 5.6

S1_LandingSlope1: 2.3

S2_LandingSlope2: 1.9

S3_RampCrossSlope2: 1.4

S4_RampSlope2: 7.0

S5_RampCrossSlope3: 2.2

S6_RampSlope3: 2.0

S7_RampSlope1: 4.0

S8_RampCrossSlope1: 0.9

S9_WingSlope1: 7.9


S10_WingSlope2: 3.0

S11_CounterSlope: 1.7

GutterSlope: 2.3

LipHeight:

CR_749





OBJECTID (Parallel Ramp): 26

Name: CR_749

Address: 3000 NW Stewart Pkwy

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 0.4

S3_RampCrossSlope1: 1.6

S4_RampSlope1: 7.1

S5_RampCrossSlope2: 0.9


S6_RampSlope2: 6.7

S7_CounterSlope: -3.1

GutterSlope: 0.1

LipHeight:

CR_750





OBJECTID (Parallel Ramp): 27

Name: CR_750

Address: 2125 NW Stewart Pkwy

TruncDomes: True

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 6.3

S1_LandingSlope1: 2.4

S2_LandingSlope2: 1.5

S3_RampCrossSlope1: 0.5

S4_RampSlope1: 9.6

S5_RampCrossSlope2: 0.3


S6_RampSlope2: 5.1

S7_CounterSlope: -4.6

GutterSlope: 1.4

LipHeight:

CR_751





OBJECTID (Parallel Ramp): 28

Name: CR_751

Address: 2125 NW Stewart Pkwy

TruncDomes: True

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 6.4

S1_LandingSlope1: 0.2

S2_LandingSlope2: 2.5

S3_RampCrossSlope1: 2.3

S4_RampSlope1: 5.3

S5_RampCrossSlope2: 1.4

S6_RampSlope2: 8.0

S7_CounterSlope: -6.3

GutterSlope: 3.2

LipHeight:

CR_857





OBJECTID (Unclassified Ramp): 32 **Address:** 2755 NW Stewart Pkwy

Name: CR_857

CR_858






OBJECTID (Unclassified Ramp): 33 **Address:** 2260 NW Stewart Pkwy

Name: CR_858

CR_34





OBJECTID (Bus Stop-Median): 34

Name: CR_34

Address: 2880 NW Stewart Pkwy

Comments:

D1_LandingDim1: 8.0

D2_LandingDim2: 8.0

S1_LandingSlope1: 3.1

S2_LandingSlope2: 0.9

CR_35





OBJECTID (Bus Stop-Median): 35

Name: CR_35

Address: 2455 NW Stewart Pkwy

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 8.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 1.0

CR_36





OBJECTID (Bus Stop-Median): 36

Name: CR_36

Address: 2125 NW Stewart Pkwy

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 8.0

S1_LandingSlope1: 1.9

S2_LandingSlope2: 0.4

CR_916



OBJECTID (Unclassified Ramp): 91 **Address:** 1600 NW Stewart Pkwy

Name: CR_916

CR_203





OBJECTID (Perpendicular Ramp): 114

Name: CR_203

Address: 2900 NW Stewart Pkwy

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 8.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 4.1

S3_RampSlope: 7.2

S4_RampCrossSlope: 0.7

S5_WingSlope1: 8.5

S6_WingSlope2: 7.2

S7_CounterSlope: 0.5

GutterSlope: 1.9

LipHeight:

CR_204





OBJECTID (Perpendicular Ramp): 115

Name: CR_204

Address: 3001 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 5.7

D3_RampWidth: 5.0

S1_LandingSlope1: 0.3

S2_LandingSlope2: 0.3

S3_RampSlope: 8.9

S4_RampCrossSlope: 0.6

S5_WingSlope1: 9.8


S6_WingSlope2: 9.4

S7_CounterSlope: 4.6

GutterSlope: 1.2

LipHeight:

CR_205





OBJECTID (Perpendicular Ramp): 116

Name: CR_205

Address: 2757 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.2

S4_RampCrossSlope: 1.5

S5_WingSlope1: 10.8


S6_WingSlope2: 10.9

S7_CounterSlope: 8.0

GutterSlope:

LipHeight:

CR_206





OBJECTID (Perpendicular Ramp): 117

Name: CR_206

Address: 2655 NW Stewart Pkwy

TruncDomes:

Comments: No landing. Traffic pole in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 5.8

S4_RampCrossSlope: 0.4

S5_WingSlope1: 6.9

S6_WingSlope2: 7.7

S7_CounterSlope: 4.9

GutterSlope:

LipHeight:

CR_207





OBJECTID (Perpendicular Ramp): 118

Name: CR_207

Address: 2700 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.8

S4_RampCrossSlope: 0.5

S5_WingSlope1: 4.7


S6_WingSlope2: 9.9

S7_CounterSlope: 2.9

GutterSlope:

LipHeight:

CR_208





OBJECTID (Perpendicular Ramp): 119

Name: CR_208

Address: 3013 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 3.8

D3_RampWidth: 4.9

S1_LandingSlope1: 2.4

S2_LandingSlope2: 0.5

S3_RampSlope: 9.5

S4_RampCrossSlope: 1.8

S5_WingSlope1: 9.3


S6_WingSlope2: 11.5

S7_CounterSlope: -2.8

GutterSlope: 0.8

LipHeight:

CR_209





OBJECTID (Perpendicular Ramp): 120

Name: CR_209

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: On Stuart. Manhole in landing

D1_LandingDim1: 5.5

D2_LandingDim2: 5.3

D3_RampWidth: 2.3

S1_LandingSlope1: 4.3

S2_LandingSlope2: 1.9

S3_RampSlope: 11.3

S4_RampCrossSlope: 1.4

S5_WingSlope1: 6.3


S6_WingSlope2: 11.4

S7_CounterSlope: 4.4

GutterSlope: 0.7

LipHeight: 0.4

CR_210





OBJECTID (Perpendicular Ramp): 121

Name: CR_210

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: On renann

D1_LandingDim1: 4.0

D2_LandingDim2: 3.0

D3_RampWidth: 4.3

S1_LandingSlope1: 3.6

S2_LandingSlope2: 2.3

S3_RampSlope: 9.2

S4_RampCrossSlope: 1.2

S5_WingSlope1: 9.9


S6_WingSlope2: 5.1

S7_CounterSlope: 7.0

GutterSlope: 0.9

LipHeight: 0.4

CR_211





OBJECTID (Perpendicular Ramp): 122

Name: CR_211

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: On renann

D1_LandingDim1: 6.0

D2_LandingDim2: 3.1

D3_RampWidth: 5.0

S1_LandingSlope1: 2.2

S2_LandingSlope2:

S3_RampSlope: 9.6

S4_RampCrossSlope: 0.2

S5_WingSlope1: 7.0


S6_WingSlope2: 7.0

S7_CounterSlope: 7.8

GutterSlope: 0.7

LipHeight: 1.2

CR_212





OBJECTID (Perpendicular Ramp): 123

Name: CR_212

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: On stewart

D1_LandingDim1: 10.0

D2_LandingDim2: 3.1

D3_RampWidth: 4.4

S1_LandingSlope1: 1.4

S2_LandingSlope2: 1.2

S3_RampSlope: 11.2

S4_RampCrossSlope: 6.0

S5_WingSlope1: 7.8


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_213





OBJECTID (Perpendicular Ramp): 124

Name: CR_213

Address: 2535 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.3

S4_RampCrossSlope: 1.6

S5_WingSlope1: 15.3


S6_WingSlope2: 11.1

S7_CounterSlope: 6.7

GutterSlope:

LipHeight: 1.3

CR_214





OBJECTID (Perpendicular Ramp): 125

Name: CR_214

Address: 2549 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.0

S4_RampCrossSlope: 2.7

S5_WingSlope1: 10.5


S6_WingSlope2: 24.3

S7_CounterSlope: 6.9

GutterSlope:

LipHeight: 1.2

CR_290





OBJECTID (Perpendicular Ramp): 201

Name: CR_290

Address: 2800 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.8

D3_RampWidth: 5.0

S1_LandingSlope1: 0.6

S2_LandingSlope2: 2.7

S3_RampSlope: 8.5

S4_RampCrossSlope: 3.5

S5_WingSlope1: 12.9

S6_WingSlope2: 7.6

S7_CounterSlope: 5.5

GutterSlope: 4.5

LipHeight:

CR_291





OBJECTID (Perpendicular Ramp): 202

Name: CR_291

Address: 2757 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.1

S4_RampCrossSlope:

S5_WingSlope1: 6.3


S6_WingSlope2: 9.1

S7_CounterSlope: 3.8

GutterSlope: 2.7

LipHeight:

CR_292





OBJECTID (Perpendicular Ramp): 203

Name: CR_292

Address: 2700 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.0

S4_RampCrossSlope: 6.1

S5_WingSlope1: 2.3

S6_WingSlope2: 15.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_293





OBJECTID (Perpendicular Ramp): 204

Name: CR_293

Address: 2655 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp - no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 0.6

S4_RampCrossSlope: 3.8

S5_WingSlope1: 8.2

S6_WingSlope2: 4.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_294





OBJECTID (Perpendicular Ramp): 205

Name: CR_294

Address: 2757 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.4

S4_RampCrossSlope: 4.2

S5_WingSlope1: 27.4


S6_WingSlope2: 11.1

S7_CounterSlope:

GutterSlope:

LipHeight: 1.0

CR_295





OBJECTID (Perpendicular Ramp): 206

Name: CR_295

Address: 3013 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 3.6

D3_RampWidth: 5.2

S1_LandingSlope1: 1.0

S2_LandingSlope2: 1.2

S3_RampSlope: 8.8

S4_RampCrossSlope: 2.2

S5_WingSlope1: 9.0

S6_WingSlope2: 9.7

S7_CounterSlope: -0.5

GutterSlope: 2.1

LipHeight:

CR_296





OBJECTID (Perpendicular Ramp): 207

Name: CR_296

Address: 2549 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.7

S4_RampCrossSlope: 0.3

S5_WingSlope1: 10.2


S6_WingSlope2: 8.0

S7_CounterSlope: 10.0

GutterSlope: 0.8

LipHeight:

CR_297





OBJECTID (Perpendicular Ramp): 208

Name: CR_297

Address: 2549 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.4

S4_RampCrossSlope: 2.4

S5_WingSlope1: 8.5


S6_WingSlope2: 9.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_298





OBJECTID (Perpendicular Ramp): 209

Name: CR_298

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing on Stewart pkwy

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.7

S4_RampCrossSlope: 0.5

S5_WingSlope1: 11.2


S6_WingSlope2: 2.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_299





OBJECTID (Perpendicular Ramp): 210

Name: CR_299

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing on Renann st

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 2.0

S5_WingSlope1: 21.9


S6_WingSlope2: 18.8

S7_CounterSlope:

GutterSlope:

LipHeight: 0.8

CR_300





OBJECTID (Perpendicular Ramp): 211

Name: CR_300

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing on Renann

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.2

S4_RampCrossSlope: 1.1

S5_WingSlope1: 19.5


S6_WingSlope2: 20.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_301





OBJECTID (Perpendicular Ramp): 212

Name: CR_301

Address: 2460 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.6

S4_RampCrossSlope: 1.9

S5_WingSlope1: 10.5


S6_WingSlope2: 19.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_302





OBJECTID (Perpendicular Ramp): 213

Name: CR_302

Address: 2549 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp - no lading

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.2

S4_RampCrossSlope: 0.7

S5_WingSlope1: 22.6


S6_WingSlope2: 19.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_303





OBJECTID (Perpendicular Ramp): 214

Name: CR_303

Address: 2260 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 2.9

D3_RampWidth: 4.2

S1_LandingSlope1: 7.2

S2_LandingSlope2: 1.0

S3_RampSlope: 9.5

S4_RampCrossSlope: 3.5

S5_WingSlope1: 15.9


S6_WingSlope2: 3.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_311





OBJECTID (Perpendicular Ramp): 222

Name: CR_311

Address: 2075 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 2.8

D3_RampWidth: 4.2

S1_LandingSlope1: 7.1

S2_LandingSlope2: 3.6

S3_RampSlope: 9.6

S4_RampCrossSlope: 2.5

S5_WingSlope1: 14.2

S6_WingSlope2: 8.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_312





OBJECTID (Perpendicular Ramp): 223

Name: CR_312

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: On Stewart parkway

D1_LandingDim1: 4.6

D2_LandingDim2: 2.9

D3_RampWidth: 4.6

S1_LandingSlope1: 2.9

S2_LandingSlope2: 3.7

S3_RampSlope: 11.4

S4_RampCrossSlope: 2.5

S5_WingSlope1: 10.9


S6_WingSlope2: 4.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_313





OBJECTID (Perpendicular Ramp): 224

Name: CR_313

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: On garden valley, signal pole in landing

D1_LandingDim1: 4.8

D2_LandingDim2: 3.2

D3_RampWidth: 4.8

S1_LandingSlope1: 2.1

S2_LandingSlope2: 4.8

S3_RampSlope: 12.3

S4_RampCrossSlope: 3.7

S5_WingSlope1: 11.3

S6_WingSlope2: 4.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_314





OBJECTID (Perpendicular Ramp): 225

Name: CR_314

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 5.0

D2_LandingDim2: 3.5

D3_RampWidth: 5.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 1.5

S3_RampSlope: 11.3

S4_RampCrossSlope: 2.7

S5_WingSlope1: 9.0


S6_WingSlope2: 5.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_315





OBJECTID (Perpendicular Ramp): 226

Name: CR_315

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: On Stewart parkway

D1_LandingDim1: 4.8

D2_LandingDim2: 3.2

D3_RampWidth: 4.8

S1_LandingSlope1: 1.8

S2_LandingSlope2: 3.5

S3_RampSlope: 10.0

S4_RampCrossSlope: 1.0

S5_WingSlope1: 11.2


S6_WingSlope2: 5.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_317





OBJECTID (Perpendicular Ramp): 228

Name: CR_317

Address: 2125 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing - on driveway

D1_LandingDim1: 4.0

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 5.2

S4_RampCrossSlope: 0.6

S5_WingSlope1: 7.0


S6_WingSlope2: 9.4

S7_CounterSlope: 7.2

GutterSlope:

LipHeight:

CR_318





OBJECTID (Perpendicular Ramp): 229

Name: CR_318

Address: 2125 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp - no landing - on Stewart pkwy

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.1

S4_RampCrossSlope: 1.0

S5_WingSlope1: 8.2

S6_WingSlope2: 4.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_319





OBJECTID (Perpendicular Ramp): 230

Name: CR_319

Address: 2373 NW Stewart Pkwy

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.4

S4_RampCrossSlope: 2.4

S5_WingSlope1: 16.1

S6_WingSlope2: 11.5

S7_CounterSlope:

GutterSlope:

LipHeight: 0.3

CR_320





OBJECTID (Perpendicular Ramp): 231

Name: CR_320

Address: 2373 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.3

D2_LandingDim2: 4.1

D3_RampWidth: 4.3

S1_LandingSlope1: 1.8

S2_LandingSlope2: 2.5

S3_RampSlope: 10.6

S4_RampCrossSlope: 0.8

S5_WingSlope1: 8.5

S6_WingSlope2: 11.4

S7_CounterSlope: 1.3

GutterSlope:

LipHeight:

CR_322





OBJECTID (Perpendicular Ramp): 233

Name: CR_322

Address: 1600 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.9

D2_LandingDim2: 3.7

D3_RampWidth: 4.9

S1_LandingSlope1: 2.1

S2_LandingSlope2: 3.8

S3_RampSlope: 9.7

S4_RampCrossSlope: 3.1

S5_WingSlope1: 7.0


S6_WingSlope2: 9.7

S7_CounterSlope: 4.5

GutterSlope: 2.5

LipHeight:

CR_382





OBJECTID (Perpendicular Ramp): 294

Name: CR_382

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.9

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.6

S4_RampCrossSlope: 4.1

S5_WingSlope1: 6.4


S6_WingSlope2: 11.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_383





OBJECTID (Perpendicular Ramp): 295

Name: CR_383

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.8

S4_RampCrossSlope: 1.1

S5_WingSlope1: 29.5

S6_WingSlope2: 18.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_395





OBJECTID (Perpendicular Ramp): 307

Name: CR_395

Address: 2260 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 3.0

D3_RampWidth: 4.0

S1_LandingSlope1: 7.9

S2_LandingSlope2: 3.2

S3_RampSlope: 8.8

S4_RampCrossSlope: 2.4

S5_WingSlope1: 6.6

S6_WingSlope2: 11.0

S7_CounterSlope: 8.7

GutterSlope: 0.3

LipHeight:

CR_396





OBJECTID (Perpendicular Ramp): 308

Name: CR_396

Address: 2245 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 2.7

D3_RampWidth: 4.2

S1_LandingSlope1: 7.5

S2_LandingSlope2: 6.0

S3_RampSlope: 7.6

S4_RampCrossSlope: 5.8

S5_WingSlope1: 5.3

S6_WingSlope2: 13.0

S7_CounterSlope: 8.5

GutterSlope: 3.5

LipHeight:

CR_397





OBJECTID (Perpendicular Ramp): 309

Name: CR_397

Address: 2220 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.1

D2_LandingDim2: 3.1

D3_RampWidth: 4.1

S1_LandingSlope1: 7.0

S2_LandingSlope2: 0.8

S3_RampSlope: 6.8

S4_RampCrossSlope: 2.7

S5_WingSlope1: 6.2


S6_WingSlope2: 5.1

S7_CounterSlope: 3.6

GutterSlope: 0.2

LipHeight:

CR_398





OBJECTID (Perpendicular Ramp): 310

Name: CR_398

Address: 2075 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 4.2

D2_LandingDim2: 2.9

D3_RampWidth: 4.2

S1_LandingSlope1: 8.1

S2_LandingSlope2: 7.7

S3_RampSlope: 10.1

S4_RampCrossSlope: 8.4

S5_WingSlope1: 2.7


S6_WingSlope2: 14.5

S7_CounterSlope: 2.1

GutterSlope: 7.5

LipHeight:

CR_399





OBJECTID (Perpendicular Ramp): 311

Name: CR_399

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: On stewart

D1_LandingDim1: 4.4

D2_LandingDim2: 3.7

D3_RampWidth: 4.4

S1_LandingSlope1: 2.8

S2_LandingSlope2: 0.7

S3_RampSlope: 12.5

S4_RampCrossSlope: 1.4

S5_WingSlope1: 10.7

S6_WingSlope2: 10.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_400





OBJECTID (Perpendicular Ramp): 312

Name: CR_400

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: On garden valley

D1_LandingDim1: 4.5

D2_LandingDim2: 3.9

D3_RampWidth: 4.5

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.7

S3_RampSlope: 9.1

S4_RampCrossSlope: 1.4

S5_WingSlope1: 11.0

S6_WingSlope2: 8.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_401





OBJECTID (Perpendicular Ramp): 313

Name: CR_401

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: On garden valley. No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.3

S4_RampCrossSlope: 0.8

S5_WingSlope1: 7.6


S6_WingSlope2: 9.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_402





OBJECTID (Perpendicular Ramp): 314

Name: CR_402

Address: 2040 NW Stewart Pkwy

TruncDomes:

Comments: No landing. On garden valley.

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.3

S4_RampCrossSlope: 1.5

S5_WingSlope1: 5.7


S6_WingSlope2: 7.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_404





OBJECTID (Perpendicular Ramp): 316

Name: CR_404

Address: 2125 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.9

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 4.5

S4_RampCrossSlope: 0.7

S5_WingSlope1: 11.6


S6_WingSlope2: 5.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_405





OBJECTID (Perpendicular Ramp): 317

Name: CR_405

Address: 2125 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 4.4

S4_RampCrossSlope: 1.3

S5_WingSlope1: 8.2


S6_WingSlope2: 6.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_406





OBJECTID (Perpendicular Ramp): 318

Name: CR_406

Address: 2220 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.3

S4_RampCrossSlope: 10.8

S5_WingSlope1: 24.8


S6_WingSlope2: 8.2

S7_CounterSlope: 9.4

GutterSlope: 6.8

LipHeight: 1.0

CR_407





OBJECTID (Perpendicular Ramp): 319

Name: CR_407

Address: 2245 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.6

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.7

S4_RampCrossSlope: 4.6

S5_WingSlope1: 17.1

S6_WingSlope2: 25.0

S7_CounterSlope: 10.4

GutterSlope:

LipHeight:

CR_409





OBJECTID (Perpendicular Ramp): 321

Name: CR_409

Address: 1600 NW Stewart Pkwy

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.2

D3_RampWidth: 5.0

S1_LandingSlope1: 2.4

S2_LandingSlope2: 1.6

S3_RampSlope: 8.7

S4_RampCrossSlope: 1.7

S5_WingSlope1: 12.0


S6_WingSlope2: 9.9

S7_CounterSlope: 10.2

GutterSlope:

LipHeight:

CR_469





OBJECTID (Perpendicular Ramp): 381

Name: CR_469

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 5.2

S5_WingSlope1: 9.4

S6_WingSlope2: 8.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_470





OBJECTID (Perpendicular Ramp): 382

Name: CR_470

Address: 2424 NW Stewart Pkwy

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.7

S4_RampCrossSlope: 1.5

S5_WingSlope1: 23.2

S6_WingSlope2: 33.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_192





OBJECTID (Perpendicular Ramp): 103

Name: CR_192

Address: 1739 NE Sunset St

TruncDomes:

Comments: Railing in landing

D1_LandingDim1: 5.0

D2_LandingDim2: 3.5

D3_RampWidth: 5.0

S1_LandingSlope1: 0.1

S2_LandingSlope2: 20.1

S3_RampSlope: 7.8

S4_RampCrossSlope: 16.7

S5_WingSlope1: 4.6

S6_WingSlope2: 22.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_278





OBJECTID (Perpendicular Ramp): 189

Name: CR_278

Address: 1739 NE Sunset St

TruncDomes:

Comments: Non compliant ramp

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 17.7

S4_RampCrossSlope: 7.6

S5_WingSlope1: 25.6


S6_WingSlope2: 22.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_756





OBJECTID (Parallel Ramp): 33

Name: CR_756

Address: 2490 NW Troost St

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.8

S1_LandingSlope1: 2.7

S2_LandingSlope2: 6.2

S3_RampCrossSlope1: 0.5

S4_RampSlope1: 14.5

S5_RampCrossSlope2: 4.6


S6_RampSlope2: 1.8

S7_CounterSlope: 3.5

GutterSlope: 7.0

LipHeight:

CR_334





OBJECTID (Perpendicular Ramp): 246

Name: CR_334

Address: 1598 NW Troost St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 1.1

S5_WingSlope1: 13.0

S6_WingSlope2: 15.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_335





OBJECTID (Perpendicular Ramp): 247

Name: CR_335

Address: 1602 NW Troost St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.8

S4_RampCrossSlope: 2.6

S5_WingSlope1: 16.1

S6_WingSlope2: 10.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_370





OBJECTID (Perpendicular Ramp): 282

Name: CR_370

Address: 2350 NW Troost St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 15.7

S3_RampSlope: 9.2

S4_RampCrossSlope: 15.1

S5_WingSlope1: 7.1

S6_WingSlope2: 22.4

S7_CounterSlope: 12.9

GutterSlope: 15.5

LipHeight:

CR_371





OBJECTID (Perpendicular Ramp): 283

Name: CR_371

Address: 2350 NW Troost St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.5

D3_RampWidth: 5.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 3.1

S3_RampSlope: 5.8

S4_RampCrossSlope: 5.5

S5_WingSlope1: 11.4

S6_WingSlope2: 3.6

S7_CounterSlope: 16.0

GutterSlope: 6.3

LipHeight:

CR_372





OBJECTID (Perpendicular Ramp): 284

Name: CR_372

Address: 2270 NW Troost St

TruncDomes:

Comments: Signal pole in landing

D1_LandingDim1: 5.0

D2_LandingDim2: 3.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.8

S2_LandingSlope2: 7.2

S3_RampSlope: 10.0

S4_RampCrossSlope: 6.1

S5_WingSlope1: 7.0


S6_WingSlope2: 15.4

S7_CounterSlope: 7.8

GutterSlope: 7.0

LipHeight:

CR_373





OBJECTID (Perpendicular Ramp): 285

Name: CR_373

Address: 2270 NW Troost St

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.9

S2_LandingSlope2: 2.6

S3_RampSlope: 10.7

S4_RampCrossSlope: 2.5

S5_WingSlope1: 11.1


S6_WingSlope2: 5.2

S7_CounterSlope: 4.3

GutterSlope: 0.3

LipHeight:

CR_374





OBJECTID (Perpendicular Ramp): 286

Name: CR_374

Address: 2229 NW Troost St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.6

S4_RampCrossSlope: 4.0

S5_WingSlope1: 24.1

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_375





OBJECTID (Perpendicular Ramp): 287

Name: CR_375

Address: 2229 NW Troost St

TruncDomes:

Comments: Non compliant ramp no landing, cabinet at bow

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.2

S4_RampCrossSlope: 5.9

S5_WingSlope1: 9.2

S6_WingSlope2: 20.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_376





OBJECTID (Perpendicular Ramp): 288

Name: CR_376

Address: 2022 NW Troost St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.1

S4_RampCrossSlope: 5.4

S5_WingSlope1: 4.2


S6_WingSlope2: 20.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_381





OBJECTID (Perpendicular Ramp): 293

Name: CR_381

Address: 1612 NW Troost St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 0.3

S5_WingSlope1: 13.3

S6_WingSlope2: 13.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_455





OBJECTID (Perpendicular Ramp): 367

Name: CR_455

Address: 2350 NW Troost St

TruncDomes: True

Comments:

D1_LandingDim1: 5.2

D2_LandingDim2: 3.9

D3_RampWidth: 5.2

S1_LandingSlope1: 1.7

S2_LandingSlope2: 4.6

S3_RampSlope: 6.5

S4_RampCrossSlope: 4.5

S5_WingSlope1: 1.3

S6_WingSlope2: 15.3

S7_CounterSlope: 10.9

GutterSlope: 10.0

LipHeight:

CR_456





OBJECTID (Perpendicular Ramp): 368

Name: CR_456

Address: 2449 NW Troost St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.5

D3_RampWidth: 5.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 12.0

S3_RampSlope: 6.0

S4_RampCrossSlope: 9.0

S5_WingSlope1: 23.2


S6_WingSlope2: 7.3

S7_CounterSlope: 12.5

GutterSlope: 13.9

LipHeight:

CR_459





OBJECTID (Perpendicular Ramp): 371

Name: CR_459

Address: 2270 NW Troost St

TruncDomes: True

Comments: Light pole in landing. On garden valley

D1_LandingDim1: 5.7

D2_LandingDim2: 3.1

D3_RampWidth: 5.7

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.6

S3_RampSlope: 6.2

S4_RampCrossSlope: 0.5

S5_WingSlope1: 6.6

S6_WingSlope2: 6.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_460





OBJECTID (Perpendicular Ramp): 372

Name: CR_460

Address: 2270 NW Troost St

TruncDomes: True

Comments: On troost

D1_LandingDim1: 5.2

D2_LandingDim2: 4.1

D3_RampWidth: 5.2

S1_LandingSlope1: 1.3

S2_LandingSlope2: 0.2

S3_RampSlope: 8.2

S4_RampCrossSlope: 0.5

S5_WingSlope1: 6.0


S6_WingSlope2: 9.7

S7_CounterSlope: 5.7

GutterSlope: 0.3

LipHeight:

CR_461





OBJECTID (Perpendicular Ramp): 373

Name: CR_461

Address: 2270 NW Troost St

TruncDomes: True

Comments: On troost

D1_LandingDim1: 5.0

D2_LandingDim2: 4.1

D3_RampWidth: 5.0

S1_LandingSlope1: 3.1

S2_LandingSlope2: 3.5

S3_RampSlope: 7.1

S4_RampCrossSlope: 2.9

S5_WingSlope1: 14.1


S6_WingSlope2: 2.8

S7_CounterSlope: 10.4

GutterSlope: 4.7

LipHeight:

CR_462





OBJECTID (Perpendicular Ramp): 374

Name: CR_462

Address: 2270 NW Troost St

TruncDomes: True

Comments: On garden valley

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth: 5.0

S1_LandingSlope1: 3.9

S2_LandingSlope2: 3.7

S3_RampSlope: 9.8

S4_RampCrossSlope: 2.0

S5_WingSlope1: 12.9

S6_WingSlope2: 9.3

S7_CounterSlope: 11.2

GutterSlope: 2.6

LipHeight:

CR_463





OBJECTID (Perpendicular Ramp): 375

Name: CR_463

Address: 2022 NW Troost St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.4

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 4.8

S5_WingSlope1: 6.8


S6_WingSlope2: 17.9

S7_CounterSlope:

GutterSlope:

LipHeight: 0.5

CR_466





OBJECTID (Perpendicular Ramp): 378

Name: CR_466

Address: 1950 NW Troost St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 1.0

S5_WingSlope1: 8.6


S6_WingSlope2: 15.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_468





OBJECTID (Perpendicular Ramp): 380

Name: CR_468

Address: 1632 NW Troost St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 4.6

S5_WingSlope1: 12.2


S6_WingSlope2: 27.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_861



OBJECTID (Unclassified Ramp): 36 **Address:** 1490 NW Valley View Dr

Name: CR_861

CR_768





OBJECTID (Parallel Ramp): 45

Name: CR_768

Address: 1490 NW Valley View Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 6.1

S1_LandingSlope1: 3.3

S2_LandingSlope2: 4.4

S3_RampCrossSlope1: 3.9

S4_RampSlope1: 10.0

S5_RampCrossSlope2: 1.7

S6_RampSlope2: 5.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_344





OBJECTID (Perpendicular Ramp): 256

Name: CR_344

Address: 1490 NW Valley View Dr

TruncDomes: True

Comments: On valley view

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 3.9

S1_LandingSlope1: 2.4

S2_LandingSlope2: 2.0

S3_RampSlope: 7.4

S4_RampCrossSlope: 0.4

S5_WingSlope1: 7.6

S6_WingSlope2: 6.8

S7_CounterSlope: 10.4

GutterSlope: 1.3

LipHeight:

CR_352





OBJECTID (Perpendicular Ramp): 264

Name: CR_352

Address: 1714 NW Valley View Dr

TruncDomes:

Comments: Power pole in landing, non compliant

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.5

S2_LandingSlope2: 4.3

S3_RampSlope: 8.4

S4_RampCrossSlope: 5.8

S5_WingSlope1: 16.0


S6_WingSlope2: 4.9

S7_CounterSlope: 12.9

GutterSlope: 3.4

LipHeight:

CR_428





OBJECTID (Perpendicular Ramp): 340

Name: CR_428

Address: 1490 NW Valley View Dr

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 2.6

S2_LandingSlope2: 1.5

S3_RampSlope: 7.3

S4_RampCrossSlope: 1.5

S5_WingSlope1: 6.3

S6_WingSlope2: 9.7

S7_CounterSlope: 8.4

GutterSlope:

LipHeight:

CR_780





OBJECTID (Parallel Ramp): 57

Name: CR_780

Address: 1882 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 3.7

D2_LandingDim2: 5.8

S1_LandingSlope1: 1.9

S2_LandingSlope2: 7.2

S3_RampCrossSlope1: 2.6

S4_RampSlope1: 13.5

S5_RampCrossSlope2: 0.8

S6_RampSlope2: 4.8

S7_CounterSlope: 8.4

GutterSlope: 6.2

LipHeight:

CR_782





OBJECTID (Parallel Ramp): 59

Name: CR_782

Address: 2152 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 4.5

D2_LandingDim2: 6.0

S1_LandingSlope1: 0.3

S2_LandingSlope2: 9.2

S3_RampCrossSlope1: 1.6

S4_RampSlope1: 17.1

S5_RampCrossSlope2: 1.6


S6_RampSlope2: 2.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_786





OBJECTID (Parallel Ramp): 63

Name: CR_786

Address: 1912 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 4.0

D2_LandingDim2: 5.8

S1_LandingSlope1: 0.5

S2_LandingSlope2: 4.5

S3_RampCrossSlope1: 2.5

S4_RampSlope1: 1.7

S5_RampCrossSlope2: 0.6

S6_RampSlope2: 12.4

S7_CounterSlope: 8.4

GutterSlope: 4.4

LipHeight:

CR_787





OBJECTID (Parallel Ramp): 64

Name: CR_787

Address: 1882 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 6.0

S1_LandingSlope1: 4.3

S2_LandingSlope2: 0.9

S3_RampCrossSlope1: 3.6

S4_RampSlope1: 9.3

S5_RampCrossSlope2: 4.9

S6_RampSlope2: 6.0

S7_CounterSlope: 7.9

GutterSlope: 1.0

LipHeight:

CR_508





OBJECTID (Perpendicular Ramp): 420

Name: CR_508

Address: 1723 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 1.6

S2_LandingSlope2: 8.5

S3_RampSlope: 9.8

S4_RampCrossSlope: 8.4

S5_WingSlope1: 6.0


S6_WingSlope2: 14.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_510





OBJECTID (Perpendicular Ramp): 422

Name: CR_510

Address: 2160 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2: 5.2

S3_RampSlope: 4.8

S4_RampCrossSlope: 5.2

S5_WingSlope1: 10.9


S6_WingSlope2: 3.7

S7_CounterSlope: 10.2

GutterSlope: 2.2

LipHeight:

CR_549





OBJECTID (Perpendicular Ramp): 461

Name: CR_549

Address: 1562 NE Vine St

TruncDomes:

Comments:

D1_LandingDim1: 4.6

D2_LandingDim2: 3.0

D3_RampWidth: 5.1

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.3

S3_RampSlope: 8.0

S4_RampCrossSlope: 2.4

S5_WingSlope1: 12.3


S6_WingSlope2: 7.2

S7_CounterSlope: 7.7

GutterSlope: 2.4

LipHeight:

CR_551





OBJECTID (Perpendicular Ramp): 463

Name: CR_551

Address: 1723 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 3.0

S2_LandingSlope2: 6.9

S3_RampSlope: 10.6

S4_RampCrossSlope: 6.2

S5_WingSlope1: 14.7

S6_WingSlope2: 2.2

S7_CounterSlope: 8.1

GutterSlope: 4.9

LipHeight:

CR_553





OBJECTID (Perpendicular Ramp): 465

Name: CR_553

Address: 2152 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 4.6

D2_LandingDim2: 4.0

D3_RampWidth: 4.7

S1_LandingSlope1: 2.0

S2_LandingSlope2: 4.7

S3_RampSlope: 14.5

S4_RampCrossSlope: 4.6

S5_WingSlope1: 11.7

S6_WingSlope2: 16.3

S7_CounterSlope: 4.2

GutterSlope: 3.3

LipHeight:

CR_554





OBJECTID (Perpendicular Ramp): 466

Name: CR_554

Address: 2162 NE Vine St

TruncDomes: True

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

D3_RampWidth: 5.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 1.2

S3_RampSlope: 15.4

S4_RampCrossSlope: 0.8

S5_WingSlope1: 14.0

S6_WingSlope2: 12.8

S7_CounterSlope: 8.5

GutterSlope: 1.4

LipHeight:

CR_54





OBJECTID (Combination Ramp): 7

Name: CR_54

Address: 2225 SE Waldon Ave

TruncDomes:

Comments:

D1_LandingDim1: 4.6

D2_LandingDim2: 4.0

D3_RampWidth2: 5.9

D4_RampWidth3: 5.9

D5_RampWidth1: 5.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 3.3

S3_RampCrossSlope2: 1.0

S4_RampSlope2: 3.3

S5_RampCrossSlope3: 3.7

S6_RampSlope3: 9.7

S7_RampSlope1: 4.1

S8_RampCrossSlope1: 3.8

S9_WingSlope1: 6.3

S10_WingSlope2: 11.1

S11_CounterSlope: 13.8

GutterSlope: 2.9

LipHeight:

CR_514





OBJECTID (Perpendicular Ramp): 426

Name: CR_514

Address: 1117 NE Walnut St

TruncDomes:

Comments: On walnut

D1_LandingDim1: 2.0

D2_LandingDim2: 5.2

D3_RampWidth: 4.3

S1_LandingSlope1: 0.1

S2_LandingSlope2: 5.9

S3_RampSlope: 9.7

S4_RampCrossSlope: 7.3

S5_WingSlope1: 9.8


S6_WingSlope2: 11.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_515





OBJECTID (Perpendicular Ramp): 427

Name: CR_515

Address: 1117 NE Walnut St

TruncDomes:

Comments: On chestnut

D1_LandingDim1: 2.9

D2_LandingDim2: 3.9

D3_RampWidth: 3.9

S1_LandingSlope1: 1.1

S2_LandingSlope2: 6.9

S3_RampSlope: 8.7

S4_RampCrossSlope: 3.4

S5_WingSlope1: 6.1


S6_WingSlope2: 11.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_516





OBJECTID (Perpendicular Ramp): 428

Name: CR_516

Address: 1086 NE Walnut St

TruncDomes:

Comments: On chestnut

D1_LandingDim1: 3.3

D2_LandingDim2: 3.2

D3_RampWidth: 4.1

S1_LandingSlope1: 0.5

S2_LandingSlope2: 1.3

S3_RampSlope: 8.3

S4_RampCrossSlope: 2.4

S5_WingSlope1: 12.7


S6_WingSlope2: 6.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_517





OBJECTID (Perpendicular Ramp): 429

Name: CR_517

Address: 1086 NE Walnut St

TruncDomes:

Comments: On walnut

D1_LandingDim1: 3.6

D2_LandingDim2: 4.6

D3_RampWidth: 4.0

S1_LandingSlope1: 0.6

S2_LandingSlope2: 2.1

S3_RampSlope: 2.2

S4_RampCrossSlope: 1.0

S5_WingSlope1: 0.3


S6_WingSlope2: 9.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_521





OBJECTID (Perpendicular Ramp): 433

Name: CR_521

Address: 1217 NE Walnut St

TruncDomes:

Comments: On ward

D1_LandingDim1: 3.3

D2_LandingDim2: 4.4

D3_RampWidth: 4.0

S1_LandingSlope1: 0.8

S2_LandingSlope2: 4.9

S3_RampSlope: 7.2

S4_RampCrossSlope: 4.2

S5_WingSlope1: 5.0

S6_WingSlope2: 11.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_522





OBJECTID (Perpendicular Ramp): 434

Name: CR_522

Address: 1217 NE Walnut St

TruncDomes:

Comments: On walnut

D1_LandingDim1: 3.0

D2_LandingDim2: 4.6

D3_RampWidth: 4.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 3.8

S3_RampSlope: 7.2

S4_RampCrossSlope: 6.3

S5_WingSlope1: 3.4


S6_WingSlope2: 8.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_523





OBJECTID (Perpendicular Ramp): 435

Name: CR_523

Address: 1217 NE Walnut St

TruncDomes:

Comments: On walnut

D1_LandingDim1: 4.0

D2_LandingDim2: 2.6

D3_RampWidth: 3.4

S1_LandingSlope1: 1.8

S2_LandingSlope2: 0.6

S3_RampSlope: 12.3

S4_RampCrossSlope: 1.4

S5_WingSlope1: 15.0


S6_WingSlope2: 7.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_524





OBJECTID (Perpendicular Ramp): 436

Name: CR_524

Address: 1217 NE Walnut St

TruncDomes:

Comments: On ward

D1_LandingDim1: 3.7

D2_LandingDim2: 4.8

D3_RampWidth: 4.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 2.0

S3_RampSlope: 11.1

S4_RampCrossSlope: 0.3

S5_WingSlope1: 5.7


S6_WingSlope2: 8.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_526





OBJECTID (Perpendicular Ramp): 438

Name: CR_526

Address: 1186 NE Walnut St

TruncDomes:

Comments: On walnut

D1_LandingDim1: 3.4

D2_LandingDim2: 3.3

D3_RampWidth: 4.0

S1_LandingSlope1: 4.5

S2_LandingSlope2: 4.9

S3_RampSlope: 11.0

S4_RampCrossSlope: 2.6

S5_WingSlope1: 10.5

S6_WingSlope2: 9.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_527





OBJECTID (Perpendicular Ramp): 439

Name: CR_527

Address: 1186 NE Walnut St

TruncDomes:

Comments: On ward

D1_LandingDim1: 4.0

D2_LandingDim2: 5.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.3

S2_LandingSlope2: 3.3

S3_RampSlope: 11.0

S4_RampCrossSlope: 4.2

S5_WingSlope1: 15.3


S6_WingSlope2: 6.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_528





OBJECTID (Perpendicular Ramp): 440

Name: CR_528

Address: 1186 NE Walnut St

TruncDomes:

Comments: On walnut

D1_LandingDim1: 4.0

D2_LandingDim2: 4.0

D3_RampWidth: 4.0

S1_LandingSlope1: 1.2

S2_LandingSlope2: 1.9

S3_RampSlope: 11.3

S4_RampCrossSlope: 1.2

S5_WingSlope1: 8.8


S6_WingSlope2: 6.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_529





OBJECTID (Perpendicular Ramp): 441

Name: CR_529

Address: 1376 NE Walnut St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.3

S4_RampCrossSlope: 3.1

S5_WingSlope1: 11.8

S6_WingSlope2: 12.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_530





OBJECTID (Perpendicular Ramp): 442

Name: CR_530

Address: 1376 NE Walnut St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2: 4.2

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.9

S4_RampCrossSlope: 0.3

S5_WingSlope1: 17.1

S6_WingSlope2: 12.8

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_558





OBJECTID (Perpendicular Ramp): 470

Name: CR_558

Address: 1117 NE Walnut St

TruncDomes:

Comments: On walnut

D1_LandingDim1: 3.0

D2_LandingDim2: 4.2

D3_RampWidth: 3.8

S1_LandingSlope1: 1.8

S2_LandingSlope2:

S3_RampSlope: 13.7

S4_RampCrossSlope: 1.6

S5_WingSlope1: 12.9


S6_WingSlope2: 11.0

S7_CounterSlope: 6.5

GutterSlope: 0.2

LipHeight:

CR_559





OBJECTID (Perpendicular Ramp): 471

Name: CR_559

Address: 1117 NE Walnut St

TruncDomes:

Comments: On chestnut

D1_LandingDim1: 3.0

D2_LandingDim2: 4.8

D3_RampWidth: 4.0

S1_LandingSlope1: 3.2

S2_LandingSlope2: 0.9

S3_RampSlope: 14.3

S4_RampCrossSlope: 1.0

S5_WingSlope1: 11.6


S6_WingSlope2: 13.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_424





OBJECTID (Perpendicular Ramp): 336

Name: CR_424

Address: 1612 NW Wanell St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 2.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.1

S4_RampCrossSlope: 15.0

S5_WingSlope1: 15.7


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_525





OBJECTID (Perpendicular Ramp): 437

Name: CR_525

Address: 447 NE Ward Ave

TruncDomes:

Comments: On ward

D1_LandingDim1: 3.9

D2_LandingDim2: 3.6

D3_RampWidth: 4.0

S1_LandingSlope1: 0.9

S2_LandingSlope2: 4.3

S3_RampSlope: 10.5

S4_RampCrossSlope: 2.8

S5_WingSlope1: 13.9


S6_WingSlope2: 7.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_566





OBJECTID (Perpendicular Ramp): 478

Name: CR_566

Address: 228 NE Ward Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.5

S4_RampCrossSlope: 1.7

S5_WingSlope1: 23.2


S6_WingSlope2: 15.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_567





OBJECTID (Perpendicular Ramp): 479

Name: CR_567

Address: 228 NE Ward Ave

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 6.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.7

S4_RampCrossSlope: 3.9

S5_WingSlope1: 18.8

S6_WingSlope2: 24.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_30





OBJECTID (Bus Stop-Median): 30

Name: CR_30

Address: 908 SE Washington Ave

Comments: On main

D1_LandingDim1: 6.1

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.0

S2_LandingSlope2: 0.4

CR_31





OBJECTID (Bus Stop-Median): 31

Name: CR_31

Address: 908 SE Washington Ave

Comments: ON Washington


D1_LandingDim1: 5.9

D2_LandingDim2: 4.0

S1_LandingSlope1: 1.4

S2_LandingSlope2: 0.1

CR_32





OBJECTID (Bus Stop-Median): 32

Name: CR_32

Address: 908 SE Washington Ave

Comments: On washington


D1_LandingDim1: 4.9


D2_LandingDim2: 4.0

S1_LandingSlope1: 0.4

S2_LandingSlope2: 0.7

CR_33





OBJECTID (Bus Stop-Median): 33

Name: CR_33

Address: 908 SE Washington Ave

Comments: On main

D1_LandingDim1: 5.0

D2_LandingDim2: 4.0

S1_LandingSlope1: 0.1

S2_LandingSlope2: 0.5

CR_702





OBJECTID (Perpendicular Ramp): 614

Name: CR_702

Address: 625 W Wharton St

TruncDomes:

Comments: No landing. Hydrant in landing area

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.8

S4_RampCrossSlope: 1.8

S5_WingSlope1: 19.3

S6_WingSlope2: 17.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_392





OBJECTID (Perpendicular Ramp): 304

Name: CR_392

Address: 506 Wide Ave

TruncDomes:

Comments: Broad st Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.6

S4_RampCrossSlope: 1.8

S5_WingSlope1: 3.8

S6_WingSlope2: 12.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_483





OBJECTID (Perpendicular Ramp): 395

Name: CR_483

Address: 506 Wide Ave

TruncDomes:

Comments: Broad. No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.1

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.9

S4_RampCrossSlope: 2.2

S5_WingSlope1: 7.4

S6_WingSlope2: 7.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_885





OBJECTID (Unclassified Ramp): 60 **Address:** 931 NE Winchester St

Name: CR_885

CR_785





OBJECTID (Parallel Ramp): 62

Name: CR_785

Address: 403 NE Winchester St

TruncDomes:

Comments: Detectable warning strips

D1_LandingDim1: 6.0

D2_LandingDim2: 5.0

S1_LandingSlope1: 5.2

S2_LandingSlope2: 0.7

S3_RampCrossSlope1: 2.4

S4_RampSlope1: 5.2

S5_RampCrossSlope2: 1.8

S6_RampSlope2: 8.8

S7_CounterSlope: 5.3

GutterSlope: 0.4

LipHeight:

CR_912





OBJECTID (Unclassified Ramp): 87 **Address:** 931 NE Winchester St

Name: CR_912

CR_496





OBJECTID (Perpendicular Ramp): 408

Name: CR_496

Address: 368 NE Winchester St

TruncDomes:

Comments: Hydrant in wing

D1_LandingDim1: 3.2

D2_LandingDim2: 3.8

D3_RampWidth: 3.2

S1_LandingSlope1: 6.4

S2_LandingSlope2: 1.5

S3_RampSlope: 5.8

S4_RampCrossSlope: 3.5

S5_WingSlope1: 13.1

S6_WingSlope2: 6.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_497





OBJECTID (Perpendicular Ramp): 409

Name: CR_497

Address: 452 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.6

S4_RampCrossSlope: 2.9

S5_WingSlope1: 19.2

S6_WingSlope2: 8.4

S7_CounterSlope: 4.4

GutterSlope:

LipHeight:

CR_498





OBJECTID (Perpendicular Ramp): 410

Name: CR_498

Address: 427 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.7

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.0

S4_RampCrossSlope: 6.5

S5_WingSlope1: 14.9

S6_WingSlope2: 12.4

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_499





OBJECTID (Perpendicular Ramp): 411

Name: CR_499

Address: 508 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.2

S4_RampCrossSlope: 9.2

S5_WingSlope1: 15.8

S6_WingSlope2: 4.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_500





OBJECTID (Perpendicular Ramp): 412

Name: CR_500

Address: 508 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 7.2

S5_WingSlope1: 16.0

S6_WingSlope2: 7.3

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_501





OBJECTID (Perpendicular Ramp): 413

Name: CR_501

Address: 577 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 12.5

S4_RampCrossSlope: 9.0

S5_WingSlope1: 19.0


S6_WingSlope2: 8.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_502





OBJECTID (Perpendicular Ramp): 414

Name: CR_502

Address: 596 NE Winchester St

TruncDomes:

Comments: No landig

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.5

S4_RampCrossSlope: 8.6

S5_WingSlope1: 16.7

S6_WingSlope2: 3.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_503





OBJECTID (Perpendicular Ramp): 415

Name: CR_503

Address: 692 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.5

S4_RampCrossSlope: 15.9

S5_WingSlope1: 23.8

S6_WingSlope2: 4.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_504





OBJECTID (Perpendicular Ramp): 416

Name: CR_504

Address: 931 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.9

S4_RampCrossSlope: 1.2

S5_WingSlope1: 11.3


S6_WingSlope2: 12.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_541





OBJECTID (Perpendicular Ramp): 453

Name: CR_541

Address: 403 NE Winchester St

TruncDomes: True

Comments: Non compliant ramp no landing, detectable warning strips

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 14.7

S4_RampCrossSlope: 1.1

S5_WingSlope1: 11.3

S6_WingSlope2: 5.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_542





OBJECTID (Perpendicular Ramp): 454

Name: CR_542

Address: 407 NE Winchester St

TruncDomes: True

Comments: Detectable warning strips

D1_LandingDim1: 4.0

D2_LandingDim2: 5.7

D3_RampWidth: 4.0

S1_LandingSlope1: 2.2

S2_LandingSlope2: 7.5

S3_RampSlope: 7.4

S4_RampCrossSlope: 3.5

S5_WingSlope1: 2.8

S6_WingSlope2: 10.5

S7_CounterSlope: 0.4

GutterSlope: 4.0

LipHeight:

CR_543





OBJECTID (Perpendicular Ramp): 455

Name: CR_543

Address: 477 NE Winchester St

TruncDomes: True

Comments: Non compliant ramp no landing Detectable warning strips

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.0

S4_RampCrossSlope: 2.4

S5_WingSlope1: 2.3

S6_WingSlope2: 12.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_544





OBJECTID (Perpendicular Ramp): 456

Name: CR_544

Address: 508 NE Winchester St

TruncDomes: True

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.3

S4_RampCrossSlope: 4.2

S5_WingSlope1: 7.7

S6_WingSlope2: 11.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_545





OBJECTID (Perpendicular Ramp): 457

Name: CR_545

Address: 613 NE Winchester St

TruncDomes: True

Comments: Detectable warning strips Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 5.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.1

S4_RampCrossSlope: 4.0

S5_WingSlope1: 5.1

S6_WingSlope2: 7.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_546





OBJECTID (Perpendicular Ramp): 458

Name: CR_546

Address: 613 NE Winchester St

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.5

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.9

S4_RampCrossSlope: 11.8

S5_WingSlope1: 3.3


S6_WingSlope2: 18.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_547





OBJECTID (Perpendicular Ramp): 459

Name: CR_547

Address: 713 NE Winchester St

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 11.1

S4_RampCrossSlope: 10.2

S5_WingSlope1: 21.2

S6_WingSlope2: 3.1

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_645





OBJECTID (Perpendicular Ramp): 557

Name: CR_645

Address: 931 NE Winchester St

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1: 9.4

S2_LandingSlope2: 6.9

S3_RampSlope: 21.3

S4_RampCrossSlope: 3.9

S5_WingSlope1: 5.0


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_648





OBJECTID (Perpendicular Ramp): 560

Name: CR_648

Address: 508 NE Winchester St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 13.4

S4_RampCrossSlope: 4.4

S5_WingSlope1: 24.4

S6_WingSlope2: 3.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_649





OBJECTID (Perpendicular Ramp): 561

Name: CR_649

Address: 508 NE Winchester St

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 7.1

S4_RampCrossSlope: 0.8

S5_WingSlope1: 13.1

S6_WingSlope2: 11.0

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_684





OBJECTID (Perpendicular Ramp): 596

Name: CR_684

Address: 931 NE Winchester St

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.8

S4_RampCrossSlope: 2.5

S5_WingSlope1: 4.7

S6_WingSlope2: 14.5

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_685





OBJECTID (Perpendicular Ramp): 597

Name: CR_685

Address: 931 NE Winchester St

TruncDomes:

Comments: No compliant landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.3

S1_LandingSlope1: 10.7

S2_LandingSlope2: 7.8

S3_RampSlope: 5.0

S4_RampCrossSlope: 7.8

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_467





OBJECTID (Perpendicular Ramp): 379

Name: CR_467

Address: 2020 NW Witherspoon Ave

TruncDomes:

Comments: No landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 6.9

S4_RampCrossSlope: 0.4

S5_WingSlope1: 16.2

S6_WingSlope2: 12.3

S7_CounterSlope:

GutterSlope:

LipHeight: 0.5

CR_883






OBJECTID (Unclassified Ramp): 58 **Address:** 3101 W Woodside Ave

Name: CR_883

CR_364





OBJECTID (Perpendicular Ramp): 276

Name: CR_364

Address: 116 Woodwillow Dr

TruncDomes:

Comments: Non compliant ramp no landing , 1.5" lip between panels

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.8

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 8.8

S4_RampCrossSlope: 6.8

S5_WingSlope1: 1.6

S6_WingSlope2: 16.7

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_365





OBJECTID (Perpendicular Ramp): 277

Name: CR_365

Address: 116 Woodwillow Dr

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 9.3

S4_RampCrossSlope: 5.5

S5_WingSlope1: 4.2

S6_WingSlope2: 9.2

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_366





OBJECTID (Perpendicular Ramp): 278

Name: CR_366

Address: 1401 Woodwillow Dr

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 3.0

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.8

S4_RampCrossSlope: 11.9

S5_WingSlope1: 2.8

S6_WingSlope2: 16.9

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_367





OBJECTID (Perpendicular Ramp): 279

Name: CR_367

Address: 1401 Woodwillow Dr

TruncDomes:

Comments: Non compliant ramp no landing

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth: 4.2

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope: 10.1

S4_RampCrossSlope: 5.7

S5_WingSlope1: 0.7

S6_WingSlope2: 8.6

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_450





OBJECTID (Perpendicular Ramp): 362

Name: CR_450

Address: 1401 Woodwillow Dr

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth: 5.0

S1_LandingSlope1: 2.5

S2_LandingSlope2: 11.6

S3_RampSlope: 13.1

S4_RampCrossSlope: 9.6

S5_WingSlope1: 17.9

S6_WingSlope2: 1.5

S7_CounterSlope: 7.2

GutterSlope:

LipHeight:

CR_451





OBJECTID (Perpendicular Ramp): 363

Name: CR_451

Address: 1401 Woodwillow Dr

TruncDomes:

Comments:

D1_LandingDim1: 5.0

D2_LandingDim2: 3.9

D3_RampWidth: 5.0

S1_LandingSlope1: 2.1

S2_LandingSlope2: 8.2

S3_RampSlope: 9.2

S4_RampCrossSlope: 6.5

S5_WingSlope1: 15.9

S6_WingSlope2: 8.7

S7_CounterSlope: 15.3

GutterSlope:

LipHeight:

CR_0





OBJECTID (Bus Stop-Median): 1

Name: CR_0

Address: 410 SE Spruce St

GeoStreet: Spruce

Compliant: Verify

Comments:


D1_LandingDim1:


D2_LandingDim2:

S1_LandingSlope1:

S2_LandingSlope2:

CR_1





OBJECTID (Combination Ramp): 2

Name: CR_1

Address: 1228 NE Klamath Ave

GeoStreet: Klamath

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_2





OBJECTID (Combination Ramp): 3

Name: CR_2

Address: 1314 NE Odell Ave

GeoStreet: Odell

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_3





OBJECTID (Combination Ramp): 4

Name: CR_3

Address: 1360 NE Klamath Ave

GeoStreet: Klamath

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_4





OBJECTID (Combination Ramp): 5

Name: CR_4

Address: 1760 NE Freemont Ave

GeoStreet: Freemont

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_5





OBJECTID (Combination Ramp): 6

Name: CR_5

Address: 750 SE Flint St

GeoStreet: Flint

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_6





OBJECTID (Combination Ramp): 7

Name: CR_6

Address: 260 SE Lane Ave

GeoStreet: Lane

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_7





OBJECTID (Combination Ramp): 8

Name: CR_7

Address: 805 SE Flint St

GeoStreet: Flint

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_8





OBJECTID (Combination Ramp): 9

Name: CR_8

Address: 805 SE Flint St

GeoStreet: Flint

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_9





OBJECTID (Combination Ramp): 14

Name: CR_9

Address: 1037 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_10





OBJECTID (Combination Ramp): 15

Name: CR_10

Address: 211 SE Miller Ave

GeoStreet: Miller

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:


S11_CounterSlope:

GutterSlope:

LipHeight:

CR_11





OBJECTID (Combination Ramp): 16

Name: CR_11

Address: 192 SE Miller Ave

GeoStreet: Miller

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_12





OBJECTID (Combination Ramp): 17

Name: CR_12

Address: 192 SE Miller Ave

GeoStreet: Miller

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_13





OBJECTID (Combination Ramp): 18

Name: CR_13

Address: 1138 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_14





OBJECTID (Combination Ramp): 19

Name: CR_14

Address: 1210 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_15





OBJECTID (Combination Ramp): 20

Name: CR_15

Address: 1138 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_16





OBJECTID (Combination Ramp): 21

Name: CR_16

Address: 1210 SE Fullerton St

GeoStreet: Fullerton

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_17





OBJECTID (Combination Ramp): 22

Name: CR_17

Address: 1240 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_18





OBJECTID (Combination Ramp): 23

Name: CR_18

Address: 1302 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:


S11_CounterSlope:

GutterSlope:

LipHeight:

CR_19





OBJECTID (Combination Ramp): 24

Name: CR_19

Address: 1240 SE Fullerton St

GeoStreet: Fullerton

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_20





OBJECTID (Combination Ramp): 25

Name: CR_20

Address: 1302 SE Fullerton St

GeoStreet: Fullerton

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_21





OBJECTID (Combination Ramp): 26

Name: CR_21

Address: 934 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_22





OBJECTID (Combination Ramp): 27

Name: CR_22

Address: 934 SE Fullerton St

GeoStreet: Fullerton

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_23





OBJECTID (Combination Ramp): 28

Name: CR_23

Address: 1006 SE Fullerton St

GeoStreet: Fullerton

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_24





OBJECTID (Combination Ramp): 29

Name: CR_24

Address: 1006 SE Fullerton St

GeoStreet: Fullerton

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_25





OBJECTID (Combination Ramp): 33

Name: CR_25

Address: 305 SE Pitzer St

GeoStreet: Pitzer

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_26





OBJECTID (Combination Ramp): 34

Name: CR_26

Address: 276 SE Pitzer St

GeoStreet: Pitzer

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_27





OBJECTID (Combination Ramp): 35

Name: CR_27

Address: 276 SE Pitzer St

GeoStreet: Pitzer

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_28





OBJECTID (Combination Ramp): 38

Name: CR_28

Address: 485 SE Kane St

GeoStreet: Kane

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_29





OBJECTID (Combination Ramp): 39

Name: CR_29

Address: 1071 SE Washington Ave

GeoStreet: Washington

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_30





OBJECTID (Combination Ramp): 40

Name: CR_30

Address: 485 SE Kane St

GeoStreet: Kane

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_31





OBJECTID (Combination Ramp): 41

Name: CR_31

Address: 485 SE Kane St

GeoStreet: Kane

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_32





OBJECTID (Combination Ramp): 50

Name: CR_32

Address: 729 SE Washington Ave

GeoStreet: Washington

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:


S11_CounterSlope:

GutterSlope:

LipHeight:

CR_33





OBJECTID (Combination Ramp): 51

Name: CR_33

Address: 729 SE Washington Ave

GeoStreet: Washington

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_34





OBJECTID (Combination Ramp): 52

Name: CR_34

Address: 729 SE Washington Ave

GeoStreet: Washington

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_35





OBJECTID (Combination Ramp): 53

Name: CR_35

Address: 729 SE Washington Ave

GeoStreet: Washington

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:


S11_CounterSlope:

GutterSlope:

LipHeight:

CR_36





OBJECTID (Combination Ramp): 54

Name: CR_36

Address: 1257 SE Mill St

GeoStreet: Mill

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_37





OBJECTID (Combination Ramp): 55

Name: CR_37

Address: 1342 SE Mill St

GeoStreet: Mill

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_38





OBJECTID (Combination Ramp): 56

Name: CR_38

Address: 1505 SE Mill St

GeoStreet: Mill

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_39





OBJECTID (Combination Ramp): 57

Name: CR_39

Address: 433 SE Burke Ave

GeoStreet: Burke

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_40





OBJECTID (Combination Ramp): 61

Name: CR_40

Address: 813 SE Oak Ave

GeoStreet: Oak

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_41





OBJECTID (Combination Ramp): 62

Name: CR_41

Address: 522 SE Rose St

GeoStreet: Rose

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_42





OBJECTID (Combination Ramp): 63

Name: CR_42

Address: 522 SE Rose St

GeoStreet: Rose

Compliant: Verify

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_43





OBJECTID (Combination Ramp): 64

Name: CR_43

Address: 721 SE Oak Ave

GeoStreet: Oak

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:


S11_CounterSlope:

GutterSlope:

LipHeight:

CR_44





OBJECTID (Combination Ramp): 66

Name: CR_44

Address: 555 SE Kane St

GeoStreet: Kane

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:


S11_CounterSlope:

GutterSlope:

LipHeight:

CR_45





OBJECTID (Combination Ramp): 67

Name: CR_45

Address: 1035 SE Oak Ave

GeoStreet: Oak

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:

S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_46





OBJECTID (Combination Ramp): 68

Name: CR_46

Address: 1133 SE Cass Ave

GeoStreet: Cass

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_47





OBJECTID (Combination Ramp): 69

Name: CR_47

Address: 1138 SE Cass Ave

GeoStreet: Cass

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth2:

D4_RampWidth3:

D5_RampWidth1:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampCrossSlope2:

S4_RampSlope2:

S5_RampCrossSlope3:

S6_RampSlope3:

S7_RampSlope1:

S8_RampCrossSlope1:

S9_WingSlope1:


S10_WingSlope2:

S11_CounterSlope:

GutterSlope:

LipHeight:

CR_48





OBJECTID (Perpendicular Ramp): 1

Name: CR_48

Address: 18880 SW Martinazzi Ave

GeoStreet: Martinazzi

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_49





OBJECTID (Perpendicular Ramp): 2

Name: CR_49

Address: 1132 W Harris Hills Dr

GeoStreet: Harris Hills

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_50





OBJECTID (Perpendicular Ramp): 3

Name: CR_50

Address: 1171 W Harris Hills Dr

GeoStreet: Harris Hills

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_51





OBJECTID (Perpendicular Ramp): 4

Name: CR_51

Address: 3101 W Rosemary Ave

GeoStreet: Rosemary

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_52





OBJECTID (Perpendicular Ramp): 5

Name: CR_52

Address: 1610 W Tarragon Dr

GeoStreet: Tarragon

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_53





OBJECTID (Perpendicular Ramp): 6

Name: CR_53

Address: 3111 W Woodside Ave

GeoStreet: Woodside

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_54





OBJECTID (Perpendicular Ramp): 7

Name: CR_54

Address: 169 W Broccoli St

GeoStreet: Broccoli

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_55





OBJECTID (Perpendicular Ramp): 8

Name: CR_55

Address: 1489 NW Grove St

GeoStreet: Grove

Compliant: No

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_56





OBJECTID (Perpendicular Ramp): 9

Name: CR_56

Address: 1489 NW Grove St

GeoStreet: Grove

Compliant: No

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_57





OBJECTID (Perpendicular Ramp): 10

Name: CR_57

Address: 1499 NW Grove St

GeoStreet: Grove

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_58





OBJECTID (Perpendicular Ramp): 11

Name: CR_58

Address: 2271 NW Chambers Dr

GeoStreet: Chambers

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_59





OBJECTID (Perpendicular Ramp): 12

Name: CR_59

Address: 2680 NW Loma Vista Dr

GeoStreet: Loma Vista

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_60





OBJECTID (Perpendicular Ramp): 13

Name: CR_60

Address: 1560 NW Avery St

GeoStreet: Avery

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_61





OBJECTID (Perpendicular Ramp): 14

Name: CR_61

Address: 1584 NW Avery St

GeoStreet: Avery

Compliant: Verify

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_62





OBJECTID (Perpendicular Ramp): 15

Name: CR_62

Address: 2375 NW Lila Ct

GeoStreet: Lila

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_63





OBJECTID (Perpendicular Ramp): 16

Name: CR_63

Address: 1700 NW Avery St

GeoStreet: Avery

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_64





OBJECTID (Perpendicular Ramp): 17

Name: CR_64

Address: 2275 NW Luth St

GeoStreet: Luth

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_65





OBJECTID (Perpendicular Ramp): 18

Name: CR_65

Address: 1824 NW Moore Ave

GeoStreet: Moore

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_66





OBJECTID (Perpendicular Ramp): 19

Name: CR_66

Address: 2490 NW Troost St

GeoStreet: Troost

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_67





OBJECTID (Perpendicular Ramp): 21

Name: CR_67

Address: Could Not Geocode

GeoStreet:

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_68





OBJECTID (Perpendicular Ramp): 22

Name: CR_68

Address: 2801 NW Mercy Dr

GeoStreet: Mercy

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_69





OBJECTID (Perpendicular Ramp): 23

Name: CR_69

Address: 417 NE Jackson St

GeoStreet: Jackson

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_70





OBJECTID (Perpendicular Ramp): 24

Name: CR_70

Address: 1314 NE Odell Ave

GeoStreet: Odell

Compliant: Verify

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_71





OBJECTID (Perpendicular Ramp): 25

Name: CR_71

Address: 1617 NE Commercial Ave

GeoStreet: Commercial

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_72





OBJECTID (Perpendicular Ramp): 26

Name: CR_72

Address: 868 SE Parrott St

GeoStreet: Parrott

Compliant: No

TruncDomes: No

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_73





OBJECTID (Perpendicular Ramp): 27

Name: CR_73

Address: 100 SE Templin Ave

GeoStreet: Templin

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_74





OBJECTID (Perpendicular Ramp): 28

Name: CR_74

Address: 544 SE Douglas Ave

GeoStreet: Douglas

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight:

CR_75





OBJECTID (Perpendicular Ramp): 29

Name: CR_75

Address: 800 SE Court Ave

GeoStreet: Court

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_76





OBJECTID (Perpendicular Ramp): 30

Name: CR_76

Address: 800 SE Court Ave

GeoStreet: Court

Compliant: Verify

TruncDomes: Yes

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:


S6_WingSlope2:


S7_CounterSlope:

GutterSlope:

LipHeight:

CR_77





OBJECTID (Perpendicular Ramp): 31

Name: CR_77

Address: 310 SE Rose St

GeoStreet: Rose

Compliant: Verify

TruncDomes:

Comments:

D1_LandingDim1:

D2_LandingDim2:

D3_RampWidth:

S1_LandingSlope1:

S2_LandingSlope2:

S3_RampSlope:

S4_RampCrossSlope:

S5_WingSlope1:

S6_WingSlope2:

S7_CounterSlope:

GutterSlope:

LipHeight: